



NO. 94-014

CESSNA A150L

ZK-DJP

REWA, NEAR HUNTERVILLE

11 JUNE 1994

ABSTRACT

On 11 June 1994 the student pilot was authorised for a period of practice aerobatics. He decided to fly over a friend's house and lost control during a steep turn at low level and the aircraft collided with the ground.

TRANSPORT ACCIDENT INVESTIGATION COMMISSION

AIRCRAFT REPORT NO. 94-014

| | |
|---|--|
| Aircraft Type, Serial Number and Registration: | Cessna A150L, A1500388 ZK-DJP |
| Number and Type of Engines: | One Rolls Royce Continental O-200 |
| Year of Manufacture: | 1973 |
| Date and Time: | 11 June 1994, 1415 hours* |
| Location: | Rewa Latitude: 39°57.5'S Longitude: 175°39'E |
| Type of Flight: | Flying School, Training |
| Persons on Board: | Crew: 1 Passengers: Nil |
| Injuries: | Crew: 1 Fatal Passengers: Nil |
| Nature of Damage: | Destroyed |
| Pilot in Command's Licence: | Student Pilot Licence (Aeroplane) |
| Pilot in Command's Age: | 23 |
| Pilot in Command's Total Flying Experience: | 57 hours, including 36 dual instruction |
| Information Sources: | Transport Accident Investigation Commission field investigation |
| Investigator in Charge: | R Chippindale |

*All times in this report are NZST (UTC + 12 hours)

1. NARRATIVE

- 1.1 On the morning of 11 June 1994 the pilot telephoned the CFI and obtained approval for a solo aerobatics flight in ZK-DJP. The CFI arranged to meet him at Feilding, where the aircraft was based, and discussed the flight that he was to undertake.
- 1.2 As it was to be the student's first aerobatic solo flight the CFI told him to restrict his exercise to loops and barrel rolls.
- 1.3 The CFI had just returned, from a sortie with another student, from the area between Ashhurst and Aokautere and told the student to confine his exercise to that area. He also briefed him on the weather there as being a cloud base of 5000 feet, no turbulence and a light northerly wind.
- 1.4 The need to keep clear of the Ohakea TMA was discussed as was the requirement to have the aircraft back by 1430 hours for another student.
- 1.5 The CFI expected that the aircraft would need refuelling on its return and waited at the fuel pump, from about 1415 hours, to assist with this chore.
- 1.6 When the aircraft had not returned by 1500 hours he flew another aircraft to 1000 feet to listen for an ELT transmission and called Palmerston North Tower who confirmed they had not heard from the student pilot.
- 1.7 When the CFI returned he was advised that ZK-DJP had been involved in an accident and the wreckage located. The ELT had been switched off by one of the rescue personnel.
- 1.8 The CFI recalled that the area in which the accident occurred had been flown over in the course of a dual map reading exercise during which the student had pointed out that he used to work in the vicinity and still had a friend living there.
- 1.9 The student had prearranged a visit to his friend and proceeded to the farm in the vicinity of Rewa, 17 nm north of Feilding, instead of flying to the area authorised by the CFI, which was 7 nm south-east of Feilding. He had not advised any intention to land at the property.
- 1.10 On arrival over the farm he had circled the area below tree top height and made a dummy approach to a farm strip.
- 1.11 On the last circuit about the student's friend's house the aircraft entered a steep left turn with 20° of flap lowered. After turning through some 90° the aircraft was seen to flick and dive into the ground.
- 1.12 The witnesses were divided as to which direction the aircraft rolled out of the steep turn when it flicked.
- 1.13 The aircraft impacted the steep bank of a gully. The combined flight path and slope angle resulted in an impact angle of approximately 115°, ie. 25° over the vertical.
- 1.14 The pilot was restrained by a shoulder harness and lap strap. The two shoulder straps were attached to the cockpit's rear bulkhead which moved forward relative to the pilot's seat when the aircraft jackknifed during the impact sequence. The engine and nose undercarriage were driven rearward reducing the occupiable area particularly around the pilot's feet.
- 1.15 One of the spectators was a nurse and she administered first aid to the pilot immediately. The pilot was airlifted to hospital from the accident site but he succumbed to his injuries three days after the accident.
- 1.16 The CFI, who had been the student's principal instructor, had been employed as a Flying Instructor since 21 June 1990 and attained a B Category rating on 31 January 1991. He had a total flying

time of 2500 hours with 1568 hours of instructing of which 117 hours was devoted to teaching aerobatics.

1.17 The student went solo after 10.25 hours and had completed 6.65 hours dual instruction in spinning and aerobatics. He had also undergone 3.2 hours dual instruction in low flying. His performance was assessed as above average by the CFI.

1.18 The CFI had flown the aircraft on the flight prior to that on which the accident occurred. The aircraft had performed normally and had sufficient fuel for the student's flight without a refuel.

1.19 A witness believed that he heard the aircraft's engine cut prior to the aircraft flicking out of the steep turn. The engine was therefore subjected to a strip examination by an approved overhaul company. No defects were found that might have led to the symptom described or to any other significant loss of power.

1.20 The fuel system of the aircraft was supplied by two tanks which fed to the engine simultaneously. The supply of fuel was controlled by a single on/off selector which was lockwired in the "ON" position. There was a significant quantity of fuel in each tank after the accident although the left tank had been punctured in the accident sequence. Both fuel caps were in place after the impact.

1.21 No fire occurred.

1.22 The student had been taught to use flap during his dual low flying exercises. Although this flying was in a different aircraft type the amount of flap used was similar. The use of 20° in ZK-DJP during the low level display to his friend was appropriate.

1.23 The Cessna 150 Owner's Manual included a table that gave the "power off" stalling speed with 60° of bank and 20° flap lowered as 70 mph (61 knots).

1.24 The aircraft's impact heading was 345° which was some 180° from its flight path prior to entering the steep turn.

1.25 No fault was found which might have interfered with the pre-impact operation of the aircraft's control systems.

1.26 The sequence of events suggested that the pilot entered a steep turn, the first portion of which involved flying cross-wind. In the light northerly conditions this would have caused an apparent slipping out of the turn if he was using the ground as a reference, or subconsciously noted the background while watching the spectators on the ground. In such an event he may have introduced bottom rudder in an attempt to "balance" the turn and thus initiated the stall and flick observed prior to the aircraft's collision with the terrain. It was also possible that a ridge of hills, some 200 to 300 feet above the level of the accident site and some 500 metres away, created a false horizon. If so the pilot may have raised the aircraft's nose in compensation and consequently reduced the aircraft's margin of speed above the stall.

2. FINDINGS

2.1 The CFI was suitably qualified and had sufficient knowledge of the student's ability to authorise the solo aerobatic flight.

2.2 The student had sufficient training and skill to complete the solo aerobatic flight as briefed.

- 2.3 The student departed from the CFI's authorization both in the type of flying in which he engaged and the area in which it was flown.
- 2.4 The student had received instruction in low flying but was not authorised for solo low flying. He lost control of the aircraft during a steep turn at low level.
- 2.5 The aircraft was airworthy prior to the accident.
- 2.6 The aircraft was properly loaded and fuelled for the flight.
- 2.7 The weather conditions were suitable for the flight as briefed.
- 2.8 The student may have been misled by an illusion that the aircraft was slipping out of the turn and made an inappropriate application of rudder which initiated a loss of control of the aircraft.
- 2.9 A nearby ridge of hills may have created a false horizon.
- 2.10 The student had been shown and had practised recovery from spins.
- 2.11 The height at which the aircraft flicked out of the turn precluded any realistic chance of recovery.
- 2.12 The chances of the student's survival would have been enhanced if his shoulder harness had been fixed to a section of the aircraft less likely to move forward on impact.
- 2.13 The bystanders and emergency services acted promptly and efficiently in response to the accident.

3. OBSERVATION

- 3.1 This is not the first occasion on which the Commission has been required to investigate an accident which resulted from a student engaging in a low flying display near the home of a friend or relative after departing from the instructor's specific instructions for the flight.
- 3.2 Low flying is a skill which requires specific training and regular practice even by experienced pilots. A number of factors resulting from the proximity to the ground create a significant potential for loss of control of the aircraft or for flying into obstructions. There is little time for recovery from a loss of control and such recovery itself depends upon training, and experience.
- 3.3 An article published in the CAA magazine "Flight Safety" six weeks prior to this accident commenced:

"It is not long since we featured an item on beat-ups. Nevertheless another instance has recently been brought to our attention, and we fear that there are other occurrences that we have not heard about.

It seems there are still pilots who believe they are immortal—despite the fact that the New Zealand accident records offer many examples of like-thinking pilots who have come to grief.

...These accidents also show that the beat-up mentality is not confined to any particular stereotype—increased flying experience and age do not necessarily coincide with increased wisdom.

You may get away with it once or twice, and this tends to engender false confidence. Any low flying has inherent dangers. Unnecessary low flying, with little or no margin for error and lack of time and space to cope with the unexpected, is not worth the risk. Don't join the (New Zealand list of low flying accident victims)."

- 3.4 There followed brief descriptions of 13 accidents resulting from low flying displays.
- 3.5 The pilot was on the distribution list for "Flight Safety."

12 October 1994

M F Dunphy
Chief Commissioner

ABBREVIATIONS COMMONLY USED IN TAIC REPORTS

| | |
|---------------|---|
| AD | Airworthiness Directive |
| ADF | Automatic direction-finding equipment |
| agl | Above ground level |
| AI | Attitude indicator |
| AIC | Aeronautical Information Circular |
| AIP | Aeronautical Information Publication |
| amsl | Above mean sea level |
| ASI | Airspeed indicator |
| ATA | Actual time of arrival |
| ATC | Air Traffic Control |
| ATD | Actual time of departure |
| ATIS | Automatic terminal information service |
| ATPL (A or H) | Airline Transport Pilot Licence (Aeroplane or Helicopter) |
| AUW | All-up weight |
| C | Celsius |
| CAA | Civil Aviation Authority |
| CASO | Civil Aviation Safety Order |
| CFI | Chief Flying Instructor |
| cm | Centimetres |
| CPL (A or H) | Commercial Pilot Licence (Aeroplane or Helicopter) |
| DME | Distance measuring equipment |
| E | East |
| ELT | Emergency location transmitter |
| ERC | En route chart |
| ETA | Estimated time of arrival |
| ETD | Estimated time of departure |
| F | Fahrenheit |
| FAA | Federal Aviation Administration (United States) |
| FL | Flight level |
| g | Acceleration due to gravity |
| GPS | Global Positioning System |
| HF | High frequency |
| hPa | Hectopascals |
| IAS | Indicated airspeed |
| IGE | In ground effect |
| IFR | Instrument Flight Rules |
| ILS | Instrument landing system |
| IMC | Instrument meteorological conditions |
| ins Hg | Inches of mercury |
| kHz | Kilohertz |
| KIAS | Knots indicated airspeed |
| km | Kilometres |
| kt | Knot(s) |

| | |
|--------------|--|
| LF | Low frequency |
| LLZ | Localiser |
| M | Mach number (e.g. M1.2) |
| M | Magnetic |
| MAANZ | Microlight Aircraft Association of New Zealand |
| MAP | Manifold absolute pressure (measured in inches of mercury) |
| MAUW | Maximum all-up weight |
| METAR | Aviation routine weather report (in aeronautical meteorological code) |
| MF | Medium frequency |
| MHz | Megahertz |
| mm | Millimetres |
| mph | Miles per hour |
| N | North |
| NDB | Non-directional radio beacon |
| NOTAM | Notice to Airmen |
| nm | Nautical mile |
| NZ | New Zealand |
| NZAACA | New Zealand Amateur Aircraft Constructors Association |
| NZGA | New Zealand Gliding Association |
| NZHGPA | New Zealand Hang Gliding and Paragliding Association |
| NZMS | New Zealand Mapping Service map series number |
| NZDT | New Zealand daylight time (UTC + 13 hours) |
| NZST | New Zealand standard time (UTC + 12 hours) |
| NTSB | National Transportation Safety Board (United States) |
| octa | Eighths of sky cloud cover (eg: 5 octas = 5/8 of cloud cover) |
| OGE | Out of ground effect |
| PAR | Precision approach radar |
| PIC | Pilot in command |
| PPL (A or H) | Private Pilot Licence (Aeroplane or Helicopter) |
| psi | Pounds per square inch |
| QFE | An altimeter subscale setting to obtain height above aerodrome |
| QNH | An altimeter subscale setting to obtain elevation above mean sea level |
| RNZAC | Royal New Zealand Aero Club |
| RNZAF | Royal New Zealand Air Force |
| rpm | Revolutions per minute |
| RTF | Radio telephone or radio telephony |
| S | South |
| SAR | Search and Rescue |
| SSR | Secondary surveillance radar |
| T | True |
| TACAN | Tactical Air Navigation aid |
| TAF | Terminal aerodrome forecast |
| TAS | True airspeed |
| TIS | Time-in-service |
| UHF | Ultra high frequency |

| | |
|--------|--|
| US | United States |
| UTC | Coordinated Universal Time |
| VASIS | Visual approach slope indicator system |
| VFG | Visual Flight Guide |
| VFR | Visual flight rules |
| VHF | Very high frequency |
| VMC | Visual meteorological conditions |
| VOR | VHF omnidirectional radio range |
| VORTAC | VOR and TACAN combined |
| VTC | Visual terminal chart |
| W | West |