



Transport Accident
Investigation
Commission

Final Report

Tuhinga whakamutunga

Aviation inquiry A0-2021-003
Airbus Helicopters AS350 B3e, ZK-ITD
Loss of control in flight
Lammerlaw Range,
40 km northwest of Dunedin Aerodrome
16 September 2021

November 2023



The Transport Accident Investigation Commission

Te Kōmihana Tirotiro Aituā Waka

No repeat accidents – ever!

“The principal purpose of the Commission shall be to determine the circumstances and causes of accidents and incidents with a view to avoiding similar occurrences in the future, rather than to ascribe blame to any person.”

Transport Accident Investigation Commission Act 1990, s4 Purpose

The Transport Accident Investigation Commission is an independent Crown entity and standing commission of inquiry. We investigate selected maritime, aviation and rail accidents and incidents that occur in New Zealand or involve New Zealand-registered aircraft or vessels.

Our investigations are for the purpose of avoiding similar accidents in the future. We determine and analyse contributing factors, explain circumstances and causes, identify safety issues, and make recommendations to improve safety. Our findings cannot be used to pursue criminal, civil, or regulatory action.

At the end of every inquiry, we share all relevant knowledge in a final report. We use our information and insight to influence others in the transport sector to improve safety, nationally and internationally.

Commissioners

Chief Commissioner	Jane Meares
Deputy Chief Commissioner	Stephen Davies Howard
Commissioner	Paula Rose, QSO
Commissioner	Richard Marchant (until 31 October 2022)
Commissioner	Bernadette Roka Arapere (from 1 December 2022)
Commissioner	David Clarke (from 1 December 2022)

Key Commission personnel

Chief Executive	Martin Sawyers
Chief Investigator of Accidents	Naveen Kozhuppakalam
Investigator-in-Charge for this inquiry	Hamish Johnstone
Commission General Counsel	Cathryn Bridge

Notes about Commission reports

Kōrero tāpiri ki ngā pūrongo o te Kōmihana

Citations and referencing

The citations section of this report lists public documents. Documents unavailable to the public (that is, not discoverable under the Official Information Act 1982) are referenced in footnotes. Information derived from interviews during the Commission's inquiry into the occurrence is used without attribution.

Photographs, diagrams, pictures

The Commission owns the photographs, diagrams and pictures in this report unless otherwise specified.

Verbal probability expressions

For clarity, the Commission uses standardised terminology where possible.

One example of this standardisation is the terminology used to describe the degree of probability (or likelihood) that an event happened, or a condition existed in support of a hypothesis. The Commission has adopted this terminology from the Intergovernmental Panel on Climate Change and Australian Transport Safety Bureau models. The Commission chose these models because of their simplicity, usability, and international use. The Commission considers these models reflect its functions. These functions include making findings and issuing recommendations based on a wide range of evidence, whether or not that evidence would be admissible in a court of law.

Terminology	Likelihood	Equivalent terms
Virtually certain	> 99% probability of occurrence	Almost certain
Very likely	> 90% probability	Highly likely, very probable
Likely	> 66% probability	Probable
About as likely as not	33% to 66% probability	More or less likely
Unlikely	< 33% probability	Improbable
Very unlikely	< 10% probability	Highly unlikely
Exceptionally unlikely	< 1% probability	



Figure 1: Airbus Helicopters AS350 B3e, ZK-ITD
(Credit: Lister Helicopters)



Figure 2: Location of accident: Lammerlaw Range, 40 km northwest of Dunedin aerodrome

Contents

Rārangi take

1	Executive summary	1
	What happened.....	1
	Why it happened	1
	What we can learn.....	2
	Who may benefit	2
2	Factual information	3
	Narrative.....	3
	Personnel information	8
	Pilot	8
	Aircraft information	9
	Meteorological information.....	10
	Illumination	11
	Recorded data.....	11
	Flight recorders.....	11
	Other digital data sources used in the inquiry	12
	Site and wreckage information	12
	Terrain	12
	Impact.....	12
	Wreckage	12
	Organisational information.....	15
	Operator	15
	Aviation New Zealand AIRCARE™ Accreditation Programme	15
	CAA Night Visual Flight Rules.....	16
	Spatial disorientation	18
3	Analysis	20
	Introduction	20
	What happened.....	20
	Avenues of inquiry	20
	Medical	20
	Mechanical.....	21
	Environment.....	21
	Spatial disorientation.....	24

Summary	26
Other factors that affect safety.....	26
Night-flying rules	26
Instrument currency requirements for night flying.....	29
Emergency Locator Transmitter	30
Cockpit video recorders	31
4 Findings	32
5 Safety issues and remedial action	33
General.....	33
Safety issues.....	33
6 Recommendations.....	35
General.....	35
New recommendations.....	35
Notice of recommendations.....	35
7 Key lessons	36
8 Data summary	37
9 Conduct of the inquiry	38
Abbreviations.....	39
Whakapotonga	39
Glossary	40
Citations	41
Appendix 1 Advisory Circular AC61-5 Night extract.....	43
Appendix 2 Spatial disorientation	45

Figures

Figure 1: Airbus Helicopters AS350 B3e, ZK-ITD	iii
Figure 2: Location of accident: Lammerlaw Range, 40 km northwest of Dunedin aerodrome	iv
Figure 3: Flight path, approaching Lawrence.....	3
Figure 4: Final minutes of the flight path.....	4
Figure 5: Flight detail and timeline	6
Figure 6: General timeline.....	7
Figure 7: Location of main wreckage relative to rear door and windows (340 m to right rear window).....	13
Figure 8: Aerial view of main wreckage.....	13
Figure 9: Wreckage distribution (about 130 m to pilot’s seat)	14
Figure 10: Main rotor hub with tail rotor in background	14
Figure 11: Altitude of helicopter and cloud tops estimates along track	22
Figure 12: Illustration of 25 nm restriction	27
Figure 13: Flight path with 25 nm range rings.....	28

1 Executive summary

Tuhinga whakarāpopoto

What happened

- 1.1. On Thursday 16 September 2021, an Airbus AS350 B3e helicopter ZK-ITD was being flown from the operator's base in Milton to a client's cherry orchard near Alexandra to conduct frost protection operations.
- 1.2. The flight departed approximately one hour before the beginning of morning civil twilight (when the centre of the rising sun's disc is 6 degrees below the horizon). It proceeded normally until just before reaching the township of Lawrence.
- 1.3. The helicopter conducted a series of turns immediately before, and after, reaching the township of Lawrence. Soon after passing Lawrence, while over the Lammerlaw Range, the helicopter made a descending right-hand turn through nearly 160 degrees before entering a left-hand spiral dive that ended in a near vertical nose-down impact with the ground.
- 1.4. The helicopter was destroyed on impact and the pilot (the sole occupant) did not survive.

Why it happened

- 1.5. The helicopter had departed the operator's base one hour after the moon had set and one hour before the beginning of morning civil twilight. It was close to the darkest part of the night.
- 1.6. The pilot **almost certainly** encountered cloud in the vicinity of Lawrence and was **very likely** attempting to manoeuvre around it. With increasing cloud cover and little or no terrestrial light in the Lammerlaw Range area it was **very likely** that the pilot lost their clearly defined horizon soon after passing Lawrence.
- 1.7. The helicopter continued to climb straight ahead for nearly three minutes before the pilot **very likely** became disorientated. The pilot's disorientation **very likely** resulted in a high angle of bank turn, followed by the rapid descent of the helicopter, which was consistent with spatial disorientation and loss of control of the helicopter.
- 1.8. The pilot had met the currency requirements for their restricted night rating. However, it had been about nine years since the pilot had last logged instrument flying practice. It was **very unlikely** that the pilot was proficient in flight with sole reference to aircraft instruments at the time of the accident.
- 1.9. Two safety issues were identified:
 1. The rules and guidance information for night Visual Flight Rules (VFR) are ambiguous. This could lead to night VFR pilots flying longer distances than permitted at night and encountering night flying conditions outside their capabilities.
 2. The current rules for and guidance on instrument currency for night VFR do not adequately mitigate the risks of inadvertent flight into conditions where the clearly defined horizon is lost.

- 1.10. The Transport Accident Investigation Commission made two **recommendations** to the Director of Civil Aviation to address these safety issues.

What we can learn

- 1.11. It has long been known that instrument flying skills are perishable and need to be regularly refreshed. This equally applies to night flying.
- 1.12. The risk of losing a clearly defined horizon by not remaining clear of cloud and in sight of the surface increases when flying at night. An immediate transition to instrument flight is required to maintain situational awareness and control of the aircraft in order to re-establish a clearly defined horizon.
- 1.13. Visual night cross-country flying requires additional training and different skills from those required for visual night flying near a lighted aerodrome or heliport.
- 1.14. The use of tracking technologies to supplement onboard Emergency Locator Transmitters can significantly reduce the time taken to locate missing aircraft.
- 1.15. Cockpit video recorders, where fitted, can provide valuable information about causes of accidents and help avoid recurrences.

Who may benefit

- 1.16. All pilots and operators, and those who use the services of helicopters, especially those who are involved in night operations such as frost protection, may benefit from the findings and recommendations in this report.

2 Factual information

Pārongo pono

Narrative

- 2.1. At 0517¹ on Thursday 16 September 2021, the pilot of ZK-ITD (the helicopter), an Airbus AS350 B3e helicopter, departed from Lister Helicopters' (the operator's) base near Milton. The moon had set about one hour before departure, and it was about one hour before morning civil twilight². The pilot was the sole occupant and was not wearing any Night Vision Imaging System³, nor were they qualified or equipped to do so. The purpose of the flight was to ferry the helicopter to a cherry orchard near Alexandra, a flight of 62 nautical miles (nm) (115 kilometres [km]), to conduct a frost-protection⁴ operation. The flight would normally have taken about 30 minutes. The helicopter did not arrive at the intended destination.




Figure 3: Flight path, approaching Lawrence

¹ Times in this report are in New Zealand Standard Time (Universal Co-ordinated time +12 hours) expressed in the 24 hour format.

² When the centre of the rising sun's disc is 6 degrees below the horizon. It is defined as the end of night in CARs Part 1 'Definitions and Abbreviations'.

³ A system that integrates all elements necessary for a pilot wearing night-vision goggles to operate an aircraft successfully and safely. Night Vision Imaging System operations allow a pilot to have enhanced vision while flying at night under visual meteorological conditions.

⁴ Helicopter frost protection involves low-level flying over an affected crop to mix warmer air aloft with the cooler air below to prevent frost from settling on the fruit. The operator referred to it as 'frost fighting' in their exposition. An exposition is a document detailing the policies and processes that underpin the way the organisation goes about its day-to-day business.

2.2. The flight path of the helicopter was recorded by the Airways New Zealand Automatic Dependent Surveillance – Broadcast (ADS-B) system. At 0526:36 the helicopter made a right turn immediately before the township of Lawrence (see Figure 3) at an altitude of 6475 feet (ft) (2000 metres (m)) above mean sea level (amsl). This was the first in a series of turns in the next four minutes.




Figure 4: Final minutes of the flight path

2.3. The last ADS-B data point was received at 0531:35. At that time the helicopter was at an altitude of 3475 ft (1060 m) amsl and on a track of 293 degrees (see Figure 4). There were several data points recorded after this time; however, they were determined to be 'coasted'⁵ data points and not from the helicopter. Moments later the helicopter struck the ground in a near vertical nose-down attitude, at an elevation

⁵ If a connection with an aircraft is lost, the ADS-B system calculates the likely position of the aircraft, based on its previous position, altitude and speed, and labels it as 'coasted' rather than received data for the purpose of predicting the location of the aircraft until a connection is re-established.

of about 2430 ft (740 m). See Figure 5 for the flight timeline, with altitude and airspeed.

- 2.4. The helicopter was destroyed as a result of the impact and post-impact fire. The pilot did not survive the accident.
- 2.5. The pilot had flown a frost-protection operation with the same helicopter at the same orchard on the previous morning (Wednesday 15 September 2021). They had not expected to be required for Thursday morning. After a change in the weather forecast, the client contacted the operator⁶ at about 1820 on Wednesday evening to request the aircraft for the next morning. The operator recalled telling the client that it was too late to safely deploy the helicopter that evening, but that the helicopter could be there after first light the following morning.
- 2.6. The pilot phoned the operator at 1917 on Wednesday and was informed of the task for the following morning. The last recorded activity that night on the pilot's phone was at 2147.
- 2.7. On Thursday 16 September 2021 at 0458 the aircraft tracker activated for 29 seconds then shut down again, consistent with the aircraft power being turned on briefly during the pilot's pre-flight inspection.
- 2.8. There were two calls at 0501 between the operator and the pilot, the first a 4 second call from the operator to the pilot, followed by a 66 second call from the pilot to the operator. There were no further calls or text messages to or from the pilot's phone until 0541, when the operator made six attempts to call the pilot's phone. The last attempt was at 0607.
- 2.9. The operator advised the Commission that at about 0500 they had discussed the lighting conditions with the pilot before departure, as being clear and starry at the operator's base at the time. The operator advised the Commission that they told the pilot to use their discretion in departing when it was light enough and when the pilot was happy with the conditions.
- 2.10. The helicopters in the operator's fleet were fitted with navigation tracking systems that, once powered up, provided real-time updates of helicopter locations that could be viewed using a cell phone application. The operator recalled checking the flight-tracking application on their phone at about 0530 and realising the helicopter had departed, but that the tracking information was no longer being updated.
- 2.11. At about 0540 the operator contacted the owner of another local helicopter company to request search and rescue (SAR) assistance.
- 2.12. At 0614, after being refuelled and the helicopters' role equipment re-configured for a search and rescue operation, the SAR helicopter departed for the search area from the SAR helicopter company's base at Taieri Airfield. The pilot of the SAR helicopter later recalled that the cloud base in the search area had been about 1800–2000 ft amsl (550–610 m) when they arrived in the area at about 0630. Because of the nature of the terrain, this meant the cloud was down to the ground in many places, including the accident site.
- 2.13. The operator also tasked another of their pilots to take a company aircraft to search for the missing helicopter.

⁶ The operator was also the Chief Pilot of the company. The term operator is used throughout this report.




Figure 5: Flight detail and timeline




Figure 6: General timeline

- 2.14. The Emergency Locator Transmitter (ELT) from the helicopter did not activate. The operator passed the last recorded tracking data point received from the helicopter tracking system to the owner of the SAR helicopter. The Rescue Coordination Centre supplied the helicopter's last known location, derived from ADS-B data, to the SAR helicopter crew to assist with the search.
- 2.15. Initially the search was unable to find the crash site because of low cloud, often on the ground. By 0743 the cloud base had lifted further up the hill, sufficient for the SAR helicopter crew to locate the wreckage and to land nearby. The wreckage was at 2434 ft (742 m) amsl, just below the cloud base at the time it was located.
- 2.16. The arriving SAR helicopter crew reported high humidity with damp ground and patches of fog when they landed. The crew also reported several small fires still burning around the accident site, which self-extinguished soon after they arrived.

Personnel information

Pilot

- 2.17. The pilot, aged 36 years, had been issued with a Commercial Pilot Licence (Helicopter) in November 2008. They had been issued with a 'B' category flight instructor rating in May 2011, with the last renewal conducted in April 2021.
- 2.18. The pilot held a restricted⁷ night rating issued according to the Civil Aviation Authority (CAA) Advisory Circular 61-5 (AC61-5) 'Pilot Licences and Ratings – Commercial Pilot Licence' (see Appendix 1), first meeting the requirements in October 2008. This meant they could exercise the privileges of a Commercial Pilot Licence (Helicopter) at night⁸ but not beyond 25 nm of a lighted⁹ heliport¹⁰ or aerodrome¹¹. The pilot was also issued with a restricted night VFR instructor approval in September 2010.
- 2.19. The pilot's last flight-crew competency check with the operator had been conducted in June 2021 in accordance with the operator's exposition and the Civil Aviation Rules (CARs).
- 2.20. At the time of the accident the pilot had a total flight time of about 4230 hours, of which about 1200 had been on the AS350 aircraft type¹². The pilot had flown about 63 hours of night flying, including 4.2 hours the previous night.
- 2.21. The most recent night flights recorded in the pilot's logbook before this had been 1.0 hour on 8 October 2020 and 3.0 hours on 1 October 2020. There were no night flights recorded in the pilot's logbook between October 2014 and October 2020.

⁷ For night operations within 25 nm of a lighted heliport or aerodrome.

⁸ As defined in Civil Aviation Rules (CARs) Part 01, night means the hours between:

(1) the end of evening civil twilight, which is when the centre of the setting sun's disc is 6 degrees below the horizon; and

(2) the beginning of morning civil twilight.

⁹ Not defined in CARs.

¹⁰ See paragraph 2.70.

¹¹ Any defined area of land or water intended or designed to be used either wholly or partly for the landing, departure and surface movement of aircraft (CARs Part 1 'Definitions and Abbreviations').

¹² Includes both Airbus Helicopters AS350 and EC130 helicopters as they share a type certificate.

- 2.22. The pilot had logged a total 20 hours' instrument time, of which 14.5 hours had been simulated in flight¹³ and 5.5 hours had been conducted in an approved ground simulator. The pilot's last simulated instrument flight had been conducted in April 2012.

Pilot medical information

- 2.23. The pilot held a class 1 medical certificate with no restrictions, valid until 30 October 2021.
- 2.24. The pilot's medical history was reviewed during the investigation by the Commission's aviation medical specialist. The specialist determined that there was nothing of relevance in the pilot's medical history.
- 2.25. The injuries sustained during the accident limited the autopsy examination. The medical examination was inconclusive in identifying any potential medical factors contributing to the accident. No evidence of performance-impairing substances was found.
- 2.26. Commission investigators interviewed two people who had been in direct contact with the pilot in the 72 hours before the accident. The interviewees stated the pilot had rested following the previous morning's flying and was not known to be suffering from any personal health or fatigue issues. There had been no noticeable change in the pilot's demeanour.

Aircraft information

- 2.27. ZK-ITD was an Airbus AS350 B3e helicopter, serial number 7815, constructed in March 2014 by Airbus Helicopters in France. The AS350 B3e helicopter is fitted with a single Safran Arriel 2D turboshaft engine.
- 2.28. The helicopter had 3136.8 hours' total flying time since new recorded in the aircraft maintenance logbook as of 15 September 2021.
- 2.29. The helicopter had been imported into New Zealand in July 2014 and registered as ZK-IOJ. The aircraft had had several owners before the operator took possession in January 2019, at which time the registration was changed to ZK-ITD¹⁴.
- 2.30. A Review of Airworthiness was carried out on 8 June 2021 at 3082.5 hours' total time in service; no defects were observed. The next Review of Airworthiness was due on 25 May 2022.
- 2.31. On 6 August 2021, with 3085.7 hours' total time in service, it was recorded in the helicopter logbook that the scheduled 600 and 1200 flight hour and 24-month calendar inspections had been carried out. The helicopter had been repainted and reweighed, with the new basic empty weight of 1331.0 kilograms (kg) recorded in the logbook. The helicopter logbook showed that all required inspections had been carried out at this time.
- 2.32. A review of the airframe and engine records of life components and repetitive inspections found no non-compliance with the manufacturers' instructions. The

¹³ Simulated in flight with a safety pilot present, but without entering instrument meteorological conditions.

¹⁴ A change of registration for a newly purchased aircraft to suit personal preference, or to maintain a fleet-wide standard, is not unusual.

helicopter flight manual was not available for review because of damage from the accident.

- 2.33. Airworthiness directives were checked against the CAA's airworthiness directive schedules. There were no outstanding airworthiness directives applicable to ZK-ITD.
- 2.34. The operator had its own fuel supply for use by company helicopters. Evidence of the fuel load taken was not available to the investigation; however, the operator recalled that with the type of operation to be flown, the pilot should have departed from the operator's base with a full fuel load, taken from the operator's own supply tank.
- 2.35. The fuel supply chain and quality of the fuel were reviewed by investigators. The fuel provider confirmed that the sample testing had proved satisfactory, and the fuel had met the required specifications. Other aircraft belonging to the operator used the same fuel before and after the accident, with no reported concerns.

Meteorological information

- 2.36. The MetService area forecast issued at 2311 NZST on 15 September 2021 and valid from 0300 to 0900 on 16 September 2021 for the area around the operator's base, was for broken¹⁵ cloud with bases between 1200 and 1700 ft (610 and 915 m) amsl and tops between 6000 and 7000 ft (1520 and 1830 m) amsl. Visibility was 20 km reducing to 5000 m in rain with an approaching cold front. The forecast for Otago area where the flight proceeded was for broken cloud with bases between 2000 and 3000 ft and tops between 5000 and 6000 ft. Visibility was forecast as 30 km reducing to 500 m in localised fog and freezing fog patches. Freezing level¹⁶ was forecast over the Otago region between 3000 and 3500 ft.
- 2.37. The wind was forecast¹⁷ to be from the southwest at 10 knots at 3000 ft increasing to west-southwest 20 knots at 10,000 ft.
- 2.38. The Terminal Aerodrome Forecast for Dunedin Aerodrome¹⁸, issued at 2309 on 15 September 2021, was valid from midnight until 1800 the following day. For the time of the flight, it forecast the surface wind as variable at two knots and 30 km visibility with clear skies. There was a 30% probability of visibility reducing to 500 m in freezing fog between 0100 and 0800.
- 2.39. The National Institute of Water and Atmospheric Research (NIWA) weather station in Balclutha, 16 km south-west of the operator's base, recorded a relative humidity of 88% and a temperature of plus five degrees Celsius (°C) at 0520, three minutes after the time the helicopter departed.
- 2.40. By comparison, the NIWA station at Alexandra, 64 km north north-west of the accident site, showed relative humidity rising to 98% and temperature lowering to minus 0.3°C at 0530, about the time of the accident.
- 2.41. A local helicopter pilot flying southwest from Taieri to Kaitangata flew past the operator's base at about 0506. The pilot, operating on night vision goggles, reported that the cloud base in the area was about 2200 ft (670 m) amsl, with cloud extending to the west.

¹⁵ Five to seven eighths' cloud cover.

¹⁶ The altitude at which the temperature is at 0 °C in a free atmosphere (the freezing point of water).

¹⁷ Area Clyde (CY) valid 1200 to 0600 UTC.

¹⁸ The nearest aerodrome to the flight route.

- 2.42. CARs Part 91.301 'Visual Flight Rules (VFR) meteorological minima for flight in uncontrolled airspace' requires:

Above 3000 feet amsl or 1000 feet above terrain, whichever is the higher	2 km horizontally and 1000 feet vertically clear of cloud with 5km visibility
At or below 3000 feet amsl or 1000 feet above terrain, whichever is the higher	Clear of cloud and in sight of the surface with 5 km visibility

However, Part 91.301(c)(1) states that:

a helicopter may operate in Class G airspace with a flight visibility of less than 5 km if manoeuvred at a speed that gives adequate opportunity to observe other traffic or any obstructions in order to avoid collisions.

Illumination

- 2.43. The moon set at 0414,¹⁹ about one hour before the helicopter departed the operator's base.
- 2.44. The beginning of morning civil twilight was published as 0617.²⁰ Sunrise was at 0641.²¹
- 2.45. As a result, there was virtually no background illumination to give a clearly defined horizon.

Recorded data

- 2.46. The helicopter was fitted with TracMap GPS and TracPlus™ navigation and tracking systems that recorded its flight path. The flight path of the helicopter was also recorded by Airways New Zealand's ADS-B tracking system. Collectively, the tracking systems provided an accurate record of the helicopter's flight path for the duration of the flight.

Flight recorders

- 2.47. The helicopter was not fitted with a flight data recorder or a cockpit voice recorder, nor was it required to be. However, the helicopter was fitted with a Vehicle and Engine Multifunction Display (VEMD), an Engine Data Recorder (EDR) and an Electronic Engine Control Unit (EECU). The VEMD was designed to record and display a range of engine- and airframe-related parameters, including any exceedances of the manufacturer's limits.
- 2.48. The VEMD, EDR and EECU from the helicopter were damaged in the accident. They were removed and sent to the Bureau d'Enquêtes et d'Analyses (BEA)²² in France to determine if any information could be extracted. The BEA was able to download the engine performance data for the previous 32 flights from the VEMD. The data identified nothing unusual for the 32 flights, including the accident flight. There were no recorded engine exceedances or malfunctions. No data could be recovered from the EDR or EECU because of fire damage.

¹⁹ <https://www.mooncalc.org>.

²⁰ Aeronautical Information Publication New Zealand Gen 2.7 – 6.

²¹ <https://www.suncalc.org>.

²² The BEA was the International Civil Aviation Organization's Annex 13 representative for the state of manufacture (France) of the helicopter and engine.

2.49. The summary of the BEA report states:

Flight report: The last recorded flight was flight 1556 and was identified as the flight of the event. It lasted 22 min 45s. There was no failure, nor overlimit recorded.

Failure report: The last failure recorded was related to flight 1513, 43 flights before the flight of the event.

EPC [in-flight engine power check]: The last EPC was good and was done during flight 1553, three flights before the accident flight.

Other digital data sources used in the inquiry

2.50. The pilot's cell phone records included times and durations of calls and details of text messages between the pilot and other parties, including the operator and client on the day of the flight as well as the previous day.

Site and wreckage information

Terrain

2.51. The accident site was 15 km northeast of Lawrence at an altitude of 2434 ft amsl. The terrain was generally rolling, with gullies and small valleys leading up to the Lammerlaw Range north of the site.

2.52. The surface consisted of tussock grass and some groups of small trees, predominantly around the valleys. There was a thin layer of soil over a solid clay base.

Impact

2.53. The helicopter descended in a left spiral dive, striking the ground in a near-vertical nose-down attitude with a very high rate of descent.

Wreckage

2.54. The right rear window was located about 340 m from the main wreckage, on a bearing of about 090 degrees true. The right rear door and left rear window were located together on the same line about 180 m from the main wreckage. They were all located outside the flight path of the helicopter as it descended (see Figure 7). The majority of the helicopter wreckage, including the engine and both main and tail rotors were located close to the initial impact point.

2.55. The left skid and flight step were buried at a depth of about 1 m into the clay. Some small pieces of the nose of the aircraft, and some parts of the instrument panel, were buried to the right and forward of the left skid.

2.56. The orientation of the helicopter on initial impact was assessed as being on a heading of about 150 degrees true. The main wreckage, including the pilot's seat and other items, were displaced outwards and to the right of the direction of impact (see Figure 8 and Figure 9).

2.57. The impact of the helicopter removed the top layer of soil, leaving a small crater. The fuselage of the helicopter was lying next to the crater. The blades were still attached to the main rotor hub and were in the topsoil layer immediately in front of the nose impact point (see Figure 10). There were breakages in the Starflex™ main rotor hub and two of the three vibration damper springs were thrown clear of the wreckage.

2.58. The rear section of the tail boom²³, including the tail rotor and tail rotor gearbox were largely intact with damage consistent with the impact forces received, and located to the north side of the initial impact point.



Figure 7: Location of main wreckage relative to rear door and windows (340 m to right rear window)





Figure 8: Aerial view of main wreckage

²³ The tail boom extends out from the rear of the body of the helicopter.



**Figure 9: Wreckage distribution
(about 130 m to pilot's seat)**



Figure 10: Main rotor hub with tail rotor in background

Organisational information

Operator

2.59. The operator held a CARs Part 119 Air Operator Certificate and a Part 137 Agricultural Aircraft Operator Certificate, issued by the CAA. The operator's certificate permitted operations in accordance with the operator's exposition, which did not permit the operator to conduct VFR air transport operations at night (see paragraph 2.60 regarding CAA guidance on general frost-flight permission).

2.60. The operator, according to the CAA website guidance on frost protection, was also permitted to conduct operations under CARs Part 91 'General Operating and Flight Rules'. The website included the following guidance for frost protection:²⁴

Frost protection operations can be carried out for hire or reward under Part 91 of the Civil Aviation Rules.

Pilots engaging in frost protection must hold a Commercial Pilot Licence, Helicopter, and a current night rating.

Any related flights with passengers on board, such as reconnaissance flights to survey vineyards, must be done by the holder of a Part 119 Air Operator Certificate.

The New Zealand Helicopter Association has published a standard operating procedure for Aerial Frostfighting Operations which provides guidance on managing risks.

2.61. The operator's exposition contained a section on frost fighting.²⁵ The following are extracts from the manual:

Hazards

- All frost fighting work must²⁶ be carried out with visual reference to the ground, if a risk of losing this visual reference to the ground exists then the operation must stop immediately.
- Frost fighting is only approved if the pilot has thoroughly inspected the area to be treated in 'daylight conditions' prior to commencing operations. This requires that the aircraft be positioned to the scene of operations in time to carry out the necessary inspections in daylight.

Callout Procedures

- The client must be advised of the latest time that a Frost Fighting callout will be accepted. That time is calculated by adding the time needed to get the aircraft and crew prepared, the ferry flight time required and the site inspection time. This total time then needs to be deducted from evening civil twilight to establish the final callout time.

Aviation New Zealand AIRCARE™ Accreditation Programme

2.62. The operator was accredited to the Aviation New Zealand AIRCARE™ Accreditation Programme²⁷ on 25 November 2020, and the accreditation was valid for three years.

²⁴ [Helicopter frost protection | aviation.govt.nz](https://www.aviation.govt.nz/safety/safety-advice/helicopter-safety/helicopter-frost-protection) <https://www.aviation.govt.nz/safety/safety-advice/helicopter-safety/helicopter-frost-protection>.

²⁵ Also known as frost protection, the term used by the CAA.

²⁶ Emphasis in the original.

²⁷ [AIRCARE™ \(aviationnz.co.nz\)](https://www.aviationnz.co.nz/AIRCARE.html) <https://www.aviationnz.co.nz/AIRCARE.html>.

The standards in the AIRCARE™ programme for which the operator was accredited were listed on its Certificate of Accreditation as:

- Safety Management System – QA and Risk Management
- Environmental – Discharges – GROWSAFE
- Environmental – Discharges – SPREADMARK – Aerial
- Environmental – Amenity Values – Noise Abatement.

2.63. Aviation New Zealand, which includes the New Zealand Helicopter Association as a division, developed the AIRCARE™ programme to assist members to meet industry best practice flight safety and environmental management systems. The AIRCARE™ website includes the following statement:

The rules and standards incorporated in this programme not only represent best industry practice but compliance with them will also provide independently assessed assurance that participants in the programme are performing at a level that consistently ensures compliance with regulations and industry codes of practice.

2.64. The AIRCARE™ resources available included Frost Fighting Standard Operating Procedures, which outlined the roles and responsibilities of all participants in frost-fighting operations, including management, pilots and clients.

2.65. Pilot responsibilities included:

He/she is fully aware of the requirements of these procedures particularly in relation [to] ferry flight after Evening Civil Twilight and before Morning Civil Twilight.

He/she fully understands the dangers of losing visual reference with the ground during operations and establishes practices that do not allow this to occur.

2.66. The AIRCARE™ document included a comprehensive Hazard Register with Controls. Included in this register was the following risk control for loss of spatial orientation:

Hazard Identified	Potential Harm	Hazard Controls
Loss of spatial orientation	Serious or fatal	<ul style="list-style-type: none"> • Always maintain visual reference with the ground • Don't carry out cross-country flight to and from the block being treated²⁸

CAA Night Visual Flight Rules

2.67. The eligibility requirements for a Commercial Pilot Licence are listed in CARs Part 61, under Subpart E 'Commercial Pilot Licences'.²⁹ The requirements for a night rating, as part of Part 61.203 (a), include:

(5) if the person seeks to exercise commercial pilot privileges during the night, have night flight time experience acceptable to the Director³⁰.

²⁸ While not explicitly stated, the advice on cross-country flights would logically only apply to night flights.

²⁹ For simplicity, this report refers to the rules and guidance for commercial helicopter pilots. However, the rules and guidance for private helicopter pilots are substantially similar and the same lessons apply.

³⁰ The Director of Civil Aviation.

2.68. CAA advisory circulars contain guidance on standards, practices and procedures that the Director has found to be acceptable means of compliance with the associated rules and legislation.

2.69. AC61-5 stated that helicopter³¹ pilots required the following experience:

For night operations within 25 nm of a lighted heliport or aerodrome:

- 2 hours dual instrument flight instruction³² in helicopters; and
- 10 hours night flight time in helicopters including:
 - o 5 hours dual instruction
 - o 2 hours solo including 10 solo take-offs, translation circuits and landings at night.

However, where an applicant has completed 5 hours night flight time in helicopters including 2 hours dual instruction, 2 hours solo, and 2 hours dual instrument flight instruction in helicopters, the applicant may exercise the privileges of a PPL(H) [Private Pilot Licence (helicopter)] at night.

For night operations beyond 25 nm of a lighted heliport or aerodrome (night cross-country):

- 10 hours dual instrument instruction in helicopters of which no more than 5 hours may be instrument time in a synthetic helicopter flight trainer; and
- 10 hours night flight time in helicopters including:
 - o 5 hours dual instruction
 - o 2 hours solo including 10 solo take-offs, translation circuits and landings at night
 - o 3 hours night cross-country training which is to have been conducted in accordance with the syllabus set out in Appendix II of this advisory circular.

An applicant who does not meet these requirements does not comply with rule 61.203(5) and may not exercise those privileges of a Commercial Pilot Licence (helicopter) at night beyond 25 nm of a lighted heliport or aerodrome.

2.70. CARs Part 1 'Definitions and Abbreviations' defines a heliport as:

any defined area of land or water, and any defined area on a structure, intended or designed to be used either wholly or partly for the landing, departure, and surface movement of helicopters.

It defines a cross-country flight as:

a flight which extends more than 25 nautical miles in a straight-line distance from the centre of the aerodrome of departure.

2.71. CARs Part 1 'Definitions and Abbreviations' does not define 'lighted heliport'.

2.72. See Appendix 1 for the complete night flying advice contained in AC61-5.

³¹ Holders of private or commercial aeroplane licences do not have an 'operations within 25 nm' option.

³² Flight instruction provided to a person by an appropriately licensed and rated flight instructor occupying a pilot seat.

Spatial disorientation

- 2.73. Spatial disorientation is described as a state characterised by an erroneous sense of one's position and motion relative to the plane of Earth's surface. It is caused by the orientation senses within the body³³ misrepresenting a person's position in space (United States Department of Transportation, 2010).
- 2.74. In normal circumstances, the visual system is dominant and provides approximately 80 per cent of raw orientation information sent to the brain for processing. When visual cues are poor, missing or absent entirely, the brain relies on information provided by the vestibular and proprioceptive system for orientation. However, both systems are less accurate than vision and both systems are susceptible to illusions. This can result in the brain receiving conflicting sensory information and misinterpreting the way in which the individual is orientated or moving.
- 2.75. The vestibular system is prone to several common illusions that can affect pilots during flight. The system is designed to sense motion on the ground and is therefore more limited and less reliable when exposed to manoeuvres typical of those flown in an aircraft that has three axes of rotation.³⁴ Provided adequate visual cues are available, these will take precedence over the information transmitted by the vestibular system, and a pilot can correctly interpret their orientation despite the presence of any illusions.
- 2.76. When a pilot lacks the visual cues required to orientate themselves correctly, spatial disorientation can occur. The primary visual signal for referencing orientation is the ability to determine where the horizon is, and the loss of this reference typically occurs when flying either in cloud or on dark (moonless) nights when there is little terrestrial lighting. It has been estimated that almost every pilot will experience an episode of spatial disorientation in their flying career.³⁵ Spatial disorientation accidents are frequently fatal, with some studies placing fatality rates as high as 80–90 per cent.³⁶
- 2.77. Given the prevalence of spatial disorientation during flight, there is an extensive body of international industry guidance material available to pilots. Much of this guidance material is captured in the Australian Transport Safety Bureau (2007) research and analysis report. To avoid becoming spatially disorientated during night flight, the report recommends the following:

Pilots should seriously weigh the option of rescheduling a flight if it would otherwise involve night VFR operations. If night VFR operations are conducted, then pilots need to consider the amount of celestial light that will be available, including information about the phase of the moon, and whether high level cloud will reduce the amount of light that would increase the challenges of night operations.³⁷

³³ Vision (eyes), vestibular (inner ear) and proprioceptors (receptors within the subcutaneous tissues).

³⁴ For a comprehensive review of how the vestibular system works, see Demir, A. E. & Aydin, E. (2021). Vestibular illusions and alterations in aerospace environments. *Turk Arch Otorhinolaryngology*, 59(2): 139-149.

³⁵ ATSB Aviation Research and Analysis Report B2007/0063, An Overview of spatial disorientation as a factor in aviation accidents and incidents. <https://www.atsb.gov.au/publications/2007/b20070063>

³⁶ (Lyons, Ercoline, Freeman, & Gillingham, 1994, pp. 147-152); (Gibb, Ercoline, & Scharff, Spatial Disorientation: Decades of Pilot Fatalities, 2011, pp. 717-724); (Gresty, Golding, Le, & Nightingale, 2008, pp. 105-111); (Gibb, Gray, & Scharff, Aviation Visual Perception: Research, Misperception and Mishaps, 2010).

³⁷ (Newman, 2007, p. 24).

- 2.78. To recover from being spatially disorientated, pilots must rely on their flight instruments and be able to interpret and trust the information that is provided correctly, despite experiencing what can be powerful and disorientating motion sensations incongruent with what is displayed on the instruments.

When a pilot's vision is compromised by darkness or bad weather conditions... acceleratory motion cues can cause the development of SD [spatial disorientation]; however, the pilot usually avoids it by referring to the aircraft instruments for orientation information. If the pilot is unskilled at interpreting the instruments, if the instruments fail or, as frequently happens, if the pilot neglects to look at the instruments, those misleading motion cues inevitably cause disorientation.

A pilot is far less likely to become disoriented if he or she uses the instruments as soon as out-of-cockpit vision is compromised and stays on the instruments until continuous contact flying is assured. (Davis, Johnson, Stepanek, & Fogarty, 2008, p. 185)

- 2.79. Research on spatial disorientation indicates that, for helicopter pilots who are not instrument rated, loss of control can occur within about 60 seconds when they lose a clearly defined horizon. Many regulatory and aviation safety agencies have taken steps to highlight the dangers of spatial disorientation for non-instrument-rated pilots, including through the educational videos [178 Seconds to Live](#)³⁸ for aeroplane pilots and [56 Seconds to Live](#)³⁹ for helicopter pilots. See Appendix 2 for a summary of recent occurrences of spatial disorientation reported in New Zealand and Australia.

³⁸ <https://youtu.be/pc9xl4kpY4w>

³⁹ <https://ushst.org/56secs>

3 Analysis

Tātaritanga

Introduction

- 3.1. The accident flight was a positioning flight from the operator's base in Milton to a client's cherry farm near Alexandra and was being conducted as a night VFR flight.
- 3.2. The pilot had spent the previous night at the same property, conducting frost-protection flights after repositioning the aircraft during the day in accordance with the operator's procedures. The pilot therefore had some familiarity with the area of operations and the route to and from the destination. They had recently flown the route to and from during daylight hours only.
- 3.3. The following section analyses the circumstances surrounding the event to identify those factors that increased the likelihood of the event occurring or increased the severity of its outcome. It also examines two safety issues that have the potential to affect future operations adversely.

What happened

- 3.4. The flight proceeded normally until immediately before Lawrence, and tracking data showed the track over the ground was consistent with, although much higher than, those tracks the helicopter had previously flown to and from the same destination. The previous flights were conducted during daylight with both the same pilot the previous day and a different pilot from the operator the day before.
- 3.5. Immediately before and after the township of Lawrence, there was a series of turns. The turns were followed by an apparent loss of control of the helicopter, which then spiralled down, striking the ground.

Avenues of inquiry

- 3.6. The Commission considered several potential contributing factors to the loss of control of the helicopter and the subsequent high-energy vertical impact with terrain. Some of these potential contributing factors are discussed below.

Medical

- 3.7. The pilot was 36 years old and held a valid class 1 medical certificate with no restrictions. They had no known underlying medical conditions. A review of the pilot's recent history indicated there were no fatigue issues and he was observed to be in good health leading up to the accident. There was no presence of any performance-impairing substances. While the inability to conduct a comprehensive autopsy could not fully exclude a medical event, the Commission's medical expert considered, based on the pilot's medical records and the evidence available, that it was **very unlikely** that the pilot suffered a medical event leading to a loss of control.

Mechanical

- 3.8. The helicopter was maintained in accordance with the manufacturer's instructions, with no outstanding maintenance requirements, defects or airworthiness bulletins in effect at the time of the accident.
- 3.9. As discussed in paragraph 2.34, the helicopter should have departed with a full fuel load. This was supported by the operator's comments, the type of operation to be flown and the finding of fire at the accident.
- 3.10. The helicopter's empty weight was 1331.0 kg⁴⁰ and the maximum allowed take-off weight was 2250 kg. Allowing for a full fuel load of 427 kg⁴¹, this left about 492 kg of usable weight for the pilot and any cargo or operations equipment. No evidence of any significant extra cargo⁴² was found at the accident scene, nor was any expected. It was therefore **virtually certain** that the helicopter weight and centre of gravity were within limits.
- 3.11. Further to the evidence in paragraph 2.48, the BEA concluded that there was no sign of failure of the monitored aircraft systems before the accident.
- 3.12. Signature marks on the main rotor hub were consistent with the blades rotating at speed on impact.
- 3.13. The helicopter's initial turns by Lawrence, first to the right and then to the left, showed that the helicopter was under control. It was also **very unlikely** that there were any mechanical or system malfunctions during this time.

Environment

- 3.14. The moon had set approximately one hour and 15 minutes before the accident. The beginning of morning civil twilight was at 0617, about one hour after the helicopter had departed the operator's base, and the sun was not due to rise until 0641.
- 3.15. There were several built-up areas in the initial segment of the flight. When the helicopter first took off, and until just past Lawrence, it is **very likely** that there was light available to provide a clearly defined horizon from terrestrial sources such as houses, streetlights and vehicles.
- 3.16. It was close to the darkest part of the night when the helicopter took off and there would have been insufficient light for a clearly defined horizon in the Lammerlaw Range area, after passing Lawrence.

Cloud

- 3.17. The weather forecast and reports, the observations of another pilot who flew past the operator's base and the first responders who located the accident site, indicates it was **virtually certain** that there was cloud in the vicinity of Lawrence as the helicopter approached.
- 3.18. The highest terrain on a direct track from Milton to the orchard was about 3300 feet amsl, about 42 nm (78 km) or just after the halfway point, with other high ground in the second half of the flight. The helicopter had maintained a climb since departure

⁴⁰ Established by re-weighing on 6 August 2021.

⁴¹ 540 litres converted at specific gravity of 0.79, as per the Airbus Helicopters AS350 B3e Flight Manual.

⁴² Evidence of a standard away kit, including blade tie-downs, covers and spare oil, was found at the scene.

from Milton, passing 3300 feet about 4 minutes after departure and continuing to climb to the ultimate altitude of 7250 ft amsl (2200m).

- 3.19. MetService observations and calculations relating to the weather conditions over Otago on 16 September 2021 detailed the sky was clear at the operator’s base at the time the helicopter departed. The first cloud would have been located about 8 nm (14 km) after departure, with the estimated cloud tops at about 3700 ft amsl, increasing in altitude to an estimated altitude of about 7100 ft amsl near the accident site (see Helicopter altitude (blue line) and cloud top estimates (black line))




Figure 11: Altitude of helicopter and cloud tops estimates along track

Credit: MetService

- 3.20. There are a number of possible explanations for the pilot’s decision to climb well above the height of the maximum ground elevation on the flight path, and these include:
- to climb above the cloud layer, with the expectation that there would be clear air at the destination
 - to climb sufficiently to see the lights at the destination as early as possible, to give a clearly defined horizon in the dark area of the Lammerlaw Range after passing Lawrence
 - to give the maximum safety buffer over the rising terrain
 - a combination of some, or all, of the above.
- 3.21. At night, cloud is only visible in the presence of light, such as light from the ‘glow’ of a built-up area or moonlight. It is **very likely** that any cloud present would have only been visible with the aid of terrestrial lighting, such as the lights of Lawrence. There was no moonlight at the time of the flight to illuminate cloud away from terrestrial lighting.

- 3.22. The only celestial lighting available above the cloud layer would have been from starlight. In ideal situations, starlight could give adequate illumination to see some types of cloud if there is no light pollution to reduce the effectiveness of the eye. The aircraft instrument lights would have been on during the flight, normally at a low setting⁴³, but still providing some light pollution that would affect the pilot's night vision. It is **very unlikely** that the pilot would have been able to see the cloud tops in the available starlight or have a clearly defined horizon.
- 3.23. It was **very likely** that the pilot was attempting to avoid cloud when they initially turned right just prior to Lawrence. They then attempted to re-establish a flight path direct to their destination when turning left after passing Lawrence.
- 3.24. With increasing cloud cover and diminishing terrestrial light as the flight progressed past Lawrence, it is **exceptionally unlikely** that the pilot would have been able to see any cloud present before losing their clearly defined horizon.
- 3.25. The loss of a clearly defined horizon at night can be caused by a lack of suitable light sources or cloud obscuring any light sources that are available, even if the aircraft remains clear of cloud. It can also be caused by flight into cloud or visible moisture.
- 3.26. The pilot was not qualified for flight in cloud⁴⁴ and the aircraft was not certified for flight in icing conditions⁴⁵, so the options available to the pilot, once they lost their clearly defined horizon, included:
- turn into known clear air, usually through 180 degrees to return along the flight path
 - attempt to climb to the top of the cloud level
 - descend to warmer air.
- 3.27. The first option, to turn through 180 degrees, is the most difficult to execute for a non-instrument rated pilot when attempting to fly on instruments. However it is usually the safest option with regard to the conditions. If the turn is not completed successfully, it can rapidly lead to spatial disorientation.
- 3.28. The second and third options are easier to achieve, for a non-instrument rated pilot when flying on instruments. However, they are risky when the extent of the cloud base and tops is unknown.

Icing

- 3.29. The freezing level was forecast to be between 3000 and 3500 ft amsl over the Otago region.
- 3.30. A pilot can expect icing when flying in visible precipitation, such as rain or cloud droplets, and the temperature is between +2°C and –10°C (Federal Aviation Administration, 2023).
- 3.31. The consequences of ice accretion⁴⁶ include:

⁴³ By necessity, bright enough for the pilot to be able to read the instruments with normal vision. This would contrast to a cockpit set up for Night Vision Imaging System operations, where the instruments have special lighting that has less impact on the visual acuity of the Night Vision Imaging System.

⁴⁴ As they did not have an IFR qualification.

⁴⁵ AS350 B3e flight manual.

⁴⁶ The process by which a layer of ice (icing) builds up on solid objects that are exposed to freezing precipitation or to supercooled fog or cloud droplets.

- changes to the shape of the blade aerofoil, and therefore changes to its lift coefficient
- an increase in the blade's drag coefficient
- an increase in the aircraft's gross weight

The first two factors influence the helicopter's lift/drag ratio, which in turn degrades the rotor thrust/rotor drag ratio when the total reaction leans further away from the axis of rotation.

Icing then can initially be detected by the need for more power as rotor rpm falls off when increased rotor drag begins to take its toll. Since ice accretion is almost always uneven throughout the disc, the resulting vibration gives the pilot an additional warning of ice buildup.

- 3.32. The temperatures the helicopter was flying in were in the range for aircraft icing, and the formation of icing cannot be ruled out entirely. However, there are several factors that indicate that it is **unlikely**.
- 3.32.1. The helicopter appears to have remained above the estimated cloud tops until the very end of the flight. Flight in visible moisture⁴⁷ is a prerequisite for ice formation.
- 3.32.2. The helicopter continued to climb throughout the flight, including gaining 200 ft in the beginning of the final right turn. Icing will increase the weight of the aircraft, and generally also reduces the lift available, thereby requiring increased power to continue climbing and maintaining airspeed. In extreme cases there is no further power available, and the aircraft begins to descend. There is no indication from the evidence available that this occurred in this instance.

Spatial disorientation

- 3.33. Spatial disorientation as a possible cause is a well-documented contributing factor to accidents at night-time.
- 3.34. VFR pilots are trained to always have a clearly defined horizon to protect against experiencing spatial disorientation and a subsequent loss of control of their aircraft in flight.
- 3.35. Flying at night requires a skill set that is different from flying during the day, because of the reduction in visual cues. In September 2020 the CAA revised its Good Aviation Practice booklet on night VFR to assist pilots. A section on illusions begins with:
- It is good practice to fly at night by regular reference to instruments, even when external lighting provides good visual cues, because visual and spatial illusions can provide misleading information, and visual reference can be suddenly lost. Use your awareness of illusions to avoid these pitfalls (Civil Aviation Authority of New Zealand, 2020).
- 3.36. It was therefore recognised by the CAA that it is important that a pilot has at least a basic knowledge and understanding of, and proficiency in, the skills required to fly at night with sole reference to an aircraft's flight instruments. The fewer visual cues available, the greater the reliance the pilot must have on their instruments, keeping in

⁴⁷ Cloud or freezing rain.

mind that night VFR is still governed by the visual flight rules, with the emphasis on maintaining a clearly defined horizon.

- 3.37. The requirement for instrument skills was reflected in the minimum number of hours of dual instrument instruction required prior to a pilot being issued with a night rating. However, there was no requirement for instrument currency, which is discussed further in paragraphs 3.61 to 3.72.
- 3.38. Approaching Lawrence, a definite and deliberate course change was made. Initially there was a turn to the right through 53 degrees, taking 20 seconds. The rate of turn equated to 159 degrees a minute, slightly less than a rate one turn⁴⁸. The helicopter climbed about 200 ft (60 m) during the turn, at a climb rate of about 600 ft per minute (182 m per minute). While the climb rate was higher than ideal with reduced visual cues, it was consistent with the climb rate before the turn (see Figure 5).
- 3.39. The previous flights, conducted during daylight hours, had generally followed the road. At night on the same route, the only significant terrestrial light was emitted at the townships and through other cultural lighting along the way. In contrast, the area towards which the pilot turned was uninhabited and had minimal or no terrestrial lighting.
- 3.40. The change in course was **very likely** an attempt to avoid cloud visible to the pilot near the township of Lawrence. The cloud in the area was broken (see para 2.36) and would have allowed some visibility of lights from the ground for the pilot. The region to the right of the track would have appeared darker, potentially giving the illusion of no cloud being present in that area.⁴⁹
- 3.41. About two and a half minutes after the alteration in course, the helicopter entered a second right turn at an altitude of 7150 ft (2180 m) amsl, this time with a rate of turn of about 400 degrees per minute, or more than double a rate one turn. The angle of bank⁵⁰ was calculated to average about 37 degrees, based on recorded groundspeed and rate of turn.
- 3.42. Initially climbing about 100 ft in 7 seconds, the helicopter then descended with a rate of descent in excess of 4200 ft (1280 m) per minute⁵¹ during the turn. The helicopter then immediately entered a descending and tightening left turn, descending about 3200 ft to a near vertical nose-down impact with terrain.
- 3.43. At high angles of bank, a pilot would likely start feeling the effects of the increased loading⁵². Unless properly managed, an increased loading can have a disorientating effect on a pilot, especially if they move their head during the turn with reduced visual cues.
- 3.44. Moving their head to look where they were going would be a normal reaction for a VFR pilot, as they would be more used to looking outside the aircraft while flying visually than following the instrument-flying requirement to keep their head still and their eyes scanning the helicopter instrument panel.

⁴⁸ A turn accomplished at 3 degrees per second (180 degrees per minute), and the maximum recommended rate of turn when flying with sole reference to instruments. Also known as a standard turn.

⁴⁹ See also the Commission report AO-2019-00549 Controlled Flight into Terrain (Water) in which the pilot experienced a similar visual illusion.

⁵⁰ The angle at which a vehicle is inclined about its longitudinal axis with respect to the plane of its curved path.

⁵¹ Turning through almost 160 degrees and initially climbing, then descending to 5700 ft amsl in 24 seconds.

⁵² A type of acceleration force that causes a perception of weight otherwise known as g-force.

- 3.45. Soon after passing Lawrence, and approaching the Lammerlaw Range area, the pilot was flying into an area of reduced visibility and **very likely** lost their clearly defined horizon. The helicopter continued to climb straight ahead for nearly three minutes before the pilot **very likely** became disorientated.
- 3.46. The pilot had not logged any instrument flying in the past nine years. They also did not have a night cross-country rating or an Instrument Flight Rules rating. The pilot was therefore **very unlikely** to be proficient in flying by sole reference to the instruments, and this was exacerbated by the urgency of needing to transition rapidly from flying by reference to visual cues.
- 3.47. Non-instrument rated pilots who are not proficient at flying on instruments would require a degree of concentration when conducting basic instrument skills such as the scan required to maintain a straight and level attitude. Any additional manoeuvres, such as turning the aircraft, will demand more cognitive resource as the pilot is now subjected to vestibular illusions⁵³ and must adapt their scan accordingly to counter this. In this case, the pilot was able to continue flying past Lawrence for several minutes in an apparently controlled manner before the final right-hand turn.
- 3.48. It is possible that the final right turn was an attempt by the pilot to reverse course and reestablish a clearly defined horizon, however it cannot be discounted that the turn itself was the result of the pilot becoming spatially disorientated.
- 3.49. The high angle of bank and the lack of a clearly defined horizon during the right-hand turn would significantly increase the risk of spatial disorientation and then the loss of control of the helicopter. The time from when the helicopter began the final right turn until impact with the ground was about 60 seconds (see para 2.79).

Summary

- 3.50. The investigation found no evidence of a medical event or a mechanical issue with the helicopter. The prevailing environmental conditions meant that the pilot, who was **very likely** not proficient flying solely on instruments at the time of the accident, **very likely** did not have a clearly defined horizon. These factors, together with the aircraft's tracking data during the last minute of the flight are consistent with pilot spatial disorientation.

Other factors that affect safety

Night-flying rules

Safety issue: The rules and guidance information for night VFR are ambiguous. This could lead to night VFR pilots flying longer distances at night and encountering night-flying conditions outside their capabilities.

- 3.51. Through the inquiry, the Commission found ambiguity existed around what was permitted under the night VFR rules and guidance.
- 3.52. Ambiguity, regardless of intention, creates opportunities for differing interpretations – including for rules to be read to allow the most leniency possible.
- 3.53. The wording of AC61-5 is ambiguous in light of the rules regarding what a pilot, who was restricted to operations within 25 nm of a lighted heliport or aerodrome, was

⁵³ See paragraph 2.75

permitted to do. It is unclear whether such a pilot could transit from point A to point B provided they were always within 25 nm of any lighted heliport or aerodrome (ie, the departure and destination were within 50 nm). There is further ambiguity around whether a third intermediate lighted heliport or aerodrome could be used as a waypoint en route to facilitate even longer flights at night (see Figure 12).




Figure 12: Illustration of 25 nm restriction

- 3.54. The Commission sought clarification from the CAA on the above interpretation of the CARs. The CAA responded that while AC61-5 could be clearer, the intent was that a pilot travelling beyond 25 nm from their point of departure at night would require the higher standards of the night cross-country rating.
- 3.55. The 25 nm restriction at night appears to be unique to New Zealand, with all other major jurisdictions restricting night VFR flights to the aerodrome circuit or requiring pilots to have a full night cross-country rating. The CAA's position is that it is commonly referenced within the Rules/advisory circulars that the 25 nm radius is the limiting distance for flights to be considered cross country. The Commission was unable to determine the relevance of the 25 nm limit.
- 3.56. The operator advised the Commission that as the flight was within 21 nm of Dunedin, and then using Roxburgh and Alexandra for short 'hops' within 25 nm of each other would have meant that in their view there was no requirement for a night cross-country rating for this flight (see Figure 13). The operator's interpretation of AC61-5 appears to be different from CAA's own interpretation of the intent of AC61-5, as stated by the CAA to Commission investigators.
- 3.57. According to the Aeronautical Information Publication New Zealand, neither Roxburgh nor Alexandra had aerodrome lighting. However, the exact lighting that would be required for a helicopter to operate at those aerodromes at night was not defined in the CARs.
- 3.58. There is no clear definition of what constitutes a 'lighted' heliport. This adds further to the potential for pilots to incorrectly interpret night VFRs.

- 3.59. During the investigation, Commission investigators became aware of different interpretations, among other helicopter pilots and operators, of what is permitted under the rules for visual night flying.
- 3.60. The investigation found a **safety issue** in that the current rules and guidance for visual night flying, and night currency requirements, do not adequately mitigate the risks of conducting visual flying at night. The Commission has made a recommendation in Section 6 to address this.




Figure 13: Flight path with 25 nm range rings

Instrument currency requirements for night flying

Safety issue: The current rules on and guidance for instrument currency for night VFR do not adequately mitigate the risks of inadvertent flight into conditions where a clearly defined horizon is lost.

- 3.61. The pilot was a Category B helicopter flight instructor with about 4230 hours' total flight time. Their logbook showed they had a restricted (25 nm) night rating with a total of about 63 hours' night flying experience, consisting predominantly of instructing students, with some night frost-protection flying.
- 3.62. The pilot's logbook recorded 20 hours of instrument flight time, all of which were simulated⁵⁴, with no flight time logged showing flight in actual instrument meteorological conditions with sole reference to aircraft instruments. The last entry in the pilot's logbook recording the pilot flying by reference to instruments was in April 2012, about nine and a half years before the accident.
- 3.63. The pilot was an experienced aviator and was trained in and qualified for restricted night flying, including also having in excesses of the minimum instrument flight time (but not the qualification) required for an unrestricted night rating. The Commission could not identify from the pilots' logbook if the pilot had done the cross-country flight training component of a night cross-country rating.
- 3.64. The pilot met the currency requirements for the restricted night rating that they held. However, the pilot's logbook recorded no instrument flight time in the nine years preceding the accident. They would therefore have been **very unlikely** to be proficient in this skill.
- 3.65. The importance of instrument currency for pilots is summed up in Fundamentals of Aerospace Medicine when discussing spatial disorientation:

The important factors to the pilot in preventing SD [spatial disorientation] are confidence, competency, and currency in instrument flying. It is virtually assured that a non-instrument-rated pilot who penetrates instrument weather will develop SD within a matter of seconds, just as a competent instrument-rated pilot will develop it if he or she flies in weather without functioning flight instruments. Regarding instrument flying skill, one must "use it or lose it," as they say. For that reason, it is inadvisable (and perhaps illegal) for a pilot to be in command of an aircraft in instrument weather if he or she has not had a certain amount of recent instrument flying experience (Davis et al., 2008, p. 187).
- 3.66. AC61-5 requires a pilot to have a minimum experience of two hours' dual-instrument flight instruction in helicopters to operate within 25 nm of a lighted heliport or aerodrome at night. A minimum of 10 hours' dual-instrument flight instruction in helicopters⁵⁵ is required for a night cross-country rating, to fly beyond 25 nm of a lighted heliport or aerodrome at night.
- 3.67. At the time of the accident there was no requirement for ongoing instrument recurrency training or competency assessments once the applicable night rating was awarded.

⁵⁴ Simulated flight in instrument meteorological conditions by restricting the pilot's view outside and with a safety pilot for aircraft separation.

⁵⁵ Of which no more than five hours may be instrument time in a synthetic helicopter flight trainer.

- 3.68. Flying with reference solely to instruments is a perishable skill, and pilots who held Instrument Flight Rules ratings were required to undertake refresher training as per CARs Part 61.807 with 3-month and 12-month requirements.
- 3.69. A non-Instrument Flight Rules rated pilot was not required to maintain instrument flight currency. Such a pilot flying under VFR who lost the required visual cues is unlikely to have the instrument flying competency and ability to transition to flying by sole reference to instruments. A loss of visual cues can occur suddenly and without warning, having a startle effect⁵⁶ on the pilot with the associated risk of further exacerbating the situation.
- 3.70. The SKYbrary⁵⁷ article 'Inadvertent VFR Flight into IMC' (instrument meteorological conditions) gives a concise review of the threats, likely errors and risk management required if a pilot inadvertently loses visual reference. While it is written with a Private Aeroplane Pilot Licence holder in mind, the lessons contained are relevant to any pilot licence holder without an instrument rating (SKYbrary, n.d.).
- 3.71. The pilot exceeded the minimum requirement for instrument time for their restricted night rating by a factor of 10, and they had almost double the required instrument hours for a night cross-country rating. However, they had not logged any instrument time in more than nine years at the time of the accident. The importance of instrument currency is discussed in paragraph 2.78.
- 3.72. The lack of any requirements for recent experience in instrument flight for a VFR pilot at night was a **safety issue** given the recognised difficulty when transitioning from flight with visual reference to the ground to flight with sole reference to aircraft instruments. The Commission has made a recommendation in Section 6 to address this.

Emergency Locator Transmitter

- 3.73. The ELT not activating when the helicopter struck the ground is of concern. The ELT is designed to emit an emergency broadcast signal, usually including a location, when an aircraft experiences g-forces consistent with an accident. The broadcast signal is used by SAR teams to aid in locating accident sites. An expedient locating of a crashed aircraft increases the chances of survival for the occupant/s, although the pilot did not survive this accident.
- 3.74. The exact cause of the failure of the ELT to activate could not be determined. However, it is **as likely as not** that the impact forces were outside its design parameters.
- 3.75. Despite not having an ELT location on which to base their search pattern, the SAR helicopter crew were able to locate the wreckage about 73 minutes after commencing their search. The biggest delay was **almost certainly** caused by the time taken for the cloud base to lift above the accident site.
- 3.76. The availability of tracking data from the onboard helicopter tracking system, and the available ADS-B data, combined to give searchers a small and accurate area in which

⁵⁶ Defined in SKYbrary as an uncontrollable, automatic reflex that is elicited by exposure to a sudden, intense event that violates a pilot's expectations. <https://www.skybrary.aero/articles/startle-effect>.

⁵⁷ International repository of aviation-related information managed by European Union Aviation Safety Agency (EASA) and Flight Safety Foundation.

to search for the wreckage. These systems **almost certainly** reduced the size of the search area and the time taken for searchers to find the accident site.

- 3.77. The Commission has previously made recommendations⁵⁸ to the CAA to improve the performance of ELTs. The importance of technologies to track and to locate has been an item on the Commission Watchlist since 2015.⁵⁹ These technologies improve people's chances of surviving aircraft accidents and incidents. The Commission has also commented on technologies to locate vessels and rail vehicles. This accident reinforces those recommendations.

Cockpit video recorders

- 3.78. Cockpit video recorders are now available, and the Commission has recommended that these be fitted to helicopters and other general aviation aircraft to help explain how accidents occur. The Commission acknowledges the efforts aviation industry participants have made in developing affordable video, audio, and data recorders; and the regulators' work to enable fitment of these technologies via Supplemental Type Certificates. Where fitted, these recorders can provide valuable information about causes of accidents and help avoid recurrences. The helicopter in this accident was not fitted with a cockpit video recorder, potentially denying investigators valuable insights into the progress of the flight.

⁵⁸ TAIC inquiry AO-2011-003 In-flight break-up ZK-HMU, Robinson R22, near Mount Aspiring, 27 April 2011.

⁵⁹ <http://www.taic.org.nz/watchlist/technologies-track-and-locate>

4 Findings

Ngā kitenga

- 4.1. It was **very unlikely** that the aircraft suffered a mechanical defect, or that the pilot suffered a medical event, that contributed to the loss of control.
- 4.2. It was **virtually certain** that there was cloud in the vicinity of Lawrence as the helicopter approached.
- 4.3. It was **very likely** that the pilot was attempting to avoid cloud around Lawrence.
- 4.4. It was **very likely** that the pilot lost their clearly defined horizon, soon after passing Lawrence.
- 4.5. The pilot **very likely** became spatially disorientated either immediately before, or during, the final right turn.
- 4.6. The pilot's logbook recorded no instrument flight time in the nine years preceding the accident. They were therefore **very unlikely** to be proficient in this skill.
- 4.7. There was no clear definition of lighted heliport in the Civil Aviation Rules or advisory circulars.
- 4.8. There was no clarity around the rationale for the 25-nm restricted night rating.
- 4.9. The Emergency Locator Transmitter did not activate, but the use of other tracking technologies assisted the search for the wreckage in a timely manner.

5 Safety issues and remedial action

Ngā take haumanu me ngā mahi whakatika

General

- 5.1. Safety issues are an output from the Commission's analysis. They may not always relate to factors directly contributing to the accident or incident. They typically describe a system problem that has the potential to adversely affect future transport safety.
- 5.2. Safety issues may be addressed by safety actions taken by a participant. Otherwise the Commission may issue a recommendation to address the issue.

Safety issues

The rules and guidance information for night VFR are ambiguous. This could lead to night VFR pilots flying longer distances than permitted at night and encountering night flying conditions outside their capabilities.

- 5.3. The requirements for the issue of a private or commercial helicopter pilot licence and the privileges, limitations and currency requirements of that licence are set out in CARs Part 61.
- 5.4. A private or commercial helicopter pilot wanting to exercise their privileges during the night must have night flight-time experience acceptable to the Director (CARs Part 61.203(5)) and have the appropriate rating (CARs Part 61.205).
- 5.5. AC61-3 'Pilot Licences and Ratings – Private Pilot Licence' and AC61-5 provide guidance, including on what is considered acceptable flight experience, and the ratings awarded based on that experience.
- 5.6. There is ambiguity between the relevant CARs and the advisory circulars, and within the advisory circulars themselves, as to what a 'night rating' allows a pilot to do. CARs Part 1 defines a cross-country flight as being 25 nm from the point of departure, whereas the advisory circulars calculate a cross-country flight as being 25 nm from the centre of a lighted heliport or aerodrome.
- 5.7. The Commission found evidence that pilots interpreted the CARs and advisory circulars in different ways, including by flying more than 25 nm from their points of departure at night without night cross-country ratings, as long as they remained within 25 nm of any lighted heliport or aerodrome.
- 5.8. The CAA has taken the following safety action to address this issue:
 - A work programme involving a complete horizontal review of the Part 61 Advisory Circular specific to helicopters. The main focus areas are:
 - night flying – including clarification and training guidance of Night VFR operations
 - basic Instrument flying (currency to be included in the BFR⁶⁰ – currently only compass turns)

⁶⁰ Biennial Flight Review is a review of a pilot's current knowledge and flight proficiency, undertaken every two years by a qualified flight instructor

- inadvertent IMC⁶¹ training.
 - An industry helicopter working group has been convened as part of this review in progress.
- 5.9. The Commission welcomes the safety action to-date. However, it believes more action needs to be taken to ensure the safety of future operations. Therefore, the Commission has made a recommendation in Section 6 to address this issue.

The current rules and guidance for instrument currency for night VFR do not adequately mitigate the risks of inadvertent flight into conditions where a clearly defined horizon is lost.

- 5.10. Pilots are only required to complete dual instrument flight training before the issue of the appropriate night rating (restricted or cross-country).
- 5.11. There was no requirement, as part of a night VFR rating, for a pilot to maintain currency or proficiency when flying with sole reference to the aircraft instruments.
- 5.12. However, there is a requirement for an instrument-rated pilot to maintain currency and proficiency.
- 5.13. Complex skills will deteriorate over time and require regular practice to maintain. However, there is a gap in the night-flying rules that night VFR pilots are not required to maintain currency in flight with sole reference to the aircraft instruments.
- 5.14. The risks of inadvertent flight into conditions where a VFR pilot loses a clearly defined horizon, especially when flying at night, are well known and well documented. The importance of having basic instrument flying skills is recognised in the minimum requirements for the issue of a rating.
- 5.15. The CAA has taken the following safety action to address this issue:
- A work programme involving a complete horizontal review of the Part 61 Advisory Circular specific to helicopters. The main focus areas are:
 - night flying – including clarification and training guidance of Night VFR operations
 - basic Instrument flying (currency to be included in the BFR – currently only compass turns)
 - inadvertent IMC training.
 - An industry helicopter working group has been convened as part of this review in progress.
- 5.16. The Commission welcomes the safety action to-date. However, it believes more action needs to be taken to ensure the safety of future operations. Therefore, the Commission has made a recommendation in Section 6 to address this issue.

⁶¹ see paragraph 3.70

6 Recommendations

Ngā tūtohutanga

General

- 6.1. The Commission issues recommendations to address safety issues found in its investigations. Recommendations may be addressed to organisations or people, and can relate to safety issues found within an organisation or within the wider transport system that have the potential to contribute to future transport accidents and incidents.
- 6.2. In the interests of transport safety, it is important that recommendations are implemented without delay to help prevent similar accidents or incidents occurring in the future.

New recommendations

- 6.3. On 27 September 2023, the Commission recommended that the Civil Aviation Authority of New Zealand, in consultation with stakeholders, resolve the ambiguity around night Visual Flight Rules and guidance to ensure they are fit for purpose. **(029/23)**
- 6.4. On 27 September 2023, the Commission recommended that the Civil Aviation Authority of New Zealand, in consultation with stakeholders, establish and clarify instrument currency requirements for night Visual Flight Rules flying. **(030/23)**
- 6.5. On 31 October 2023, the Civil Aviation Authority replied:

In response to these recommendations the CAA is undertaking, or intends to undertake the following:

A complete review of the Part 61 Advisory specific to helicopters is currently underway. The focus areas of this review are:

- Night flying – including clarification and training guidance of Night VFR operations.
- Basic Instrument Flying (currency to be included in the BFR – currently only compass turns)
- Inadvertent IMC training (as above).

An industry helicopter working group has been convened and will, as part of their work, consider the issues raised in recommendation 030/23.

Notice of recommendations

- 6.6. The Commission gives notice to the Ministry of Transport that it has issued recommendations **029/23** and **030/23** to the Civil Aviation Authority of New Zealand, and that these recommendations will require the involvement of the Ministry of Transport.

7 Key lessons

Ngā akoranga matua

- 7.1. The instrument flying skills required for safe night flying are perishable and need to be refreshed regularly.
- 7.2. A pilot is at risk of losing a clearly defined horizon if they do not remain clear of cloud and within sight of the surface. This risk increases when flying at night. To maintain situational awareness and control of their aircraft, the pilot must transition immediately to instrument flight to re-establish a clearly defined horizon.
- 7.3. Visual night cross-country flying requires additional training and different skills from those used for visual night flying near a lighted aerodrome or heliport.
- 7.4. The use of tracking technologies to supplement onboard ELTs can significantly reduce the time taken to locate missing aircraft.
- 7.5. Cockpit video recorders, where fitted, can potentially provide valuable information about causes of accidents and help avoid recurrences.

8 Data summary

Whakarāpopoto raraunga

Aircraft particulars

Aircraft registration:	ZK-ITD
Type and serial number:	Airbus Helicopters (formerly Eurocopter) AS350 B3e serial number 7815
Number and type of engines:	1 Safran (formerly Turbomeca) Arriel 2D turboshaft engine
Year of manufacture:	2014
Operator:	Lister Helicopters Limited
Type of flight:	aerial work
Persons on board:	one

Crew particulars

Pilot's licence:	Commercial Pilot Licence (helicopter)
Pilot's age:	36
Pilot's total flying experience:	about 4230 hours

Date and time

16 September 2021, 0531

Location

Lammerlaw Range, 40 kilometres north-west of Dunedin Aerodrome

latitude: 45° 46.847' south

longitude: 169° 43.449' east

Injuries

fatal

Damage

helicopter destroyed

9 Conduct of the inquiry

He tikanga rapunga

- 9.1. On 16 September 2021 the CAA notified the Commission of the occurrence. The Commission subsequently opened an inquiry under section 13(1) of the Transport Accident Investigation Commission Act 1990 and appointed an Investigator-in-Charge.
- 9.2. In accordance with Annex 13 to the Convention on International Civil Aviation, the Commission notified the state of manufacture of the aircraft and engine, the BEA. On 17 September 2021 the BEA appointed an accredited representative of France and appointed Airbus Helicopters (airframe) and Safran (engine) as its technical advisers.
- 9.3. On 17 September 2021 Commission investigators travelled to Dunedin and then to the accident site. A site examination was conducted between 17 September 2021 and 19 September 2021.
- 9.4. On 19 September 2021 the wreckage was removed from the accident site and transported to the Commission's technical facility in Wellington for further detailed examination.
- 9.5. On 20 September 2021 Commission investigators interviewed witnesses from the search and rescue crews.
- 9.6. On 20 September 2021 Commission investigators visited the operator's base to interview the operator and gather relevant documentation relating to the operator and the maintenance of the helicopter.
- 9.7. Over the next few weeks helicopter- and pilot-related documentation was gathered and further interviews undertaken. Several items were removed from the wreckage and sent to the BEA for examination.
- 9.8. On 6 July 2022 Commission investigators travelled to Invercargill to interview the next of kin.
- 9.9. The final analysis of this investigation was presented to the Commission on 28 August 2022.
- 9.10. On 24 May 2023 the Commission approved a draft report for circulation to four interested parties and the accredited representative for their comment.
- 9.11. The Commission received four submissions. Changes as a result of the submissions are included in the final report.
- 9.12. On 27 September 2023 the Commission approved the final report for publication

Abbreviations

Whakapotonga

AC61-5	Advisory Circular 61-5 'Pilot Licences and Ratings – Commercial Pilot Licence'
ADS-B	the Airways New Zealand Automatic Dependent Surveillance – Broadcast system
amsl	above mean sea level
BEA	Bureau d'Enquêtes et d'Analyses of France
CAA	Civil Aviation Authority (of New Zealand)
CARs	Civil Aviation Rules
ELT	Emergency Locator Transmitter
EDR	Engine Multifunction Display (VEMD), an Engine Data Recorder
EECU	electronic Engine Control Unit
ft	foot
kg	kilogram
km	kilometre
m	metre
nm	nautical mile
SAR	search and rescue
VEMD	Vehicle and Engine Multifunction Display
VFR	Visual Flight Rules

Glossary

Kuputaka

aerodrome	any defined area of land or water intended or designed to be used either wholly or partly for the landing, departure and surface movement of aircraft
angle of bank	the angle at which a vehicle is inclined about its longitudinal axis with respect to the plane of its curved path
helicopter frost protection	low-level helicopter flight over an affected crop to mix warmer air aloft with the cooler air below to prevent frost settling on the crop
heliport	any defined area of land or water, and any defined area on a structure, intended or designed to be used either wholly or partly for the landing, departure and surface movement of helicopters
morning civil twilight	when the centre of the rising sun's disc is 6 degrees below the horizon
evening civil twilight	when the centre of the setting sun's disc is 6 degrees below the horizon

Citations

Ngā tohutoru

- Australian Transport Safety Bureau. (2013, Nov 14). *VFR flight into dark night involving Aérospatiale, AS355F2 (Twin Squirrel) helicopter, VH-NTV, 145 km north of Marree, SA on 18 August 2011*. Retrieved from ATSB: https://www.atsb.gov.au/publications/investigation_reports/2011/air/ao-2011-102
- Australian Transport Safety Bureau. (2019, Aug). *Accidents involving Visual Flight Rules pilots in Instrument Meteorological Conditions*. Retrieved from ATSB: <https://www.atsb.gov.au/publications/2019/avoidable-accidents-4-vfr-into-imc>
- Australian Transport Safety Bureau. (2019, June 06). *Loss of control and collision with terrain involving Cirrus SR22, VH-PDC, Orange Airport, NSW, on 15 May 2018*. Retrieved from ATSB: https://www.atsb.gov.au/publications/investigation_reports/2018/air/ao-2018-038
- Australian Transport Safety Bureau. (2020, Apr 16). *Loss of control in flight involving Leonardo Helicopters AW139 helicopter, VH-YHF, near Adelaide River mouth, 38 km ENE of Darwin, Northern Territory, on 13 May 2018*. Retrieved from ATSB: https://www.atsb.gov.au/publications/investigation_reports/2018/air/ao-2018-039
- Australian Transport Safety Bureau. (2021, Mar 02). *VFR into IMC and loss of control involving Wittman Tailwind, VH-TWQ, Tooloom National Park, New South Wales, on 12 January 2020*. Retrieved from ATSB: https://www.atsb.gov.au/publications/investigation_reports/2020/air/ao-2020-004
- Australian Transport Safety Bureau. (2022, Nov 23). *VFR into IMC and collision with terrain involving Bell Helicopter 206L-4, VH-PRW 33 km north west of Adaminaby, New South Wales on 3 April 2022*. Retrieved from ATSB: https://www.atsb.gov.au/publications/investigation_reports/2022/air/ao-2022-017
- Australian Transport Safety Bureau. (2022, Nov 09). *VFR into IMC and in-flight break-up involving Van's Aircraft RV-7A, VH-XWI 90 km south of Charters Towers, Queensland, on 23 April 2021*. Retrieved from ATSB: https://www.atsb.gov.au/publications/investigation_reports/2021/air/ao-2021-017
- Australian Transport Safety Bureau. (2023, Feb 09). *Collision with terrain involving Robinson R22 Beta II helicopter, VH-HKC, 87 km north of Hughenden Aerodrome, Queensland, 11 February 2021*. Retrieved from ATSB: https://www.atsb.gov.au/publications/investigation_reports/2021/air/ao-2021-006
- Civil Aviation Authority of New Zealand. (2020, September). *Good aviation practice booklets*. Retrieved from CAA and Avsec: <https://www.aviation.govt.nz/safety/education/good-aviation-practice-booklets/>
- Davis, J. R., Johnson, R., Stepanek, J., & Fogarty, J. A. (2008). *FUNDAMENTALS OF AEROSPACE MEDICINE* (4th ed.). Philadelphia, PA, USA: LIPPINCOTT WILLIAMS & WILKINS, a Wolters Kluwer business.
- Federal Aviation Administration. (2023, April 20). *Aeronautical Information Manual*. Washington, D.C, United States of America: U.S Department of Transportation. Retrieved from [faa.gov](https://www.faa.gov/air_traffic/publications/atpubs/aim_html/index.html): https://www.faa.gov/air_traffic/publications/atpubs/aim_html/index.html

- Gibb, R., Ercoline, B., & Scharff, L. (2011, July). Spatial Disorientation: Decades of Pilot Fatalities. *Aviation, Space, and Environmental Medicine*, 82(7), 717-724.
doi:<https://doi.org/10.3357/ASEM.3048.2011>
- Gibb, R., Gray, R., & Scharff, L. (2010). *Aviation Visual Perception: Research, Misperception and Mishaps*. London: Routledge. doi:<https://doi.org/10.4324/9781315568584>
- Gresty, M. A., Golding, J. F., Le, H., & Nightingale, K. (2008, Feb). Cognitive impairment by spatial disorientation. *Aviation, space, and environmental medicine*, 79(2), 105-111.
doi:<https://doi.org/10.3357/ase.2143.2008>
- Lyons, T. J., Ercoline, W. R., Freeman, J. E., & Gillingham, K. K. (1994, February). Classification problems of U.S. Air Force spatial disorientation accidents, 1989-91. *Aviation, space, and environmental medicine*, 65(2), 147-152.
- Newman, D. G. (2007, 12 03). *An overview of spatial disorientation as a factor in aviation accidents and incidents*. Retrieved February 10, 2023, from ATSB:
<https://www.atsb.gov.au/publications/2007/b20070063>
- NZ Civil Aviation Authority. (2022, Mar 23). *Safety investigation reports*. Retrieved from aviation.govt.nz: <https://www.aviation.govt.nz/assets/publications/safety-investigation-reports/20-6775-zk-hgw.pdf>
- SKYbrary. (n.d.). *Inadvertent VFR Flight Into IMC*. Retrieved 08 2023, from SKYbrary:
<https://skybrary.aero/articles/inadvertent-vfr-flight-imc>
- Transport Accident Investigation Commission. (2023, Apr 20). *AO-2021-005*. Retrieved from T.A.I.C: <https://www.taic.org.nz/inquiry/ao-2019-005>
- United States Department of Transportation. (2010, November 18). *Airman Education Programs*. Retrieved from Federal Aviation Administration:
https://www.faa.gov/pilots/training/airman_education/topics_of_interest/spatial_disorientation
- Wagtendonk, W. J. (2011). *Principles of Helicopter Flight* (2nd ed.). Newcastle, Washington, U.S.A: Aviation Supplies & Academics, Inc.

Appendix 1 Advisory Circular AC61-5 Night extract

Helicopter basic mountain flying training is intended only as an introduction to mountainous terrain operations for commercial helicopter pilots or experienced private helicopter pilots.

More extensive mountain flying requires a higher level of knowledge, skill and experience and so requires additional theory and practical training before it can be conducted safely. Therefore, a person holding a commercial helicopter pilot licence issued after 31 August 2008 should not conduct advanced operations in mountainous terrain, including landing at, or making an approach to, any point above the height at which competence has been demonstrated without first completing further training.

Night flying:

Students must have at least 2 hours instrument flight time in helicopters including the following instrument flight manoeuvres before undertaking night flight training:

Straight and level flight: Maintain heading to a required accuracy of $\pm 5^\circ$, ± 100 feet altitude and in-balance.

Medium & rate 1 turns: At least 180° turns left and right, in-balance, to within $\pm 10^\circ$ of pre-selected roll-out heading with a maximum altitude variation of ± 100 feet.

Climbing and descending: To pre-selected altitudes. Level flight to be re-established at the pre-selected altitude \pm no more than 100 feet.

Unusual attitude: Prompt and correct recovery from unusual attitudes.

Emergencies: Establish autorotation and turn into wind.

Helicopters used for the instrument flight training must have operational instruments consisting of at least an airspeed indicator, an altimeter, a turn and slip indicator, a magnetic compass and a VSI.

For night operations within 25 nm of a lighted heliport or aerodrome:

- 2 hours dual instrument flight instruction in helicopters; and
- 10 hours night flight time in helicopters including:
 - 5 hours dual instruction
 - 2 hours solo including 10 solo take-offs, translation circuits and landings at night.

However, where an applicant has completed 5 hours night flight time in helicopters including 2 hours dual instruction, 2 hours solo, and 2 hours dual instrument flight instruction in helicopters, the applicant may exercise the privileges of a PPL(H) at night.

For night operations beyond 25 nm of a lighted heliport or aerodrome (night cross-country):

- 10 hours dual instrument instruction in helicopters of which no more than 5 hours may be instrument time in a synthetic helicopter flight trainer; and
- 10 hours night flight time in helicopters including:
 - 5 hours dual instruction
 - 2 hours solo including 10 solo take-offs, translation circuits and landings at night
 - 3 hours night cross-country training which is to have been conducted in accordance with the syllabus set out in Appendix II of this advisory circular.

An applicant who does not meet these requirements does not comply with rule 61.203(5) and may not exercise those privileges of a CPL(H) at night beyond 25 nm of a lighted heliport or aerodrome.

Cross crediting

Where an applicant produces acceptable evidence of piloting experience in aircraft other than in helicopters, half the pilot-in-command time experienced within the immediately preceding 12 months, up to the maximums that follow, may be credited towards the total flight experience required but not to the specific flight experiences.

For aeroplanes: 50 hours, except that if the pilot-in-command time is in aerial work or air transport operations - 70 hours.

For gliders or powered gliders: 15 hours.

For the above categories combined: 70 hours.

Glider**Total flight experience**

At least 150 hours total flight experience in gliders (except for allowable cross-crediting experience). This time is to include at least the minimum flight time requirements that follow:

Pilot-in-command:

75 hours in gliders.

Cross-country navigation:

20 hours in gliders, other than on aero-tow, which includes:

- 5 hours dual instruction;
- 1 flight of 5 hours duration as pilot-in-command;
- 1 flight of 30 nm in a straight line as pilot-in-command; and
- 5 paddock landings as pilot-in-command at places which are not licensed airfields or recognised glider launching sites.

Launches:

50 launches as pilot-in-command.

To exercise CPL(G) privileges using a specific launch method (winch, aero-tow or auto-tow), the pilot must have performed 25 launches by that method as pilot-in-command and this must be certified in the pilot's logbook.

Instrument flight instruction:

5 hours in aircraft.

Cross-crediting

Where an applicant produces acceptable evidence of piloting experience in aircraft other than in gliders, half the pilot-in-command time experienced within the immediately preceding 12 months up to the maximums that follow, may be credited towards the total flight experience required, but not to the specific flight experiences.

For aeroplanes: 60 hours.

For helicopters: 25 hours.

For permit to fly aircraft: 25 hours.

Appendix 2 Spatial disorientation

Spatial disorientation is defined as the inability of a pilot to correctly interpret aircraft attitude, altitude or airspeed in relation to Earth or other points of reference (SKYbrary, n.d., p. Spatial Disorientation).

The following is a brief summary of some recent relevant incidents in New Zealand and Australia.

Transport Accident Investigation Commission

- AO-2019-005 – BK-117 helicopter, impact with water, vicinity of Auckland Island, 22 April 2019

The helicopter's descent rate became high as the pilot, relying primarily on visual depth perception, believed the helicopter was further from the surface of the sea than it was. When the crew did see an image through the NVGs it was the 20-metre high cliffs several hundred metres ahead and above them. During the manoeuvre to avoid the cliffs, the helicopter impacted the sea. (Transport Accident Investigation Commission, 2023)

Civil Aviation Authority

- 20/6775 In-flight loss of situational awareness leading to spatial disorientation – ZK-HGW, Kawasaki BK117 B-2 – Gowanbridge

The pilot likely encountered a degradation in situational awareness due to the limited information provided by the poor visual cues available, the higher-than-usual mental workload, and distraction. (NZ Civil Aviation Authority, 2022)

Australian Transport Safety Bureau (ATSB)

- AR-2011-050 Accidents involving Visual Flight Rules (VFR) pilots in instrument meteorological conditions

This publication describes a selection of weather-related general aviation accidents and incidents that show weather alone is never the only factor affecting pilot decisions that result in inadvertent IMC [instrument meteorological conditions] encounters. These investigations consistently highlight that conducting thorough pre-flight planning is the best defence against flying into deteriorating weather. (Australian Transport Safety Bureau, 2019)

- AO-2022-017 VFR into IMC and collision with terrain involving Bell Helicopter 206L-4, VH-PRW 33 kilometres (km) northwest of Adaminaby, New South Wales on 3 April 2022

Having encountered the forecast low cloud and reduced visibility conditions, the pilot landed the helicopter at an interim landing site. Later that day, the helicopter then departed into cloud and visibility conditions unsuitable for visual flight. It is highly likely these cloud and visibility conditions resulted in the pilot experiencing a loss of visual reference and probably becoming spatially disoriented. This led to a loss of control and an unsurvivable collision with terrain. (Australian Transport Safety Bureau, 2022)

- AO-2021-017 VFR into IMC and in-flight break-up involving Van's Aircraft RV-7A, VH XWI 90 km south of Charters Towers, Queensland, on 23 April 2021

The pilot again likely entered weather conditions before becoming spatially disorientated, resulting in loss of aircraft control. This led to the airspeed limitations of the aircraft being exceeded before rudder flutter structurally compromised the tail

group, leading to a catastrophic airframe failure and in-flight break-up. (Australian Transport Safety Bureau, 2022)

- AO-2021-006 Collision with terrain involving Robinson R22 Beta II helicopter, VH-HKC, 87 km north of Hughenden Aerodrome, Queensland, 11 February 2021

The pilot of VH-HKC, who did not hold a night visual flight rules (VFR) rating, instrument rating or had night flying experience, continued flying towards his destination in a remote area after last light.

Planning, operational and navigational decisions made by the pilot before and during the flight did not adequately address the risk of visual flight into dark night conditions. Notably, the pilot had a number of opportunities to discontinue the flight before last light when he refuelled his helicopter at other stations in the area.

The pilot continued flying through the period of civil twilight into astronomical twilight then, in dark night conditions and without local ground lighting, inadvertently allowed the VFR-only equipped helicopter to descend into terrain. (Australian Transport Safety Bureau, 2023)

- AO-2020-004 VFR into IMC and loss of control involving Wittman Tailwind, VH-TWQ, Tooloom National Park, New South Wales, on 12 January 2020

En route to Boonah, the aircraft entered an area of reduced visibility and the pilot likely became spatially disorientated resulting in a loss of control and collision with terrain. (Australian Transport Safety Bureau, 2021)

- AO-2018-038 Loss of control and collision with terrain involving Cirrus SR22, VH-PDC, Orange Airport, NSW, on 15 May 2018

The ATSB found that the pilot, who was conducting his first night training flight, likely became spatially disorientated during a go-around manoeuvre, which resulted in a loss of control at low level and collision with terrain. (Australian Transport Safety Bureau, 2019)

- AO-2018-039 Loss of control in flight involving Leonardo Helicopters AW139 helicopter, VH-YHF, near Adelaide River mouth, 38 km ENE of Darwin, Northern Territory, on 13 May 2018

The pilot entered instrument meteorological conditions during approach, and lost control of vertical speed. The helicopter descended to 31 ft above ground level during the event. Reversion to standard pattern and practiced drills allowed the crew to recover the situation and avert an accident. (Australian Transport Safety Bureau, 2020)

- AO-2011-102 VFR flight into dark night involving Aérospatiale, AS355F2 (Twin Squirrel) helicopter, VH-NTV, 145 km north of Marree, SA on 18 August 2011

The helicopter levelled at 1,500 ft above mean sea level, and shortly after entered a gentle right turn and then began descending. The turn tightened and the descent rate increased until, 38 seconds after the descent began, the helicopter impacted terrain at high speed with a bank angle of about 90°. The pilot and the two passengers were fatally injured, and the helicopter was destroyed. (Australian Transport Safety Bureau, 2013)

Kōwhaiwhai - Māori scroll designs

TAIC commissioned its four kōwhaiwhai, Māori scroll designs, from artist Sandy Rodgers (Ngāti Raukawa, Tūwharetoa, MacDougal). Sandy began from thinking of the Commission as a vehicle or vessel for seeking knowledge to understand transport accident tragedies and how to avoid them. A 'waka whai mārama' (i te ara haumarū) is 'a vessel/vehicle in pursuit of understanding'. Waka is a metaphor for the Commission. Mārama (from 'te ao mārama' – the world of light) is for the separation of Rangitāne (Sky Father) and Papatūānuku (Earth Mother) by their son Tāne Māhuta (god of man, forests and everything dwelling within), which brought light and thus awareness to the world. 'Te ara' is 'the path' and 'haumarū' is 'safe' or 'risk free'.

Corporate: Te Ara Haumarū - the safe and risk free path



The eye motif looks to the future, watching the path for obstructions. The encased double koru is the mother and child, symbolising protection, safety and guidance. The triple koru represents the three kete of knowledge that Tāne Māhuta collected from the highest of the heavens to pass their wisdom to humanity. The continual wave is the perpetual line of influence. The succession of humps represents the individual inquiries.

Sandy acknowledges Tāne Māhuta in the creation of this Kōwhaiwhai.

Aviation: Ngā hau e whā - the four winds



To Sandy, 'Ngā hau e whā' (the four winds), commonly used in Te Reo Māori to refer to people coming together from across Aotearoa, was also redolent of the aviation environment. The design represents the sky, cloud, and wind. There is a manu (bird) form representing the aircraft that move through Aotearoa's 'long white cloud'. The letter 'A' is present, standing for a 'Aviation'.

Sandy acknowledges Ranginui (Sky father) and Tāwhirimātea (God of wind) in the creation of this Kōwhaiwhai.

Maritime: Ara wai - waterways



The sections of waves flowing across the design represent the many different 'ara wai' (waterways) that ships sail across. The 'V' shape is a ship's prow and its wake. The letter 'M' is present, standing for 'Maritime'.

Sandy acknowledges Tangaroa (God of the sea) in the creation of this Kōwhaiwhai.

Rail: rerewhenua - flowing across the land



The design represents the fluid movement of trains across Aotearoa. 'Rere' is to flow or fly. 'Whenua' is the land. The koru forms represent the earth, land and flora that trains pass over and through. The letter 'R' is present, standing for 'Rail'.

Sandy acknowledges Papatūānuku (Earth Mother) and Tāne Mahuta (God of man and forests and everything that dwells within) in the creation of this Kōwhaiwhai.



Transport Accident Investigation Commission

Recent Aviation Occurrence reports published by the Transport Accident Investigation Commission (most recent at top of list)

AO-2020-002	Glider, Schleicher ASK21, ZK-GTG, Impact with Terrain, Mount Tauhara, Taupō, 31 May 2020
AO-2022-001	Ultramagic Balloons, N-250, ZK-MET, pilot ejection from basket on landing, Lyndhurst, near Methven, 1 January 2022
AO-2021-001	Kavanagh Balloons E-260, ZK-FBK, hard landing and ejection of occupants, Wakatipu Basin, near Arrowtown, 9 July 2021
AO-2019-007	Air traffic services outage, 30 September 2019
AO-2019-005	BK-117-C1 ZK-IMK controlled flight into terrain (water), Auckland Islands, 22 April 2019
AO-2020-003	Eurocopter EC120-B, ZK-HEK, Loss of control in flight and collision with terrain, Kekerengu, 50 kilometres northeast of Kaikoura, 15 December 2020
AO-2019-006	Cessna 185A, ZK-CBY and Tecnam P2002, ZK-WAK, Mid-air collision, near Masterton, 16 June 2019
AO-2019-002	Bombardiers DHC-8-311, ZK-NEH, and ZK-NEF, 'Loss of separation' near Wellington, New Zealand, 12 March 2019
AO-2020-001	Pacific Aerospace Cresco 08-600, ZK-LTK impact with terrain Kourarau Hill, Masterton, 24 April 2020
AO-2019-003	Diamond DA42 aeroplane, impact with terrain, 22 nautical miles south-southeast of Taupo, Kaimanawa Ranges, 23 March 2019
AO-2018-005	MD Helicopters 600N, ZK-ILD, Engine control malfunction and forced landing, Ngamatea Station, 14 June 2018
AO-2018-001	Tandem parachute UPT Micro Sigma, registration 31Z, Double malfunction, Queenstown, 10 January 2018

Price \$20.00

ISSN 2815-8717 (Print)
ISSN 2815-8725 (Online)