

Transport Accident Investigation Commission

Final report Tuhinga whakamutunga

Aviation inquiry AO-2023-010 Kawasaki BK117 B-2, ZK-HHJ Collision with terrain Mount Pirongia 19 September 2023

April 2025



The Transport Accident Investigation Commission Te Kōmihana Tirotiro Aituā Waka

No repeat accidents - ever!

"The principal purpose of the Commission shall be to determine the circumstances and causes of accidents and incidents with a view to avoiding similar occurrences in the future, rather than to ascribe blame to any person."

Transport Accident Investigation Commission Act 1990, s4 Purpose

The Transport Accident Investigation Commission is an independent Crown entity and standing commission of inquiry. We investigate selected maritime, aviation and rail accidents and incidents that occur in New Zealand or involve New Zealand-registered aircraft or vessels.

Our investigations are for the purpose of avoiding similar accidents and incidents in the future. We determine and analyse contributing factors, explain circumstances and causes, identify safety issues, and make recommendations to improve safety. Our findings cannot be used to pursue criminal, civil, or regulatory action.

At the end of every inquiry, we share all relevant knowledge in a final report. We use our information and insight to influence others in the transport sector to improve safety, nationally and internationally.

Commissioners

Chief Commissioner	Jane Meares (until 30 September 2024)
Chief Commissioner	David Clarke (from 1 October 2024)
Deputy Chief Commissioner	Stephen Davies Howard
Commissioner	Paula Rose, QSO
Commissioner	Bernadette Roka Arapere
Commissioner	David Clarke (until 30 September 2024)

Key Commission personnel

Chief Executive	Martin Sawyers
Chief Investigator of Accidents	Naveen Kozhuppakalam
Lead Investigator	Jeffrey Shearer
Commission General Counsel	Cathryn Bridge

Notes about Commission reports Kōrero tāpiri ki ngā pūrongo o te Kōmihana

Citations and referencing

The citations section of this report lists public documents. Documents unavailable to the public (that is, not discoverable under the Official Information Act 1982) are referenced in footnotes. Information derived from interviews during the Commission's inquiry into the occurrence is used without attribution.

Photographs, diagrams, pictures

The Commission owns the photographs, diagrams and pictures in this report unless otherwise specified.

Verbal probability expressions

For clarity, the Commission uses standardised terminology where possible.

One example of this standardisation is the terminology used to describe the degree of probability (or likelihood) that an event happened, or a condition existed in support of a hypothesis. The Commission has adopted this terminology from the Intergovernmental Panel on Climate Change and Australian Transport Safety Bureau models. The Commission chose these models because of their simplicity, usability, and international use. The Commission considers these models reflect its functions. These functions include making findings and issuing recommendations based on a wide range of evidence, whether or not that evidence would be admissible in a court of law.

Terminology	Likelihood	Equivalent terms
Virtually certain	> 99% probability of occurrence	Almost certain
Very likely	> 90% probability	Highly likely, very probable
Likely	> 66% probability	Probable
About as likely as not	33% to 66% probability	More or less likely
Unlikely	< 33% probability	Improbable
Very unlikely	< 10% probability	Highly unlikely
Exceptionally unlikely	< 1% probability	



Figure 1: Kawasaki BK117 B-2, ZK-HHJ (Credit: Search and Rescue Services Limited)



Figure 2: Location of accident (Credit: Land Information New Zealand | Toitū Te Whenua)

Contents Rārangi take

1	Executive summary	1
	What happened	1
	Why it happened	1
	What we can learn	1
	Who may benefit	2
2	Factual information	3
	Narrative	3
	Personnel information	5
	Aircraft information	6
	Meteorological information	7
	Weight and balance	7
	Recorded data	8
	Site and wreckage information	8
	Survival aspects	10
	Organisational information	11
	Vortex Ring State (VRS)	11
	Why does Vortex Ring State occur?	13
	Recovery from Vortex Ring State	14
	Settling with power	15
	Previous occurrences	
3	Analysis	17
	Introduction	17
	What happened	17
	Why did the helicopter impact the terrain	19
	Engine or flight-control failures	19
	Pilot Actions	20
	Evidence the helicopter entered Vortex Ring State	21
	How the VRS onset boundary was calculated for the accident flight	21
	The helicopter's flight trajectory	22
	The effect of wind as a contributing factor to VRS	23
	The effect of pitch attitude as a contributing factor to VRS	24
	Conclusion	25

	Vortex Ring State (VRS) awareness	26
	Vortex Ring State alerting systems	27
	Emergency locator transmitter (ELT)	27
4	Findings	.29
5	Safety issues and remedial action	.30
	General	30
6	Recommendations	.31
	General	31
	New recommendations	31
7	Key lessons	.33
8	Data summary	.34
9	Onduct of the inquiry35	
Abb	reviations	.36
Glos	sary	.38
Cita	tions	.39
Арр	endix 1 Wreckage examination	.41
Арр	endix 2 Operator's standard winch circuit	.43
Appendix 3 Predicted VRS onset boundaries for the BK117 B-2 helicopter4		.44

Figures

Figure 1: Kawasaki BK117 B-2, ZK-HHJii
Figure 2: Location of accidentiv
Figure 3: Helicopter flight track
Figure 4: Accident flight4
Figure 5: Accident site
Figure 6: Accident scene
Figure 7: Predicted VRS onset boundaries for various conventional helicopters
Figure 8: Representation of the main rotor wake in forward flight
Figure 9: Structure of the rotor wake in level flight compared with the structure in fully developed VRS
Figure 10: Power versus airspeed for level flight16
Figure 11: The helicopter's flight trajectory18
Figure 12: ZK-HHJ trajectory relative to boundary for VRS onset
Figure 13: ZK-HHJ trajectory, accounting for 20 kt westerly wind and 10° orographic uplift24
Figure 14: ZK-HHJ trajectory accounting for 20 kt westerly wind, 10° orographic uplift and pitch attitude25
Figure 15: broken ELT antenna after the accident sequence

Figure 16: Splayed cross-tube	41
Figure 17: Tail rotor	41
Figure 18: Engine drive shafts	42
Figure 19: Predicted VRS onset boundaries, showing the effect of aircraft mass (a conditions). (Credit: Dr Richard E. Brown, Sophrodyne Aerospace)	t ISA sea level 44
Figure 20: Predicted VRS onset boundaries, showing the effect of air temperature with aircraft mass 3,000 kg).	at 6,000 ft 44

1 Executive summary Tuhinga whakarāpopoto

What happened

- 1.1. On 19 September 2023, an air ambulance helicopter was dispatched from Hamilton Airport to recover a trauma patient on Mount Pirongia.¹ On board the Kawasaki BK117 B-2 helicopter were a pilot, a crew member² and a paramedic.
- 1.2. While descending on the windward side of a ridge line to recover the patient by winch extraction, the helicopter rapidly and unexpectedly dropped in height. The helicopter impacted the terrain on a west-facing escarpment covered by dense native forest.
- 1.3. The helicopter was severely damaged. The pilot, crew member and paramedic escaped without injury.

Why it happened

- 1.4. It is **virtually certain** that the helicopter entered Vortex Ring State (VRS) while descending on the windward side of a ridge line to recover the patient. VRS is a hazardous aerodynamic phenomenon that a helicopter can encounter during the descent and landing phases of flight and during manoeuvres at low forward speed. The onset of VRS can lead to a rapid loss of main rotor lift and then to a sudden increase in the helicopter's rate of descent.
- 1.5. The helicopter's trajectory, particularly its descent rate and forward speed, combined with its pitch attitude and the presence of orographic uplift³ across the ridge, was conducive to the onset of VRS.
- 1.6. While on final approach, the pilot assumed that they could continue the approach to the winch site in level flight. During this critical phase of flight, the pilot's visual attention was primarily focused outside the cockpit on the patient's location. As a result of a reduced instrument scan, indications that the helicopter's forward speed and descent rate were conducive to VRS were not immediately recognised.
- 1.7. The helicopter's height above ground level (AGL) during the onset of VRS provided the pilot with insufficient time to perform an effective recovery.
- 1.8. During helicopter flight training, pilots receive generic tuition on VRS. The helicopter's Flight Manual did not contain the information necessary for the pilot to identify the flight conditions and parameters for the helicopter type that were conducive to VRS.

What we can learn

1.9. The omission of guidance by the helicopter manufacturer on the avoidance and recovery from VRS poses a significant risk to operators.

¹ Mount Pirongia is located in the Waikato region of New Zealand's North Island.

² The crew member was a hoist (winch) operator.

³ The process by which a mass of air is lifted by a geographical feature such as a line of hills or a mountain range

- 1.10. It is critical that helicopter pilots understand what VRS is and how they can avoid entering it.
- 1.11. Flying in mountainous terrain presents helicopter pilots with multiple challenges, including misinterpreting the air environment in which they are flying. Pilots need to use all available sources of information to ensure they are not subject to visual illusions that might lead them to misjudge their forward speed and rate of descent, particularly when operating close to the ground.
- 1.12. Standard operating procedures help ensure that an aircraft is operated and flown in as safe a manner as possible. Modifying these procedures can increase the risk of an adverse outcome.

Who may benefit

1.13. All helicopter pilots, operators, flight schools and manufacturers may benefit from the findings and recommendations in this report.

2 Factual information Pārongo pono

Narrative

- 2.1. ZK-HHJ (the helicopter) was a Kawasaki BK117 B-2 air ambulance helicopter operated by Search and Rescue Services Limited (the operator). On Tuesday 19 September 2023, the day-shift crew (the crew) were on standby from about 0700.⁴ The crew consisted of one pilot, a crew member and a paramedic.
- 2.2. The crew's first assigned job was an inter-hospital transfer from Taumarunui Hospital to Waikato Hospital. The flight departed from Hamilton Airport at 1017, returning at 1312, and was uneventful. The second assigned job was to recover a trauma patient, an injured tramper, from near Te Awamutu.
- 2.3. The helicopter departed Hamilton Airport at 1620 for Te Awamutu. While enroute the pilot entered the patient's global positioning system (GPS) coordinates into the helicopter's GPS, which directed them to Mount Pirongia. While searching, the national Air Desk⁵ provided the crew with the patient's mobile-phone number and coordinates from their Personal Locator Beacon, which assisted in locating the patient.



Figure 3: Helicopter flight track (Credit: Land Information New Zealand | Toitū Te Whenua)

⁴ Times are in New Zealand Standard Time (coordinated universal time +12 hours) and expressed in 24-hour format.

⁵ The national Air Desk is a coordination and tasking function, operated by Hato Hone St John, that provides oversight, dispatch and clinical support functions to air ambulance services.

- 2.4. At about 1645 the crew located the patient and their partner on the Mahaukura Track, situated below and on the southern side of Wharauroa lookout (*see* Figure 4). The crew conducted a reconnaissance of the site and found that there was no suitable place for the helicopter to land near the patient and that a winch extraction would be the most suitable method of recovery.
- 2.5. The pilot then flew the helicopter to a nearby staging area at Pirongia Forest Park Lodge so that the crew could reconfigure the cabin for a winch operation. After the pilot landed and shut down the helicopter, the crew reconfigured the cabin and checked the winch was functional. They then discussed the procedures for recovering the patient by winch extraction.



Figure 4: Accident flight (Credit: Land Information New Zealand | Toitū Te Whenua)

2.6. At 1702 the helicopter departed Pirongia Forest Park Lodge and flew up the valley on the western side of Wharauroa Lookout. After passing abeam Wharauroa Lookout the helicopter entered a 180-degree climbing turn to the left and continued ascending to an altitude of 3000 feet (ft). The pilot continued the left turn before starting a descent onto final approach towards the patient on the windward side of a ridge (*see* Figure 4).

- 2.7. An airspeed under 60 knots (kt) was required to open the rear sliding door safely in preparation for winching. During interviews the pilot recalled that, immediately after responding to the crew member's request to open the door, the helicopter suddenly and unexpectedly dropped in height.
- 2.8. Initially, the pilot tried to arrest the helicopter's descent rate. When the pilot observed the treetops in their peripheral vision, they realised that an impact was imminent and shifted focus from recovering the high rate of descent to controlling the impact to minimise injury.
- 2.9. At 1707, the helicopter descended through the tree canopy and impacted the terrain. It slid forward and down the slope about 1 metre (m), before coming to rest 7 m upslope of a pre-existing landslide.
- 2.10. The crew exited the wreckage uninjured, and the paramedic promptly attended to the patient. The pilot and crew member subsequently assisted the paramedic to prepare the patient for a winch extraction. Between 1802 and 1840 the crew, patient and patient's partner were uplifted and flown to Waikato Hospital by two rescue helicopters.

Personnel information

- 2.11. The pilot held a Commercial Pilot Licence (CPL) for helicopters and a Private Pilot Licence (PPL) for aeroplanes. Before joining the operator in 2006,⁶ they were a Senior Instructor Pilot and a Standardisation Instructor Pilot for the United States Army (US Army).
- 2.12. At the time of the occurrence, they had accrued a total of 7257 flying hours, comprised of 6895.3 hours (h) in helicopters and 361.7 h in aeroplanes. They had flown about 48 h on the BK117 B-2 type of helicopter during the 90 days before the accident. The total flying experience on a BK117 B-2 was about 1928 h. The pilot held a Class 1 medical certificate valid to 20 March 2024 and was required to have half spectacles readily available during flight.
- 2.13. The pilot had completed all the required competency assessments and was current at the time of the accident in accordance with New Zealand Civil Aviation Rules (CARs) and the operator's exposition.⁷
- 2.14. The pilot's competency check for winching was revalidated on 9 February 2023 and current until 15 February 2025. They had conducted recent winch operations on 11 September 2023 and 9 July 2023.
- 2.15. All of the operator's pilots are responsible for managing their fatigue levels by following the operator's Fatigue Risk Management System and Alternative Flight and Duty Scheme. During interviews, the pilot reported having had 12 h free of duty and 9 h sleep before their shift, and advised they were well rested and in good health on the day of the accident.

⁶ The pilot was initially employed by Philips Search and Rescue Trust, before Search and Rescue Services Limited was established in June 2009 through the merger of various helicopter rescue trusts in the central North Island.

⁷ A manual that defines the organisation, identifies the approved senior persons and details the means of compliance with the CARs.

2.16. The operator's procedures required crew to undergo drug and alcohol testing following any incident or accident. This test was carried out at Waikato Hospital about four hours after the accident and all crew returned negative (clear) results.

Aircraft information

- 2.17. The Kawasaki BK117 B-2 helicopter, serial number 1109, registration ZK-HHJ, was constructed in 1996 by Kawasaki Heavy Industries Ltd (KHI), Japan.
- 2.18. The BK117 helicopter was developed through a collaboration between Messerschmitt-Bolkow-Blohm (MBB)⁸ of Germany and KHI. The MBB and KHI BK117 helicopters have separate type certificates⁹ with production lines in separate countries.
- 2.19. The helicopter was fitted with two Honeywell LTS101-850B-2 turboshaft engines in accordance with a Supplemental Type Certificate (STC).¹⁰ The modification improves one-engine-inoperative (OEI) performance and all-engines-operating (AEO) performance at high altitudes and high temperatures.
- 2.20. The helicopter was fitted with a Breeze-Eastern 600-pound (lb) hoist mounted on the right side of the fuselage, the same side as the pilot.
- 2.21. The helicopter had been issued with a New Zealand non-terminating Certificate of Airworthiness in the Standard category on 2 November 2018.
- 2.22. The helicopter's logbooks recorded that the helicopter and engines had been maintained in accordance with the operator's approved maintenance programme.
- 2.23. A review of airworthiness¹¹ had been carried out on 20 December 2022 with no reported defects. The next review of airworthiness was due on 20 December 2023.
- 2.24. Airworthiness directives¹² were checked against the Civil Aviation Authority of New Zealand (CAA) airworthiness directive schedule. No outstanding airworthiness directives applicable to the helicopter were observed.
- 2.25. The helicopter's logbooks showed that all scheduled maintenance had been carried out as required, and the helicopter had no recorded defects at the time of the accident.
- 2.26. The BK117 B-2 helicopter has four main rotor blades made from glass and carbonfibre reinforced plastics. Each main rotor blade is affixed to the main rotor head by both a primary and a secondary bolt. The rotor system is hingeless; the flexibility of the main rotor blades rather than mechanical hinges is used to accommodate their flapping¹³ and lead-lag¹⁴ motions.

⁸ Now part of Airbus Group

⁹ A Type Certificate is issued by a Regulatory Authority and signifies the airworthiness of a particular category of aircraft, according to its manufacturing design.

 ¹⁰ A Supplemental Type Certificate (STC) is a Type Certificate issued when an applicant has received approval to modify an aeronautical product from its original design. The STC approves not only the modification but also how that modification affects the original design.

¹¹ A formal and periodic review of an aircraft and its records that is required for the aircraft to remain airworthy

¹² A mandatory airworthiness requirement that specifies modifications, inspections, conditions or limitations to be applied to an aircraft or aeronautical product to ensure continued safe operating conditions

¹³ Movement of a blade in the vertical sense relative to the plane of rotation.

¹⁴ Movement of a blade forward or aft, in the plane of rotation

- 2.27. To boost the manual control inputs by the pilot, a dual hydraulic system is located on top of the cabin roof in front of the main transmission. For redundancy, the hydraulic unit consists of two separate systems that operate independently of each other. System one is used for normal operation and system two is the standby system. The two systems are linked so that in the event of a pressure drop or a control jam in system one, a changeover to system two occurs automatically and a caution light on the annunciator panel illuminates.
- 2.28. An advisory, caution and warning annunciator panel is located below the instrument panel to alert the pilot to a system condition or failure. Whenever a yellow caution or red warning light illuminates on the annunciator panel, the master warning lights illuminate on both the upper left and right sides of the instrument panel. The purpose of this design is to capture the pilot's attention and to indicate that a light on the annunciator panel, an aural warning will alert pilots to an engine failure or to low rotor RPM.

Meteorological information

- 2.29. The Commission obtained a detailed analysis from Meteorological Service of New Zealand Ltd (MetService) of weather observations recorded on the day of the accident. The analysis showed there was no significant change in the weather conditions from the time the pilot conducted the site reconnaissance until the time of the accident.
- 2.30. MetService concluded:

At the time a high lay over northern New Zealand, bringing settled weather and westerly winds. The weather was fine enroute. However, there was cloud "cascading" over the summit of Mount Pirongia from the west, and then rapidly evaporating and clearing. The accident site was likely cloud free, with west to north westerly winds of around 20 kt and gusts to 30 kt possible. On the windward side of the immediate ridgeline, this wind flow would have resulted in orographic upslope winds and light turbulence.

- 2.31. The patient advised Commission investigators that, around the time of the accident, the wind speed was variable from a westerly direction. They had observed extremely strong gusts at times. Throughout the day, there was a mixture of high cloud and clear sky. During the winch recovery, wisps of cloud were observed between Wharauroa and Mahaukura.
- 2.32. Two rescue helicopters¹⁵ arrived at the site about an hour after the accident. The pilots of the two helicopters advised Commission investigators that the wind was strong westerly at about 20–30 kt, as recognised by the movement of trees, dust and clouds. One of the pilots said the wind speed and direction displayed on their helicopter's Primary Flight Display (PFD) coincided with this observation. They also said that there was some cloud on the ridge line around the peak of Mount Pirongia.

Weight and balance

2.33. When the crew reconfigured the helicopter cabin for winching operations, they were required to offload unneeded equipment to reduce the operational weight of the

¹⁵ MBB BK117 B-2 and Leonardo AW169.

helicopter. The pilot calculated a load manifest before departing Hamilton Airport and again at the staging area at Pirongia Forest Park Lodge.

- 2.34. The helicopter had a maximum certificated gross weight of 3350 kg and a minimum gross weight for flight of 1700 kg. CAR 133.71 states that a pilot performing an operation involving the suspension of a person beneath a helicopter must ensure that the helicopter is not operated at a weight in excess of 90% of its out of ground effect (OGE)¹⁶ hover weight. According to the hover OGE graph in the helicopter's Flight Manual, the helicopter's calculated maximum hover OGE weight at the patient's location was 3350 kg. In accordance with CAR 133.71 the helicopter's maximum permitted weight was therefore 3015 kg.
- 2.35. Using the weights from the load manifest, the pilot calculated the helicopter to have weighed 2976.8 kg before departing from Pirongia Forest Park Lodge. This was 373.2 kg less than the maximum certified weight and 38.2 kg less than the calculated maximum hover OGE weight.
- 2.36. The helicopter's longitudinal and lateral centre of gravity positions and the maximum permitted weight were calculated to be within limits for the flight.

Recorded data

- 2.37. The helicopter was not fitted with a voice or video recorder. These were not required by CARs.
- 2.38. The helicopter was fitted with a Flightcell DZMx,¹⁷ located in view of the pilot. The DZMx recorded a range of flight data, including GPS position, aircraft pitch attitude, g-force and jerk (rate of change of g-force) once every second. The recorded data was extracted by Flightcell under supervision by Commission investigators, allowing the helicopter's flight trajectory to be analysed. Flightcell reconstructed an animation of the helicopter's flight path, which assisted the investigation.

Site and wreckage information

- 2.39. The accident site was on Mount Pirongia on a west-facing escarpment covered by dense native forest, about 108 m southwest of Wharauroa Lookout (*see* Figure 5). The helicopter was sitting upright, wedged between trees below a ridge line (*see* Figure 6).
- 2.40. Damage to trees at the site indicated that the helicopter had fallen almost vertically through the tree canopy. All the wreckage was contained within a 15 m radius of the main fuselage.
- 2.41. The forward and aft cross-tubes of the landing-gear assembly had splayed outwards, causing the right side of the assembly to fracture in overload near the fuselage attachment fittings (*see* Figure 16 in Appendix 1).

¹⁶ A helicopter is said to be OGE when the rotor downwash is no longer affected by the surface under it and more power is required to hover. This change occurs gradually at a height equivalent to about one rotor disc diameter.

¹⁷ The Flightcell DZMx is a voice, data and tracking system designed and manufactured in New Zealand.



Figure 5: Accident site

- 2.42. The markings on the trees surrounding the helicopter, and the damage to its main rotor blades, was characteristic of an impact with the blades having had high rotational energy. The outboard section of each main rotor blade was severely strike damaged. The main rotor blades had fractured outboard from the primary and secondary attachment bolts. One of the four main rotor blades had separated from the rotor head during the accident and was found lying next to the wreckage.
- 2.43. Both tail rotor blades exhibited strike damage, but both were still attached to their mounting fork (*see* Figure 17 in Appendix 1).
- 2.44. The engine drive shafts of both engines had exhibited torsional¹⁸ failure (*see* Figure 18 in Appendix 1). This is consistent with the engines having continued to drive the main rotor transmission under resistance as the main rotor blades struck the surrounding trees.
- 2.45. The helicopter was equipped with an Artex C406-1 Emergency Locator Transmitter (ELT).¹⁹ The Rescue Coordination Centre New Zealand (RCCNZ) did not receive a notification from the ELT.

¹⁸ Twisting of the shaft caused by an applied force

¹⁹ An ELT transmits a distress signal to the Cospas-Sarsat search and rescue satellite system.



Figure 6: Accident scene

Survival aspects

- 2.46. Injuries sustained in aircraft accidents arise from three distinct sources:
 - excessive impact forces
 - trauma from contact with injurious surfaces
 - exposure to environmental factors such as fire or smoke.
- 2.47. The maximum impact force recorded during the accident sequence was 3.2 *g*. All three crew survived the accident without any injuries. This was attributed to the following factors:
 - Statistical trends indicate that the absence of a post-impact fire is a critical factor in crash survivability. The helicopter's fuel is stored in underfloor compartments using bladder-type fuel cells, which are designed to reduce the likelihood of a fuel leak in the event of an accident. The helicopter's fuel cells withstood the impact and prevented post-impact fuel leakage, and therefore fire.
 - Federal Aviation Administration (FAA), Title 14 Code of Federal Regulations (CFR) Part 29²⁰, prescribes airworthiness standards for the issue of type certificates, and the changes required to those certificates for the rotorcraft to be certificated as a transport category rotorcraft. At the time of design, the BK117 structure was designed to withstand higher loads than those specified by Title 14 CFR Part 29. The energy-absorbing structure of the helicopter's cabin maintained sufficient strength during the accident to prevent structural collapse and/or penetration of

²⁰ United States of America Title 14 CFR Part 29 Airworthiness Standards: Transport Category Rotorcraft

the main rotor transmission and engines into the occupied spaces inside the cabin.

- Research on helicopter accidents indicates that, in most survivable accidents, the primary crash force is vertically downwards. The helicopter had fallen through the tree canopy almost vertically and its landing gear assembly impacted the terrain, causing the cross tubes to splay outwards, as intended, to cushion the impact.
- 2.48. When the pilot realised that impact was imminent, they shifted focus from recovering from VRS to controlling the impact to minimise injury. They oriented the helicopter so that the crash force would be directed as vertically as possible through the helicopter's structure, notwithstanding the steep slope of the terrain at the accident site.

Organisational information

- 2.49. Search and Rescue Services Limited is the provider and operator of air ambulance operations in the Central North Island, New Zealand. Under its contract with National Ambulance Sector Office (NASO),²¹ helicopter crews respond to requests for emergency pre-hospital treatment and transportation of acutely unwell patients. Dispatch to these missions is authorised and coordinated by the national Air Desk.
- 2.50. Search and Rescue Services Limited also provides:
 - inter-hospital transfers (the transportation and clinical care of patients between hospitals), a process coordinated by Health New Zealand | Te Whatu Ora (HNZ) in collaboration with the respective hospitals
 - search and rescue services in collaboration with New Zealand Police and RCCNZ.

Vortex Ring State (VRS)

- 2.51. VRS is a hazardous aerodynamic phenomenon that a helicopter can encounter when in steep descending flight at low forward speed and during manoeuvres at low forward speed. The onset of the VRS can lead to a rapid loss of lift and subsequently to a sudden increase in the helicopter's rate of descent. If not detected, the helicopter can rapidly enter an unstable condition characterised by thrust fluctuations, decreased control authority and a significant increase in its rate of descent.
- 2.52. The existence of VRS is universal to all rotor designs. The major characteristics of VRS are determined principally by the disc loading of the rotor.²² The detailed design of the rotor, such as the twist of its blades and blade-tip shape, have a secondary influence on the characteristics of VRS.

²¹ NASO is an office, jointly-appointed by Health New Zealand | Te Whatu Ora (HNZ) and Accident Compensation Corporation (ACC), that provides the strategic overview, monitoring and contracting of the Emergency Ambulance Service for HNZ and ACC.

²² Defined as the helicopter's weight divided by the total area of its lifting rotors

2.53. The VRS domain extent for several well-known conventional helicopters is compared in Figure 7. The coloured line indicates the VRS onset boundary for each specific helicopter, as defined by its vertical and forward speeds. So, for instance, the BK117 helicopter will encounter VRS if its trajectory takes it into the region of the diagram that is shaded in red. Using similar logic, the large, heavy CH-53E military transport helicopter might experience VRS at descent rates between 1350 and 6000 ft/min, when flying at a speed less than 34 kt; a small helicopter, such as the Robinson R22, would only encounter VRS at descent rates between 700 and 3100 ft/min, when flying at speeds less than 17 kt.



Figure 7: Predicted VRS onset boundaries for various conventional helicopters (Credit: Dr Richard E. Brown, Sophrodyne Aerospace)

Why does Vortex Ring State occur?

2.54. In normal flight, a helicopter's main rotor creates a long, cylindrical wake that streams down into the flow below and behind the main rotor (*see* Figure 8). The wake from a helicopter's main rotor is inherently unstable. This instability causes the orderly structure of the wake eventually to break down into a highly turbulent, chaotic flow. In normal flight this breakdown occurs below and behind the helicopter and has very little influence on the aerodynamics of the main rotor itself.



Figure 8: Representation of the main rotor wake in forward flight

(Credit: Dr Richard E. Brown, Sophrodyne Aerospace)

- 2.55. A physical representation of the main rotor wake with the helicopter in forward flight is demonstrated in Figure 8. The image shows how the wake near the main rotor initially has an ordered cylindrical shape and how, further away from the helicopter, the wake becomes increasingly more disordered as its inherent instability starts to take hold. The figure at the bottom shows an idealisation of this process.
- 2.56. Within a range of descent rates and forward air speeds, the instability of the wake is able to catch up with the main rotor, causing the wake to collapse into a toroidal form, known as VRS. The onset of VRS is responsible for a sudden decline in the lift generated by the rotor. In practice this usually causes the helicopter to descend rapidly unless appropriate action is taken to recover the helicopter into normal flight.
- 2.57. A comparison of a helicopter's main rotor wake structure in level flight at a speed of 12 kt is demonstrated in Figure 9. The middle image shows the structure of the wake

just before VRS onset. The disturbances in the main rotor wake have practically caught up with the main rotor. The bottom image shows the helicopter relatively deep within VRS. The wake has transitioned into the toroidal recirculatory form that is associated with VRS.



Figure 9: Structure of the rotor wake in level flight compared with the structure in fully developed VRS

(Credit: Dr Richard E Brown, Sophrodyne Aerospace)

Recovery from Vortex Ring State

2.58. The onset of VRS is responsible for a sudden decline in the lift generated by the main rotor and usually causes the helicopter to descend rapidly unless action is taken to recover the helicopter.

- 2.59. A pilot's intuitive response to the sudden and unexpected increase in descent rate that accompanies VRS onset is usually to increase collective²³. However, this usually energises the toroidal form associated with VRS and ends up exacerbating the rate of descent. Hence the pilot's conscious action is required to suppress their natural response and to apply a proper technique to recover from VRS.
- 2.60. The two most common recovery techniques that pilots are currently taught are the 'traditional' technique and the Vuichard recovery technique. The FAA's *Helicopter flying handbook* (Federal Aviation Administration, 2019) details both these methods of VRS recovery:

The traditional recovery is accomplished by increasing airspeed, and/or partially lowering collective to exit the vortex.

In most helicopters, lateral cyclic thrust combined with an increase in power and lateral antitorque thrust will produce the quickest exit from the hazard. This technique, known as the Vuichard recovery (named after the Swiss examiner from the Federal Office of Civil Aviation who developed it) recovers by eliminating the descent rate as opposed to exiting the vortex.

Settling with power

- 2.61. Because of inconsistent terminology in aviation literature (Federal Aviation Administration, 2019) (Wagtendonk, 2006), pilots can confuse VRS with other phenomena such as 'settling with power' or 'power settling'. These phenomena can all be encountered in low-speed flight and the terms have historically been used interchangeably. However, the origins of 'settling with power or 'power settling' are different from those that precipitate the VRS.
- 2.62. The power required to sustain level flight increases as the forward speed of the helicopter is reduced below the minimum power setting for level flight (*see* Figure 10). If the engine(s) cannot provide the necessary power, then the helicopter will begin to descend or settle. This is not VRS but rather a condition where the engine(s) have reached their maximum available power limit. The power required exceeds the power available.
- 2.63. In certain circumstances, if the airspeed is slow enough, the descent rate can build up to the point at which VRS is eventually encountered in its aerodynamic form (*see* paragraphs 2.55 to 2.57).

²³ One of the flight controls used by a helicopter pilot to 'collectively' adjust the pitch angle of all main rotor blades at the same time to alter the amount of thrust/lift being produced.



Figure 10: Power versus airspeed for level flight

Previous occurrences

2.64. According to the National Transportation Safety Board (NTSB) report database, from 2008 to 2021, 48 helicopter accidents in the United States of America involved VRS encounters. The data collected only represents reported accidents and does not include VRS encounters where the pilots performed a successful recovery manoeuvre and avoided damage to the helicopter or injury to the crew. Therefore, the incidence of VRS is at a higher level than these numbers indicate.

3 Analysis Tātaritanga

Introduction

- 3.1. The national Air Desk dispatched the helicopter from Hamilton Airport to retrieve a trauma patient at Mount Pirongia. Upon locating the patient, the crew devised a retrieval plan and flew to a nearby staging area to reconfigure the helicopter for winching. The retrieval plan required the pilot to manoeuvre the helicopter into a position from which the patient could be winched up. During the final approach the helicopter rapidly and unexpectedly dropped in height, resulting in the helicopter impacting the terrain.
- 3.2. The helicopter's trajectory and pitch attitude, combined with the orographic uplift conditions on the windward side of the ridge that the helicopter was flying along, increased the risk of the helicopter entering VRS. Despite the hazard it poses to flight safety, VRS generally remains a poorly understood aerodynamic phenomenon that can be encountered during the descent and landing phases of flight, and during manoeuvres at low forward airspeeds.
- 3.3. Current helicopter certification standards do not require manufacturers to determine the range of flight conditions and operational parameters above which a helicopter might be susceptible to VRS. In the absence of this information, and particularly if it has not been incorporated into the applicable rotorcraft flight manual, pilots are less likely to be able to accurately determine the range of flight conditions in which a helicopter might be susceptible to VRS.
- 3.4. The following section analyses the circumstances surrounding the event to identify those factors that increased the likelihood of the event occurring or increased the severity of its outcome. It also examines any safety issues that have the potential to adversely affect future operations.

What happened

- 3.5. The objective of the rescue mission was to recover a trauma patient located on the Mahaukura Track on Mount Pirongia.
- 3.6. When the helicopter arrived at the patient's location, the pilot conducted a site reconnaissance and concluded that the wind was from a westerly direction, but the speed was negligible. There were sufficient power margins for the helicopter's safe operation during winching. The pilot then flew the helicopter to Mount Pirongia Forest Park Lodge and the crew reconfigured the cabin for a winch operation.
- 3.7. The pilot intended to conduct the recovery by ascending to the patient's altitude, decelerating on final approach and then positioning the helicopter about 100 ft above the patient. The crew member would then guide the pilot to the appropriate position for a winch extraction.
- 3.8. After the helicopter departed the Lodge, the pilot flew it up the valley on the western side of Wharauroa Lookout. The pilot was located in the front right seat, a paramedic in the left rear-facing seat of the rear cabin, and a crew member on the floor of the rear cabin beside the right sliding door. The crew member was restrained by a harness

and lanyard connected to the helicopter. The crew described the wind conditions as non-turbulent as the helicopter proceeded up the valley.

- 3.9. After passing abeam Wharauroa Lookout, the helicopter entered a 180 -degree climbing turn to the left and continued ascending to an altitude of 3000 ft. The patient was located below and on the southern side of Wharauroa Lookout at an altitude of 2640 ft. This required the helicopter to descend about 260 ft to position itself 100 ft overhead the patient. Despite some cloud around the summit of Mount Pirongia, the patient's location remained clear and the pilot continued the left turn before starting a descent onto final approach on the windward side of the ridge leading up to the Lookout.
- 3.10. The helicopter's speed progressively decreased during its final approach, as depicted in Figure 11, which illustrates the helicopters trajectory. At 17:06:51 the helicopter's pitch angle reached a maximum of 19.5° (nose up). This in turn reduced the helicopter's speed and increased its rate of descent.



Figure 11: The helicopter's flight trajectory

- 3.11. A maximum airspeed of 60 kt was required to open the sliding door safely in preparation for winching. During interview, the crew member recalled asking the pilot if the speed was okay to open the door. The pilot replied "we are a little too hot"²⁴ but was unable to complete their response to the crew member before the helicopter rapidly and unexpectedly dropped in height.
- 3.12. The flight data downloaded from the Flightcell DZMx shows the sudden drop in height occurred at 17:06:55, when the helicopter was at about 291 ft AGL. At this time

²⁴ See paragraph 3.20 for an explanation.

the helicopter had a descent rate of 649 ft/min and a groundspeed of 25.8 kt. The helicopter's pitch attitude was 13° (nose up) on a heading of 25° true.

- 3.13. During interview, the pilot recalled that the cyclic²⁵ and collective controls lacked responsiveness during the rapid descent. They suspected VRS and attempted to recover and arrest the high rate of descent of the helicopter by initially applying the traditional recovery technique. Upon realising that there was insufficient height available, the pilot immediately attempted a second technique, called the Vuichard recovery technique.
- 3.14. The wind by this stage was 20 kt and gusting 30 kt from a westerly direction, resulting in a crosswind from the helicopter's left rear quarter. At 17:06:59 the helicopter's heading changed relative to the wind direction, to where the wind acted from behind (tailwind). The helicopter increasingly veered to the right and proceeded to pitch nose-down. The helicopter reached a maximum descent rate of 2145 ft/min with a forward groundspeed of 9 kt.
- 3.15. Realising that impact with the terrain was imminent, the pilot focused on controlling the descent through the tree canopy to minimise the potential forces on impact. The pilot pitched the helicopter nose-down to prevent the tail from contacting the trees first, thus averting a potential slew of the helicopter. The helicopter continued turning right. The pilot was able to manoeuvre the helicopter between the trees before descending through the tree canopy.
- 3.16. At 1707, the helicopter impacted the terrain and slid down a slope about a metre, before coming to rest, seven metres upslope of a pre-existing landslide.

Why did the helicopter impact the terrain

Engine or flight-control failures

- 3.17. Based on the following evidence it was **exceptionally unlikely** that an engine or flight-control failure caused the helicopter to impact the terrain.
 - the drive shafts of both engines had twisted and separated, consistent with the engines having continued to drive the main rotor transmission under resistance as the main rotor blades struck the surrounding trees.
 - the trees surrounding the helicopter were damaged by the main rotor blades and the severity of the damage was characteristic of an impact with the main rotor blades still having high rotational energy.
 - the pilot said in interview that the helicopter was performing perfectly, that there were no aural warnings or warning lights and that they had to shut the engines down after impact.
 - post-accident inspection showed that the helicopter's primary flight controls had retained continuity and had been assisted by hydraulics up to the point of impact.

²⁵ The control which changes the pitch angle of the rotor blades individually during a cycle of revolution and as a result tilts the main rotor disc to control the direction and velocity of flight

Pilot actions

- 3.18. New Zealand CARs require each holder of an Air Operator's Certificate to establish an operational competency assessment programme for flight crew and crew members, to ensure that they are trained and competent to perform their assigned duties. During interview the operator's training manager explained how VRS was integrated into the operator's training syllabus, with emphasis on recognition and avoidance. Both the Vuichard and traditional recovery techniques were included; however, demonstrations of actual in-flight recovery from VRS were not practised following the publication of Airbus Helicopter's Safety Information Notice No 3463-S-00 (Airbus, 2022). This notice recommends that operators do not intentionally place the helicopter in fully developed VRS because of the aerodynamic loads imposed on the helicopter.
- 3.19. The operator's Standard Operating Procedures (SOP) provided detailed procedures, guidelines and allocation of responsibilities amongst the crew during various phases of flight operations. The SOP outlined that winching procedures were not rigid rules nor the only way to accomplish a task, because of the inherent risks and dynamic environment associated with winching. The SOPs also incorporated crew resource management (CRM) principles to assist the crew in forming a shared mental model of their situation and environment. Although the operator's SOP for a standard winch circuit (*see* Appendix 2) was appropriate for most situations, the operator allowed the crew to exercise their professional judgement in choosing and modifying the appropriate winching tasks to the prevailing circumstances and conditions.
- 3.20. The pilot's response to the crew member's request to open the sliding door was that "we are a little too hot". As airspeed is the only restriction to opening the door, the crew member interpreted the pilot's response to mean the speed was above 60 kt during this time. The pilot's last remembered instrument scan occurred during the left base turn onto final approach, noting the airspeed at this time to be around 50 kt. Reviewing the data from the Flightcell DZMx shows that the helicopter's groundspeed during the left base turn was around 55 kt. The helicopter continued to decelerate while on final approach (*see* Figure 11).
- 3.21. During interview, the pilot explained that they wanted to keep the door closed because they did not like having the door open when the helicopter was not in level flight. Their intention was to complete the base turn and to reduce speed before the door was opened, thus avoiding any potential blast of wind entering the cabin as the helicopter approached the winch position.
- 3.22. During the winch circuit the paramedic and crew member were attempting to resolve an issue with the handheld radio, which diverted their attention from preparing the cabin, and providing commentary to the pilot on the patient's position. Following the start of the turn, the pilot was unable to establish the stable approach profile as recommended in the operator's SOP, nor were all the pre-winch tasks completed with 100 m still to run to the patient's location. During this critical phase of flight, the pilot was under the assumption the helicopter was at the same altitude as the patient and that a descent before reaching the patient would not be required. At this time, the pilot's visual attention was primarily focused outside of the cockpit on the patient's location. As a result of a reduced instrument scan, indications that the helicopter was entering conditions conducive to VRS were not immediately recognised.

- 3.23. The pilot said during interview that they used a 'rule of thumb' to avoid VRS, based on speed, descent rates and engine power, that they had learnt in the US Army. This rule of thumb made no allowance for the type of helicopter that they were flying, nor for the actual disc loading of the rotor. Furthermore, there was no consideration of the effect of orographic winds nor for how the helicopter's pitch attitude might have been conducive to earlier-than-anticipated VRS onset.
- 3.24. Flight manoeuvres that are known to precipitate VRS are often performed at relatively low altitudes and are associated with descents and landings (Sotiropoulos-Georgiopoulos, et al., 2023). The timely identification of the symptoms of incipient VRS is critical to recovery. The pilot initially tried to arrest the descent rate of the helicopter by applying the traditional recovery technique that they had taught and demonstrated during their time in the US Army. When this did not resolve the situation, they tried the Vuichard recovery technique. The height above terrain at VRS onset was 291 ft AGL, which suggests the pilot had very little height or time to successfully execute either recovery technique.
- 3.25. Although training in VRS recovery is essential, it should not be a substitute for training pilots to identify the conditions that can lead to premature entry into VRS. In New Zealand, the CAA has published information and guidance (Civil Aviation Authority of New Zealand, 2016, 2018 and 2020) to raise awareness of VRS and has conducted workshops on VRS recovery. The Commission considers that better education regarding the factors that can induce VRS would equip pilots with the ability to better detect and avoid the onset of VRS as identified in this investigation.

Evidence the helicopter entered Vortex Ring State

3.26. The size and extent of the region of the flight envelope²⁶ in which a helicopter can encounter VRS is determined principally by the disc loading of the rotor, as well as by the local atmospheric conditions. A helicopter will encounter VRS if its trajectory takes it into this region. The helicopter's flightpath before the accident was conducive to VRS. Orographic uplift across the ridge along which the helicopter was flying and the helicopter's pitch attitude during its deceleration both contributed to the early onset of VRS. This section describes the methodology that was used to calculate the speed and descent rate required for the helicopter to enter VRS. The analysis shows how important the helicopter's pitch attitude and the effects of the wind were, especially when descending adjacent to the ridge line, in creating a set of flight conditions in which the aircraft would have been particularly susceptible to VRS.

How the VRS onset boundary was calculated for the accident flight

3.27. The location of the VRS onset boundary on the flight envelope (*see* Figure 12) was calculated using a mathematical model that recognises the inherent instability of the rotor wake as fundamentally responsible for the onset of VRS. The region of the flight envelope in which this model predicts VRS might be encountered correlates well

²⁶ The flight envelope in aviation is defined by various parameters and refers to the limits within which an aircraft can operate safely and efficiently. A flight envelope encompasses both normal and extreme flight conditions and is typically represented graphically.

against a wide range of flight tests and laboratory data for various types of rotorcraft. $^{\rm 27}$

- 3.28. Aerospace engineer Dr Richard E. Brown²⁸ from Sophrodyne Aerospace provided expert advice in locating the VRS onset boundary on the flight envelope for the accident flight.
- 3.29. The sources that were used to yield values for the parameters that define the location of the VRS onset boundary on the flight envelope for the accident flight are listed in Table 1.

Data	Sources
Elevation	Land Information New Zealand
Air density	MetService
Wind speed and direction	MetService
	witnesses
Pitch data	Kawasaki BK117 Maintenance Manual,
	Chapter 01 Dimensions and areas
Flight data:	Flightcell DZMx
• time	
trajectory	
location	
• speed	
 helicopter's rate of descent 	
altitude	
orientation	
Disc loading	• Kawasaki BK117 Maintenance Manual,
	Chapter 01 Dimensions and areas
	the helicopter's calculated load manifest
	at the staging area

Table 1: Values used to locate the VRS onset boundary

The helicopter's flight trajectory

3.30. Figure 12 shows the location of the boundary for VRS onset on the flight envelope, as defined by mapping the location of flight conditions at which the disturbances to the wake structure are able to reach the main rotor. If the axes in this figure are interpreted as the speeds of the helicopter relative to the ground, then the figure suggests that a BK117 B-2 helicopter with the weight and geometric characteristics of the accident helicopter, when flying at the altitude of the accident site, would have encountered VRS when flying at descent rates between 1050 and 4750 ft/min if flying horizontally at speeds less than 27 kt (groundspeed). The black line shows the

²⁷ (Ahlin, G.A & Brown, R.E., 2004. Predicting the Onset of the Vortex Ring State under Accelerated Flight Conditions) and (Newman, et al, 2003. Predicting the Onset of Wake Breakdown for Rotors in Descending Flight, Journal of the American Helicopter Society, Volume 48)

²⁸ Dr Richard E. Brown is an experienced aerospace engineer, with a 30-year record in modelling and understanding aircraft and helicopter aerodynamics, aerospace education, and air vehicle analysis and design. Dr Brown has published over 100 technical papers in the field of modelling and simulation of aircraft systems and is a recipient of both the Royal Aeronautical Society's bronze medal for contributions to understanding rotorcraft aerodynamics, and the Vertical Flight Society's award for extraordinary work in vertical flight. Dr Brown is the originator of our modern conception of how VRS develops on helicopter rotors and is actively involved in extending our understanding of the phenomenon in order to improve the safety of rotorcraft operations.

horizontal speed and descent rate of the accident helicopter at various points along its final trajectory, as measured relative to the ground. According to the diagram, the helicopter will have entered VRS at 17:06:59 by crossing the onset boundary with a descent rate of 1050 ft/min and a groundspeed of 18 kt.



Figure 12: ZK-HHJ trajectory relative to boundary for VRS onset

The effect of wind as a contributing factor to VRS

- 3.31. The analysis up to now shows the helicopter's trajectory in terms of groundspeed or, equivalently, airspeed in the absence of any wind. This section adds the effects of the wind in determining the helicopter's trajectory relative to the VRS onset boundary for the helicopter.
- 3.32. An analysis of the wind conditions at the time of the accident concluded that the wind speed was 20 kt, with gusts to 30 kt, from a westerly direction. The topography would have induced an upward component of wind flow relative to the helicopter's trajectory, known as orographic uplift. This upwards component of the wind would have appeared to the rotor as an increase in its effective descent rate. The blue trajectory (*see* Figure 13) depicts the helicopter's velocity, represented as a horizontal airspeed and descent rate, factoring in the influence of wind. This figure shows that, on accounting for the effect of the wind, the helicopter would have encountered VRS at 17:06:57, two seconds earlier than if the effects of the wind were not accounted for. By referring back to the trajectory shown in Figure 12 it can be inferred that the helicopter would have entered VRS at a substantially lower descent rate and higher forward speed (728 ft/min with a groundspeed of 20 kt) compared with the effects of the wind being omitted from the analysis.



Figure 13: ZK-HHJ trajectory, accounting for 20 kt westerly wind and 10° orographic uplift

3.33. An important factor was the change in the helicopter's heading around 17:06:59, causing a shift in the wind to blow from behind the helicopter (tail wind), effectively reducing the helicopter's airspeed. This shift in the relative wind contributed to the helicopter penetrating more deeply into VRS than if the heading of the helicopter had remained unchanged. As a result, the pilot would have experienced significantly exacerbated symptoms of VRS, as well as potentially greater difficulty in recovering to normal flight.

The effect of pitch attitude as a contributing factor to VRS

- 3.34. The analysis can be refined further by accounting for changes in the pitch attitude of the helicopter along the flight trajectory. The precise location on the flight envelope of the boundary for VRS onset is defined by the velocity components relative to the rotor rather than the velocity components relative to the ground or to the helicopter. The helicopter's nose-up flare while descending towards the patient increased the upwards component of air velocity through the rotor, increasing its effective descent rate and bringing the helicopter closer to the onset of VRS.
- 3.35. In Figure 14, the green trajectory denotes the airspeed and descent rate as measured relative to the helicopter's rotor, accounting for the changes in pitch attitude of the helicopter, while descending along the ridge line. The effective inclination of the rotor to the airflow was calculated by subtracting the helicopter's mast inclination angle (5°) from the helicopter's pitch attitude, as recorded by the Flightcell DZMx.



Figure 14: ZK-HHJ trajectory accounting for 20 kt westerly wind, 10° orographic uplift and pitch attitude

3.36. At 17:06:51 the helicopter's pitch attitude reached a maximum of 19.5°. The analysis presented in Figure 14 then shows that the helicopter would have crossed the VRS onset boundary sometime between 17:06:55 and 17:06:56, 3.5–4 seconds earlier than if the pitch attitude and wind were ignored in the analysis. Referring back to the speeds relative to the ground (the black trajectory in Figure 12), the helicopter would have entered VRS at a descent rate of 649 ft/min with a groundspeed of 25.8 kt.

Conclusion

- 3.37. It is **virtually certain** that the helicopter entered VRS while descending on the windward side of the ridgeline to recover the patient. The helicopter's trajectory led it into that part of the flight envelope where its combination of forward speed and descent rate precipitated the onset of VRS. After accounting for the orographic uplift over the ridge along which the helicopter was flying, as well as the helicopter's pitch attitude, VRS onset would have occurred while flying at a descent rate of 649 ft/min with a forward speed relative to the ground of 25.8 kt.
- 3.38. The analysis was able to establish the flight conditions for VRS onset, but recovery from VRS back into normal flight conditions is governed by different physical mechanisms and cannot be reliably predicted using the methodology presented here. To escape from VRS, the pilot is required to suppress those mechanisms that feed the recirculatory flow around the rotor and to re-establish the rotor wake in its normal operating state. Several piloting techniques, including the 'traditional' recovery and the more recent 'Vuichard' recovery technique, require the pilot to be aware of the early symptoms of VRS onset and to be trained in the application of the techniques.

Vortex Ring State (VRS) awareness

Safety issue: The helicopter's Flight Manual did not include sufficient guidance for pilots to recognise and avoid the onset of VRS. This increased the risk of pilots inadvertently entering conditions conducive to VRS.

- 3.39. VRS has been recognised as a hazard to the safe operation of a helicopter by aerodynamicists and helicopter designers since the early days of helicopter flight. Since then, ongoing research, supported by simulation and flight testing, has continued to refine the helicopter industry's understanding of where and how VRS can be encountered during flight.
- 3.40. Flight manoeuvres that are known to precipitate VRS are predominantly those associated with the descent and landing phases of flight and thus are often performed at relatively low height AGL. Recognising and avoiding the combination of flight conditions that is conducive to VRS is essential for preventing the helicopter from entering VRS.
- 3.41. The Commission found that the helicopter's Flight Manual did not contain the necessary guidance for the pilot to identify the potential for VRS onset.
- 3.42. The primary purpose of rotorcraft flight manuals is to provide an authoritative source of the information that is considered necessary for safe operation of the rotorcraft. To fulfil their intended function, rotorcraft flight manuals provide mandatory approved information (data) such as limitations, performance information, and a summary of the procedures that should be followed to enable the flight crew to operate the helicopter safely. Additionally, the manufacturer or operator may include additional data in separate and distinct sections of the rotorcraft flight manual. The major characteristics of VRS are determined principally by the disc loading of the rotor and are therefore specific to each helicopter model. Despite this, current certification does not require the manufacturer to include any information in the rotorcraft flight manual regarding the flight conditions and parameters that are conducive to VRS. Pilots would be better prepared to identify and manage the risk of VRS if this information was required as part of the certification process for all helicopters.
- 3.43. Operating in fully developed VRS can significantly increase the dynamic loading on the helicopter's main rotor system. VRS is not often considered when determining the service life of components, although some manufactures recommend not placing the helicopter in fully developed VRS during training to avoid undue stresses being placed on the main rotor system. Kawasaki Heavy Industries do not provide guidance on this in the BK117 B-2 Flight Manual.
- 3.44. A review of the Kawasaki BK117 B-2 Flight Manual by Commission investigators determined that it did not prescribe a recommended maximum descent rate for the helicopter in the 'normal procedures' section. However, a recommended maximum descent rate is provided in the 'normal procedures' section of the flight manuals of other related helicopter models such as the MBB BK117 B-2 and Kawasaki BK117 C-2.
- 3.45. A review of various rotorcraft flight manuals, including that for the Kawasaki BK117 B-2, failed to reveal any information that would help the pilot to determine accurately the range of descent rates and forward speeds over which VRS might be encountered, for instance through the provision of graphs showing the location of the boundary for VRS onset on the aircraft's flight envelope.

- 3.46. In the absence of this information, pilots commonly rely on rules of thumb to avoid VRS. Having to rely on ad-hoc procedures to avoid VRS is no substitute for having properly constructed graphs to hand that represent the location of the VRS onset boundary on the flight envelope as a function of the helicopter's weight and the temperature-corrected altitude (*see* examples in Appendix 3, Figures 19 and 20). This lack of essential information increases the risk of pilots inadvertently entering VRS during routine flight operations.
- 3.47. The absence of VRS information in the helicopter's Flight Manual did not directly contribute to this accident. However, when this information is not available to a pilot, they are limited in their ability to anticipate and avoid VRS-conducive conditions. The provision of this information in all rotorcraft flight manuals would give pilots the best possible chance to avoid VRS.

Vortex Ring State alerting systems

Safety issue: Not all helicopters have a timely VRS alerting function installed, so that pilots can avoid entering flight conditions that may develop into VRS. The safety objective of an alerting function is to significantly reduce the number of accidents caused by inadvertent entry into VRS.

- 3.48. The early signs of VRS cannot always be recognised by pilots unless they have been specifically trained to recognise them. The symptoms of incipient VRS differ from helicopter to helicopter, but include:
 - subtle changes in the vibration and noise from the rotor
 - wallowing in the trajectory of the aircraft
 - less precise response to controls.

These symptoms are the precursors to those experienced when the aircraft is in fully developed VRS, which include:

- increased rotor vibration and unsteadiness
- thrust and torque fluctuations
- loss of control effectiveness, and counter-intuitive control response
- uncontrolled sudden increase in the rate of descent.
- 3.49. VRS alerting systems are new technology with potential to improve flight safety by alerting the pilot to avoid the flight conditions that may develop into VRS. While this technology is installed on some new helicopters it would be technically difficult to retrofit most older helicopter models.

Emergency locator transmitter (ELT)

- 3.50. In the event of an aircraft accident, the primary function of an ELT is to automatically activate and transmit an encoded signal to the Cospas-Sarsat satellite network and subsequently a notification to the RCCNZ.
- 3.51. The helicopter was equipped with an Artex C406-1HM ELT, mounted on the right side of the tail boom mounting cone. The ELT is designed to activate automatically on detection of impact g-forces over 2.3 *g* in the forward direction and 12.5 *g* in the other five perpendicular axes (rear, left, right, up and down).

- 3.52. The ELT had a rod-type antenna mounted on the top of the right rear cowling. A photo of the helicopter at the staging area shows an intact antenna, but it was found broken at the accident site, suggesting that it broke off during the accident sequence (*see* Figure 15).
- 3.53. During interview, the crew member said that they heard the ELT's audio alert after impact. Also, the pilot observed a red light emitting diode (LED) flashing on the ELT's cockpit remote switch, indicating that the ELT had activated during the accident sequence.
- 3.54. The ELT activated as intended, but was unable to transmit a signal because its antenna broke off during the accident sequence. As a consequence, RCCNZ did not receive a notification from the ELT.
- 3.55. The Commission has previously made recommendations to the CAA to improve the performance of ELTs (Transport Accident Investigation Commission, 2014 and 2023). The importance of technology in tracking and locating has been an item on the Commission's Watchlist since 2015 (Transport Accident Investigation Commission, Watchlist 2024). These technologies improve people's chances of surviving aircraft accidents and incidents.



Figure 15: broken ELT antenna after the accident sequence

4 Findings Ngā kitenga

- 4.1. It was **exceptionally unlikely** that engine or flight-control failures caused the helicopter to impact the terrain.
- 4.2. On the flight to recover the patient, the pilot modified the operator's recommended standard winch circuit. While flying the final approach the pre-winch tasks were incomplete, and the helicopter was not on a stable approach profile.
- 4.3. The pilot's visual attention was primarily focused outside the cockpit and, as a result of a reduced instrument scan, the conditions conducive to VRS were not immediately recognised.
- 4.4. It is **virtually certain** that the helicopter entered Vortex Ring State while descending on the windward side of a ridgeline to recover the patient.
- 4.5. The helicopter's trajectory, in particular the helicopter's descent rate and airspeed, became conducive to Vortex Ring State.
- 4.6. Orographic uplift across the ridge along which the helicopter was flying and the helicopter's pitch attitude during its deceleration both contributed to the early onset of Vortex Ring State.
- 4.7. The helicopter's height above the terrain provided insufficient opportunity for recovery from the Vortex Ring State.
- 4.8. The helicopter manufacturer did not provide specific data about Vortex Ring State to assist pilots in avoiding this phenomenon.
- 4.9. The Emergency Locator Transmitter activated as intended but was unable to transmit a signal because the antenna broke off during the accident sequence.

5 Safety issues and remedial action Ngā take haumaru me ngā mahi whakatika

General

- 5.1. Safety issues are an output from the Commission's analysis. They may not always relate to factors directly contributing to the accident or incident. They typically describe a system problem that has the potential to adversely affect future transport safety.
- 5.2. Safety issues may be addressed by safety actions taken by a participant; otherwise, the Commission may issue a recommendation to address the issue.

Inadequate flight manual information on Vortex Ring State

Safety Issue: The helicopter's Flight Manual did not include sufficient guidance for pilots to recognise and avoid the onset of VRS. This increased the risk of pilots inadvertently entering conditions conducive to VRS.

- 5.3. Kawasaki Heavy Industries has taken the following action to address this issue:
 - On 8 October 2024 Kawasaki Heavy Industries published Service News KSN-117-250, titled 'Introduction of Airbus Helicopters Safety Information Notice Regarding the Vortex Ring State'. The primary purpose of this document is to inform pilots about how to recognize and avoid VRS.
 - Kawasaki Heavy Industries is proceeding to add a recommended maximum rate of descent to the KHI BK117 B-2 Flight Manual.
- 5.4. The Commission welcomes the safety action that has been taken to date. However, it believes more action needs to be taken to ensure the safety of future operations. Therefore, the Commission has made a recommendation in Section 6 to address this issue.

Vortex Ring State alerting systems

Safety Issue: Not all helicopters have a timely VRS alerting function installed, so that pilots can avoid entering flight conditions that may develop into VRS. The safety objective of an alerting function is to significantly reduce the number of accidents caused by inadvertent entry into VRS.

5.5. The Commission has made a recommendation in Section 6 to address this issue.

6 Recommendations Ngā tūtohutanga

General

- 6.1. The Commission issues recommendations to address safety issues found in its investigations. Recommendations may be addressed to organisations or people and can relate to safety issues found within an organisation or within the wider transport system that have the potential to contribute to future transport accidents and incidents.
- 6.2. In the interests of transport safety, it is important that recommendations are implemented without delay to help prevent similar accidents or incidents occurring in the future.

New recommendations

- 6.3. On 26 February 2025, the Commission recommended that Kawasaki Heavy Industries revise the Kawasaki BK117 B-2 Flight Manual to include specific data for Vortex Ring State to assist pilots in avoiding this phenomenon. **(001/25)**
- 6.4. On 17 March 2025, Kawasaki Heavy Industries replied:

Our company's response to your document is "Accepted" .

KHI is working on revising FLM to include specific data regarding the Vortex Ring State.

As planned, KHI will submit the application to Japan Civil Aviation Bureau, start discussion in April, and complete them by June.

- 6.5. On 26 February 2025, the Commission recommended to the Director of Civil Aviation at the Civil Aviation Authority of New Zealand that they promote, through the appropriate International Civil Aviation Organization (ICAO) forum, consideration for the requirement and implementation for Vortex Ring State alerting systems to be installed in new helicopters. **(002/25)**
- 6.6. On 14 April 2025, CAA replied:

CAA notes that Vortex Ring State (VRS) alerting systems are a developing technology. The technical feasibility, cost-effectiveness, and potential unintended consequences of such systems remain uncertain. The CAA will monitor development of VRS alerting systems and consider the best way to support the use of VRS. This recommendation is 'Under Consideration', the CAA will collaborate with TAIC to determine the best method for this to be raised for discussion, noting the CAA is not in a position to promote the activity with ICAO.

6.7. On 14 May 2025, CAA provided an update:

As of 13 May 2025, the CAAs position is that we will seek to engage in any future work that ICAO may undertake regarding VRS alerting systems. However, given the current maturity of the technology, it would be premature to actively promote this topic within ICAO forums at this time. The CAA will continue to review its position as the technology evolves and will discuss any updates in this area with TAIC.

- 6.8. On 26 February 2025, the Commission recommended that the Director of Civil Aviation at the Civil Aviation Authority of New Zealand use the lessons from this report to raise awareness for helicopter pilots of the risks associated with inadvertently entering flight conditions that are conducive to Vortex Ring State. (003/25)
- 6.9. On 14 April 2025, CAA replied:

CAA accepts the importance of using lessons learned to continue to raise awareness of helicopter pilots of the risks associated with inadvertently entering flight conditions that are conducive to VRS. CAA notes this topic is already comprehensively covered in existing helicopter pilot training syllabi, operational manuals, and flight standards. The CAA also notes awareness already raised through additional reports, publications and workshops . This recommendation is 'Under Consideration', the CAA will continue to raise awareness regarding VRS awareness as and when new information becomes available.

6.10. On 14 May 2025, CAA provided an update:

As of 13 May 2025, the CAA has reassessed its position and now considers this recommendation to be 'Accepted and Implemented'. The CAA recognises the importance of applying lessons learned to raise awareness among helicopter pilots about the risks of inadvertently entering conditions conducive to VRS. The Authority has previously outlined how this topic is addressed through existing materials and outreach channels, and it will continue to update and disseminate VRS-related information as new data becomes available.

- 6.11. On 26 February 2025, the Commission recommended to the Director of Civil Aviation at the Civil Aviation Authority of New Zealand that they promote, through the appropriate International Civil Aviation Organization (ICAO) forum, the need for additional information to be included in all rotorcraft flight manuals, to assist pilots in avoiding Vortex Ring State. **(004/25)**
- 6.12. On 14 April 2025, CAA replied:

CAA notes that Rotorcraft flight manuals are the responsibility of the original equipment manufacturers (OEMs) and are approved by the State of Design in accordance with ICAO and bilateral agreements. Current flight manuals already contain information on VRS recognition and avoidance. This recommendation is 'Under Consideration', the CAA will collaborate with TAIC to determine the best method for this to be raised for discussion, noting the CAA is not in a position to promote the activity.

6.13. On 14 May 2025, CAA provided an update:

As of 13 May 2025, the CAAs position is that we do not consider this recommendation actionable unless there is clear evidence of a systemic and widespread lack of appropriate VRS information in existing flight manuals. Based on current assessments, this does not appear to be the case. Any proposals of this nature that are raised with ICAO should be supported by robust evidence of a significant, broad-based issue; therefore, the CAA will not be progressing this recommendation at this time. If evidence of a systemic issue of this nature comes to light in future, the CAA will engage with TAIC with a view to establishing a unified State position and an appropriate mechanism for raising it internationally.

7 Key lessons Ngā akoranga matua

- 7.1. The omission of guidance by the helicopter manufacturer on the avoidance and recovery from Vortex Ring State poses a significant risk to operators.
- 7.2. It is critical that helicopter pilots understand what Vortex Ring State is and how they can avoid entering it.
- 7.3. Flying in mountainous terrain presents helicopter pilots with multiple challenges, including misinterpreting the air environment in which they are flying. Pilots need to use all available sources of information to ensure that they are not subject to visual illusions that might lead them to misjudge their forward speed and rate of descent, particularly when operating close to the ground.
- 7.4. Standard operating procedures help ensure that an aircraft is operated and flown in as safe a manner as possible. Modifying these procedures can increase the risk of an adverse outcome.

8 Data summary Whakarāpopoto raraunga

Aircraft particulars

Aircraft registration:	ZK-HHJ
Type and serial number:	Kawasaki BK117 B-2, serial number 1109
Number and type of engines:	2 x Honeywell LTS101-850B-2 serial numbers LE-45655C and LE45809C
Year of manufacture:	1996
Operator:	Search and Rescue Services Limited
Type of flight:	Commercial transport operations
Persons on board:	3

Crew particulars

	Pilot's licence:	Commercia	l pilot licence (helicopter)
		Private pilo	t licence (aeroplane)
	Pilot's age:	57	
	Pilot's total flying experience:	7257 hours	
Date	and time	19 Septemb	per 2023 at 1707
Location		Mount Piro	ngia, New Zealand
		latitude:	-37° 59′ 28.68
		longitude:	175° 7′ 19.2
Injuri	es	Nil	
Dama	age	Severe	

9 Conduct of the inquiry Te whakahaere i te pakirehua

- 9.1. On 19 September 2023, the Civil Aviation Authority of New Zealand notified the Commission of the occurrence.
- 9.2. On 20 September 2023 the Commission opened an inquiry under section 13(1) of the Transport Accident Investigation Commission Act 1990 and appointed an Investigator-in-Charge.
- 9.3. On 20 September 2023 a protection order was issued for the site and evidence to this inquiry.
- 9.4. On 20 September 2023 three Commission investigators travelled to Hamilton to conduct interviews and secure evidence. On 21 September 2023 investigators accessed the site and secured the Flightcell DZMx.
- 9.5. The Commission advised the Japan Transport Safety Board (JTSB) of the accident, and on 25 September 2023 the JTSB appointed an accredited representative as the State of Manufacturer in accordance with ICAO Annex 13.
- 9.6. On 4 October 2023, at the request of the Commission, the New Zealand Defence Force extracted the wreckage from the site.
- 9.7. On 5 October 2023 the wreckage was transported to the Commission's technical facility in Wellington for further examination.
- 9.8. On 9 March 2024 Sophrodyne Aerospace was engaged to provide expert advice.
- 9.9. On 23 October 2024 the Commission approved a draft report for circulation to seven interested parties for their comment.
- 9.10. Six interested parties each provided a detailed submission, and one party replied that they had no comment. Any changes as result of the submissions have been included in the final report.
- 9.11. On 27 February 2025 the Commission approved the final report for publication.

Abbreviations Whakapotonga

AGL	above ground level
CAA	Civil Aviation Authority of New Zealand
CARs	Civil Aviation Rules
CPL	commercial pilot licence
ELT	emergency locator transmitter
FAA	Federal Aviation Administration, US Department of Transportation
GPS	global positioning system
КНІ	Kawasaki Heavy Industries
kg	kilogramme
kt	knot
ICAO	International Civil Aviation Organization
MBB	Messerschmitt-Bolkow-Blohm
NTSB	National Transportation Safety Board
NZST	New Zealand Standard Time
OGE	out of ground effect
PFD	Primary Flight Display
PPL	private pilot licence

RCCNZRescue Coordination Centre New ZealandSOPStandard Operating ProcedureSTCSupplemental Type CertificateVRSVortex Ring State

Glossary Kuputaka

Exposition	A manual which defines the organisation, identifies the approved senior persons and details the means of compliance with the Civil Aviation Rules.
Flight envelope	Defined by various parameters, flight envelope refers to the limits within which an aircraft can operate safely and efficiently. A flight envelope encompasses both normal and extreme flight conditions and is typically represented graphically.
Flight manual	A controlled document kept in the cockpit that provides information about the aircraft, including system descriptions, limitations and normal and emergency procedures.
Knot	A measurement of speed in nautical miles per hour, equivalent to 1.85 km/h.
National Air Desk	A coordination and tasking function, operated by Hato Hone St John, that provides oversight, dispatch and clinical support functions to air ambulance services.
New Zealand Standard Time	Coordinated universal time +12 hours.

Citations Ngā tohutoru

Ahlin, G.A & Brown, R.E., 2004. *Predicting the Onset of the Vortex Ring State under Accelerated Flight Conditions.*. s.l., s.n.

Airbus, 2021. Vortex Ring State / Airbus Helicopters training recommendations and considerations about the "Vuichard recovery technique". Safety Information Notice 3463-S-00, s.l.: s.n.

Airbus, 2022. Useful information about the Vortex Ring State (VRS) phenomenon. Safety Information Notice 3123-S-00.

Binet, L. & Basset, P.-M., 2024. *Helicopter Vortex Ring State Experimental Research*. [Online] Available at: <u>https://www.easa.europa.eu/en/research-projects/vrs-helicopter-vortex-ring-state-experimental-research</u>

Brown, R. E., 2023. Are eVTOL Aircraft Inherently More Susceptible to the Vortex Ring State than Conventional Helicopters?. s.l., Sophrodyne Aerospace (United Kingdom).

Civil Aviation Authority of New Zealand, 2016. *Flight Test Standards Guides*. [Online] Available at: <u>https://www.aviation.govt.nz/assets/publications/flight-test-standards-guides/ftsg-cpl-bfr-helicopter.pdf</u>

[Accessed 14 December 2024].

Civil Aviation Authority of New Zealand, 2018. *Vortex Ring State*. [Online] Available at: <u>https://www.aviation.govt.nz/assets/publications/vector/Vector-2018-3.pdf</u>

Civil Aviation Authority of New Zealand, 2020. *Good Aviation Practice: Helicopter performance*. [Online]

Available at: <u>https://www.aviation.govt.nz/assets/publications/gaps/helicopter-performance.pdf</u>

[Accessed 28 February 2025].

Federal Aviation Administration, 2019. Helicopter Flying Handbook, FAA-H-8083-21B. s.l.:s.n.

Kawasaki Heavy Industries Ltd, 2021. Kawasaki BK117 B-2 Flight Manual. s.l.:s.n.

Kawasaki Heavy Industries Ltd, 2024. *Introduction of Airbus Helicopters Safety Information Notice Regarding the Vortex Ring State, Service News KSN-117-250, s.l.: s.n.*

Newman, S., Brown, R., Perry, J., Lewis, S., Orchard, M., Modha, A., 2003. Predicting the Onset of Wake Breakdown for Rotors in Descending Flight.. *Journal of the American Helicopter Society,* Volume 48, pp. 28-38.

Sotiropoulos-Georgiopoulos, E., Payan, A., Johnson, C. & Mavris, D., 2023. A Comparison of Traditional And Vuichard Vortex Ring State Recovery Techniques Using On-Line Simulation. *Presented at the Vertical Flight Society's 79th Annual Forum & Technology Display, West Palm Beach, FL, USA, May 16–18.*

Transport Accident Investigation Commission, 2014. *Aviation Inquiry AO-2011-003 In-flight break-up ZK-HMU, Robinson R22, near Mount Aspiring. 27 April 2011.* [Online] Available at: <u>https://www.taic.org.nz/inquiry/ao-2011-003</u>

Transport Accident Investigation Commission, 2023. *Aviation Inquiry AO-2022-002 Loss of control in flight ZK-HEQ, Robinson R22, Karamea, West Coast, 2 January 2022.* [Online] Available at: <u>https://www.taic.org.nz/inquiry/ao-2022-002</u>

Transport Accident Investigation Commission, *Watchlist 2024. Technologies to track and to locate.* [Online]

Available at: <u>www.taic.org.nz/watchlist/technologies-track-and-locate</u>

Wagtendonk, W. J., 2006. *Principles of Helicopter Flight (Second Edition)*. s.l.:Aviation Supplies & Academics Inc.

Appendix 1 Wreckage examination



Figure 16: Splayed cross-tube



Figure 17: Tail rotor



Figure 18: Engine drive shafts

Appendix 2 Operator's standard winch circuit

Stand	lard Winch Circuit
14.90 (There are some minor differences in technique between the three categories of winch due to the liffering problems each scenario presents. The cardinal principle is that any winch should be completed afely with maximum efficiency.
14.91	All standard calls and actions are detailed in the Winch Patter tables in this SOP.
14.92	The standard winch circuit is flown:
	 at approximately 300 ft above highest obstacle,
	b. oriented into wind,
	c. either left- or right-hand pattern as required,
	d. at 60 KIAS, and
	e. It possible, the pilot and/or winch operator should maintain the target area in sight.
14.93	Downwind:
	a. The pilot advises "turning downwind".
	 b. The winch operator: 1) Advantage and account the achie for the winch operating both equipment and
	 Acknowledges and prepares the cabin for the winch, ensuring both equipment and personnel are correctly secured, and the winch person is correctly briefed, advising when complete.
	 Requests "below 60 clear door?" "hoist power on" and "clear to set up for the winch".
	 Once approval is given brings the hook inboard and passes it to the winch person who will attach themselves to the winch hook and attach the safety lanyard to their harness.
	 calls when the target is in the "eight o'clock" position so that the pilot can commence the base turn.
	c. The pilot advises "turning on"
	d. The winch operator acknowledges and provides commentary of the target position until the pilot
	advises that they have visual contact.
	e. Descent is commenced so that the aircraft is maintains 60 KIAS with approximately 200m to run
	and 150 ft above obstacles on finals.
	Note
	01
	18
Heig	ht, speed, and position at the start of finals will need to be modified as dictated by terrain and weather conditions.
14.94	Final Approach
	a. With about 150m to run the aircraft should be on a stable final approach
	b. The winch operator will continue to provide directions to the pilot counting down the distance from 100 to run and advising height, line, and speed adjustments as required.
	c Confined area winching
	 The standard method for all over land operations.
	 When winching to or from confined areas should be commenced after the aircraft is
	established in a stable hover over the winch site. This will allow a thorough assessment of
	power requirements, hover references and the site below.
	d. Clear area winching. Generally limited to Wet or Deck winching due to no opportunity for power
	assessment prior to winching out. See Wet Winching section below.
	assessment prior to winching out. See Wet Winching section below.
	assessment prior to winching out. See Wet Winching section below. e. The pilot will advise "losing sight" of the target and the final stages of the approach are

Appendix 3 Predicted VRS onset boundaries for the BK117 B-2 helicopter



Figure 19: Predicted VRS onset boundaries, showing the effect of aircraft mass (at ISA sea level conditions). (Credit: Dr Richard E. Brown, Sophrodyne Aerospace)



Figure 20: Predicted VRS onset boundaries, showing the effect of air temperature (at 6,000 ft with aircraft mass 3,000 kg).

(Credit: Dr Richard E. Brown, Sophrodyne Aerospace)

Kōwhaiwhai - Māori scroll designs

TAIC commissioned its four kōwhaiwhai, Māori scroll designs, from artist Sandy Rodgers (Ngāti Raukawa, Tūwharetoa, MacDougal). Sandy began from thinking of the Commission as a vehicle or vessel for seeking knowledge to understand transport accident tragedies and how to avoid them. A 'waka whai mārama' (i te ara haumaru) is 'a vessel/vehicle in pursuit of understanding'. Waka is a metaphor for the Commission. Mārama (from 'te ao mārama' – the world of light) is for the separation of Rangitāne (Sky Father) and Papatūānuku (Earth Mother) by their son Tāne Māhuta (god of man, forests and everything dwelling within), which brought light and thus awareness to the world. 'Te ara' is 'the path' and 'haumaru' is 'safe' or 'risk free'.

Corporate: Te Ara Haumaru - the safe and risk free path



The eye motif looks to the future, watching the path for obstructions. The encased double koru is the mother and child, symbolising protection, safety and guidance. The triple koru represents the three kete of knowledge that Tāne Māhuta collected from the highest of the heavens to pass their wisdom to humanity. The continual wave is the perpetual line of influence. The succession of humps represents the individual inquiries. Sandy acknowledges Tāne Māhuta in the creation of this Kōwhaiwhai.

Aviation: Ngā hau e whā - the four winds



To Sandy, 'Ngā hau e whā' (the four winds), commonly used in Te Reo Māori to refer to people coming together from across Aotearoa, was also redolent of the aviation environment. The design represents the sky, cloud, and wind. There is a manu (bird) form representing the aircraft that move through Aotearoa's 'long white cloud'. The letter 'A' is present, standing for a 'Aviation'.

Sandy acknowledges Ranginui (Sky father) and Tāwhirimātea (God of wind) in the creation of this Kōwhaiwhai.

Maritime: Ara wai - waterways



The sections of waves flowing across the design represent the many different 'ara wai' (waterways) that ships sail across. The 'V' shape is a ship's prow and its wake. The letter 'M' is present, standing for 'Maritime.

Sandy acknowledges Tangaroa (God of the sea) in the creation of this Kōwhaiwhai.

Rail: rerewhenua - flowing across the land



The design represents the fluid movement of trains across Aotearoa. 'Rere' is to flow or fly. 'Whenua' is the land. The koru forms represent the earth, land and flora that trains pass over and through. The letter 'R' is present, standing for 'Rail'.

Sandy acknowledges Papatūānuku (Earth Mother) and Tāne Mahuta (God of man and forests and everything that dwells within) in the creation of this Kōwhaiwhai.



Recent Aviation Occurrence reports published by the Transport Accident Investigation Commission (most recent at top of list)

AO-2022-005	Boeing 737-484SF, ZK-TLL, Incorrect fuel configuration, Sydney to Auckland, 7 June 2022
AO-2023-001	Airbus Helicopters AS350B2 (ZK-IDB) and EC130B4 (ZK-IUP), reported close air proximity, Queenstown Aerodrome, 27 December 2022
AO-2018-009	MD Helicopters 500D, ZK-HOJ, In-flight breakup, near Wānaka Aerodrome, 18 October 2018
AO-2022-002	Robinson R22, ZK-HEQ, loss of control inflight, Karamea, West Coast, 2 January 2022
AO-2021-003	Airbus Helicopters AS350 B3e, ZK-ITD, loss of control in flight, Lammerlaw Range, 40 km northwest of Dunedin Aerodrome, 16 September 2021
AO-2020-002	Glider, Schleicher ASK21, ZK-GTG, Impact with Terrain, Mount Tauhara, Taupō, 31 May 2020
AO-2022-001	Ultramagic Balloons, N-250, ZK-MET, pilot ejection from basket on landing, Lyndhurst, near Methven, 1 January 2022
AO-2021-001	Kavanagh Balloons E-260, ZK-FBK, hard landing and ejection of occupants, Wakatipu Basin, near Arrowtown, 9 July 2021
AO-2019-007	Air traffic services outage, 30 September 2019
AO-2019-005	BK-117-C1 ZK-IMK controlled flight into terrain (water), Auckland Islands, 22 April 2019
AO-2020-003	Eurocopter EC120-B, ZK-HEK, Loss of control in flight and collision with terrain, Kekerengu, 50 kilometres northeast of Kaikoura, 15 December 2020
AO-2019-006	Cessna 185A, ZK-CBY and Tecnam P2002, ZK-WAK, Mid-air collision, near Masterton, 16 June 2019

Price \$20