

Final report Tuhinga whakamutunga

Marine inquiry MO-2021-201 Jet boat KJet 8 Loss of control Shotover River, Queenstown 21 March 2021

May 2022



Transport Accident Investigation Commission Te Kōmihana Tirotiro Aituā Waka

No repeat accidents - ever!

"The principal purpose of the Commission shall be to determine the circumstances and causes of accidents and incidents with a view to avoiding similar occurrences in the future, rather than to ascribe blame to any person."

Transport Accident Investigation Commission Act 1990, s4 Purpose

The Transport Accident Investigation Commission is an independent Crown entity and standing commission of inquiry. We investigate selected maritime, aviation and rail accidents and incidents that occur in New Zealand or involve New Zealand-registered aircraft or vessels.

Our investigations are for the purpose of avoiding similar accidents in the future. We determine and analyse contributing factors, explain circumstances and causes, identify safety issues, and make recommendations to improve safety. Our findings cannot be used to pursue criminal, civil, or regulatory action.

At the end of every inquiry, we share all relevant knowledge in a final report. We use our information and insight to influence others in the transport sector to improve safety, nationally and internationally.

Commissioners

Chief Commissioner	Jane Meares
Deputy Chief Commissioner	Stephen Davies Howard
Commissioner	Richard Marchant
Commissioner	Paula Rose, QSO

Key Commission personnel

Chief Executive	Martin Sawyers
Chief Investigator of Accidents	Harald Hendel
Investigator-in-Charge for this inquiry	Robert Thompson
Commission General Counsel	Cathryn Bridge

Notes about Commission reports Kōrero tāpiri ki ngā pūrongo o te Kōmihana

Citations and referencing

The citations section of this report lists public documents. Documents unavailable to the public (that is, not discoverable under the Official Information Act 1982) are referenced in footnotes. This draft report does not cite information derived from interviews during the Commission's inquiry into the occurrence.

Photographs, diagrams, pictures

The Commission owns the photographs, diagrams and pictures in this report unless otherwise specified.

Verbal probability expressions

For clarity, the Commission uses standardised terminology where possible.

One example of this standardisation is the terminology used to describe the degree of probability (or likelihood) that an event happened, or a condition existed in support of a hypothesis. The Commission has adopted this terminology from the Intergovernmental Panel on Climate Change and Australian Transport Safety Bureau models. The Commission chose these models because of their simplicity, usability, and international use. The Commission considers these models reflect its functions. These functions include making findings and issuing recommendations based on a wide range of evidence, whether or not that evidence would be admissible in a court of law.

Terminology	Likelihood	Equivalent terms
Virtually certain	> 99% probability of occurrence	Almost certain
Very likely	> 90% probability	Highly likely, very probable
Likely	> 66% probability	Probable
About as likely as not	33% to 66% probability	More or less likely
Unlikely	< 33% probability	Improbable
Very unlikely	< 10% probability	Highly unlikely
Exceptionally unlikely	< 1% probability	



Figure 1: Jet boat *KJet 8* (Credit: KJet)



Figure 2: Location of accident (Credit: Land Information New Zealand)

Contents Rārangi take

1	Executive summary	1
	What happened	1
	Why it happened	1
	What we can learn	1
	Who may benefit	1
2	Factual information	2
	Narrative	2
	Personnel information	4
	Vessel information	4
	Meteorological and ephemeral information	5
	Site and wreckage information	5
	The operator	5
	How a jet boat works	5
	Tests and research	6
	Previous occurrences	9
	Industry regulation	
	Maintenance and inspection	
3	Analysis	14
	Introduction	14
	Single point of failure	14
	Regulation	
4	Findings	18
5	Safety issues and remedial action	19
	General	19
	Other safety actions	
6	Recommendations	22
	General	
	New recommendations	
7	Key lessons	23
8	Data summary	24
9	Conduct of the inquiry	25
Ab	breviations	26
Glo	ossary	27

Appendix 1 MNZ Commercial Jet Boa	
-----------------------------------	--

Figures

Figure 1: Jet boat <i>KJet 8</i> i	iii
Figure 2: Location of accidenti	iv
Figure 3: Location of the accident and key route positions	3
Figure 4: Left – single 6.2 litre DI V8 Kodiac (Chevrolet) engine	4
Figure 5: Point of impact with trees lining the riverbank	5
Figure 6: General arrangement of a jet unit on a jet boat (not to scale)	6
Figure 7: Diagnostic read out from the main engine	7
Figure 8: Location of fuse box	7
Figure 9: Condition of the failed fuse removed from <i>KJet 8</i>	8
Figure 10: Example of the condition of a similar fuse deliberately failed through electrical	
overload	8
Figure 11: Left – wiring loom at the rear of the fuse box from <i>KJet 8</i> showing the two wires tha	t
had been attached to the failed fuse. Right – fuse box where the failed fuse had been located	9
Figure 12: Maintenance section of Maritime Rules Part 82 audit checklist	2
Figure 13: Image of fuse with wiring attached1	5
Figure 14: KJet's new arrangement for fuse installation2	21

1 Executive summary Tuhinga whakarāpopoto

What happened

- 1.1 On 21 March 2021, the jet boat *KJet 8* (figure 1) was travelling on the Shotover River (figure 2) with a driver and 12 passengers on board. As it rounded a right-hand bend the engine stopped and as a result the driver lost control of the jet boat.
- 1.2 It continued moving forward under its own momentum and collided with a low overhanging branch of a tree on the bank of the river.
- 1.3 The driver and one passenger were struck on the head by an overhanging branch and received moderate head injuries. They were airlifted to hospital and discharged the same day.

Why it happened

- 1.4 A fuse within the engine control system failed resulting in the engine stopping.
- 1.5 As a consequence of the engine stopping, propulsion and steering was lost, and the driver was unable to control the jet boat.
- 1.6 Examination of the failed fuse showed that it is **virtually certain** the fuse failed as a result of mechanical fatigue caused by vibration. The fuse and its connections into the main fuse box were replaced and the engine started and operated successfully.
- 1.7 The cause of the accident was a single point of failure in a critical jet boat control system, which resulted in total loss of control of the jet boat. The single point of failure had not been identified by the operator as part of a risk mitigation process and therefore the Commission has made a recommendation to the Director of Maritime New Zealand (MNZ) that:

They engage with operators working under Maritime Rules Part 82 to identify jet boat systems which carry the risk of single point failure that would result in a total loss of control of the jet boat, and discuss possible measures that could be taken to reduce the risk to passengers and crew to as low as reasonably practicable.

What we can learn

1.8 To prevent similar component failures in the future requires that an operator conducts a thorough and robust assessment of a jet boat operating system and identifies appropriate mitigation measures. Specifically, in relation to this incident by ensuring that the flexing of wires cannot apply a mechanical load to the fuses and that fuse boxes are mounted in such a way that they are not subject to the direct vibration of something as significant as an engine.

Who may benefit

1.9 The commercial jet boat industry, recreational jet boat owners, the regulator MNZ, the wider marine industry and boat builders.

2 Factual information Pārongo pono

Narrative

- 2.1 On 20 March 2021, the day before the accident, the single-engine jet boat *KJet 8* was on a return trip and approaching the road bridge before entering Lake Wakatipu. The driver, in accordance with local requirements, switched off the engine and stopped the boat.
- 2.2 Shortly afterwards the driver attempted to re-start the engine, but it would not start. The driver made a radio call to the Kawarau Jet Service Holdings Limited (KJet) Marine Base¹ (figure 3) and requested assistance before checking the battery terminals in the engine compartment.
- 2.3 The driver attempted to start the engine an additional four or five times before the engine finally started. The driver then continued the trip back to the pier at Queenstown to offload the passengers.
- 2.4 *KJet 8* was taken out of service for the rest of the day. It underwent diagnostic checks but there were no faults registered. The boat was successfully started several times before being returned to the Marine Base overnight.
- 2.5 At about 0825 on 21 March 2021, the driver of the *KJet 8* arrived at the Marine Base and checked the hazard board for any potential new route hazards before launching the boat into the water.
- 2.6 The driver carried out initial checks using prompts contained on a checklist. On completion of the checks the driver took *KJet 8* from the Marine Base to the main pier in Queenstown.
- 2.7 At about 1000, *KJet 8* departed on its first trip with 11 passengers on board. It returned 55 minutes later and there were no reported deficiencies with the boat.
- 2.8 At about 1100, *KJet 8* departed on its second trip of the day with 12 passengers on board. The outbound trip proceeded up the Kawarua and Shotover Rivers (figure 3), turning around at approximately 1135 and heading back down the river. Approaching a right-hand bend, the driver recalled not hearing any engine noise and the boat levelled out, lost steerage and continued to travel straight ahead.
- 2.9 The driver was unable to regain control of the jet boat and shouted to the passengers to "get down" just before being struck on the head by an overhanging branch from a tree. *KJet 8* came to a halt when it became entangled in a tree on the riverbank.
- 2.10 At about 1140 the Marine Base received a radio call from a passenger on board *KJet 8* requesting "help, help, help". The deputy operations manager spoke with the passenger who confirmed that they were calling from *KJet 8* and that the driver had been injured.
- 2.11 The passenger informed the deputy operations manager that the boat was located "close to some bridges".
- 2.12 At about 1142, *KJet 1* departed the Marine Base en route to assist *KJet 8*.

¹ Term for the location of workshops and overnight storage facility.

2.13 At 1154, *KJet 1* arrived at the scene. Its crew located *KJet 8*, assessed the scene and commenced first aid for the driver and passengers. The driver and one passenger appeared to have moderate head injuries, later diagnosed at the hospital, including a minor concussion.



Figure 3: Location of the accident and key route positions (Credit: Google Earth)

- 2.14 At about 1200, the passengers were assisted from the boat and onto the riverbank.
- 2.15 At 1211, it was confirmed that a rescue helicopter was at the scene, and by 1230 the driver of *KJet 8* and the injured passenger were on board and en route to the local hospital. They were released later the same day.
- 2.16 The remaining 11 passengers were transferred to other jet boats and returned to the operator's base where they were assessed by paramedics. Some passengers were treated for minor injuries before being released.
- 2.17 On completion of the passenger rescue, *KJet 8* was released from under the branch of the tree. It was floated downstream to a nearby bridge and recovered onto a road trailer and transported back to the Marine Base. An attempt had been made to start the engine, but it was unsuccessful.

Personnel information

- 2.18 The driver of *KJet 8* held a Jet Boat Driver Commercial Licence (issued by MNZ) on 23 January 2015, which was valid for 10 years.
- 2.19 The driver also held a Waka Kotahi NZ Transport Agency DL9 driver licence medical certificate issued on 19 December 2014, as required for the role, which had expired on 19 December 2019. An application for a new certificate had been made on 26 February 2021. The driver also held a current Workplace First Aid Certificate valid until 17 September 2021.
- 2.20 The driver commenced employment with KJet in 2012 and had nearly 1600 hours of driving experience. They had undergone audited driver refresher training on 16, 18 and 20 March 2021.

Vessel information

- 2.21 *KJet 8* was a 6.5 metre jet boat built by Mackraft in Bluff, New Zealand. It was initially inspected in 2003.
- 2.22 It had a maximum speed of 95 kilometres per hour and a total seating capacity of 13, permitting 12 passengers and a driver to be seated.
- 2.23 It was powered by a marinised² single petrol-driven 6.2 litre Direct Injection V8 Kodiak engine³ supplied by KEM Equipment based in Oregon, United States of America (USA) (figure 4 left). On 31 March 2021, the engine running hours totalled 1311. Propulsion was provided by a Hamilton Jet type 212 jet unit (figure 4 right).



Figure 4: Left – single 6.2 litre DI V8 Kodiac (Chevrolet) engine. Right – Hamilton Jet type 212 jet unit

² Marinisation is the process of modifying or converting for marine use.

³ Originally a Chevrolet model designed for a road vehicle, but which had been marinised by KEM Equipment and sold as a Kodiak engine.

Meteorological and ephemeral information

2.24 At 1100 on 21 March 2021, the temperature was 12°C and there was a 2 kilometre per hour southerly wind. Visibility was approximately 20 kilometres.

Site and wreckage information

2.25 The accident occurred on the return leg of the journey, travelling downstream approaching a right-hand bend. Figure 5 shows the point of impact with the tree branch situated on the left-hand bank. The jet boat suffered minor structural damage.



Figure 5: Point of impact with trees lining the riverbank

The operator

- 2.26 At the time of the accident the operator, KJet was a privately owned adventure tourism business based in Queenstown, New Zealand. Operating since 1958, the company was the world's first commercial jet boat operator.
- 2.27 Passengers board alongside the main town pier in Queenstown and are taken for a jet boat ride on the Kawarau and Shotover Rivers, returning to Queenstown about 60 minutes later.
- 2.28 KJet operated eight commercial jet boats.

How a jet boat works

2.29 A jet boat is propelled and steered through the water by a jet unit (figure 6). The jet unit is an impeller water pump powered by the jet boat's internal combustion engine.

- 2.30 The pump sucks water in through an intake under the hull and forces it out through a pipe and steering nozzle mounted on the transom,⁴ thereby providing thrust to the boat.
- 2.31 The steering nozzle can be rotated either side using the driver's steering wheel to direct the thrust and provide steering.
- 2.32 A bucket-shaped deflector is attached to the unit, which can be lowered down over the end of the steering nozzle. The deflector redirects the water jet forwards, which provides reverse thrust. The deflector is named the 'reverse bucket' and is lowered using a lever located beside the driver's seat.



Figure 6: General arrangement of a jet unit on a jet boat (not to scale)

Tests and research

Diagnostics

- 2.33 After the passengers had been evacuated from the scene of the accident, KJet mechanics used diagnostic equipment to try and identify the cause of the engine stopping without any warning. The diagnostic equipment detected a 'Powertrain Relay Contact Fault' (figure 7).
- 2.34 Once the Commission had opened an inquiry into the accident, Commission investigators worked with KJet engineers to oversee the process of diagnosing the causes and circumstances of the engine failure.

⁴ The transom is the vertical and transverse part of the hull at the extreme aft of the jet boat.



Figure 7: Diagnostic read out from the main engine

2.35 The information from the diagnostic read out provided engineers and investigators with a focal point from which to systematically try to identify the cause of engine failure. During examination of the engine, its components and the powertrain, it was found that deliberate movement of the wiring loom connected to the main engine fuse box (figure 8) caused the powertrain relay to activate.



Figure 8: Location of fuse box

2.36 Closer inspection of the fuse box found that a 20 ampere fuse protecting the engine powertrain relays had failed. The fuse and the connections into the main fuse box were replaced, the engine was retested and it operated successfully.

Independent examination

- 2.37 Following the initial findings of the investigation that a single 20 ampere fuse had contributed to the engine stopping without warning, the Commission appointed Quest Integrity NZL Limited (Quest Integrity) to examine the fuse from *KJet 8* and help determine the exact cause of the failure.
- 2.38 Essentially two modes of possible failure were examined electrical overload and mechanical fatigue.



Figure 9: Condition of the failed fuse removed from KJet 8



Figure 10: Example of the condition of a similar fuse deliberately failed through electrical overload

- 2.39 There was significant evidence to show that the fuse did not fail as a result of electrical overload as shown in figure 10. Extensive melting did not occur, the fuse section was not distorted, and failure did not occur in the normal mid-point position of the fuse (figure 9).
- 2.40 It was considered **very likely** that the fuse failed primarily because of bending fatigue due to flexing caused by an unsupported connecting wire. Evidence to support this hypothesis included: lack of gross distortion, a flat fracture face, failure occurring at the end of the radius where there was a stress concentration, the design of the fuse box, and stiff connecting wires allowing a rotation of about 10 degrees.
- 2.41 The fuse was made from zinc, which provided reasonable corrosion resistance, low melting point, good electrical conductivity and relatively low cost. Zinc is not a good structural material. It is hard and brittle and will be highly prone to fatigue failures at room temperature. It is therefore important that the wires connecting to a fuse box should not be able to transfer cyclic loading to the fuse, which would lead to fatigue.
- 2.42 The fuse box fitted to *KJet 8* was of a design commonly used in the automotive industry where wiring looms are generally secured to prevent significant vibration occurring on the wiring. When *KJet 8*'s engine was marinised the fuse box was installed on a bracket bolted to the engine without any vibration dampening. Without vibration

dampening the fuse box was subject to vibrations from the engine, which could lead to fatigue loading on the fuse box assembly. Wires were bent into place after they were fitted into the fuse box.



Figure 11: Left – wiring loom at the rear of the fuse box from *KJet 8* showing the two wires that had been attached to the failed fuse. Right – fuse box where the failed fuse had been located

2.43 If the resonant frequency⁵ of a wire assembly is close to one of the engine's vibrational frequencies, resonance will occur that could result in significant vibrational movement and increased risk of failure of the weak points, such as a fuse. In this case it is considered **probable** that the wire to the failed fuse had a longer unsupported length than the other wires (figure 11), which likely resulted in excessive vibration contributing to the mechanical failure of the fuse.

Conclusions of Quest Integrity's examination

- 2.44 The report by Quest Integrity made the following conclusions (quoted):
 - The fuse in *KJet 08* probably failed as a result of mechanical fatigue as a result of the connecting wiring flexing due to resonant vibration. This resulted in wear/damage to the fuse support hole and a straight flat fracture at the location most prone to bending fatigue.
 - The fuse in *KJet 08* did not fail as a result of electrical overload.
 - The fuse in *KJet 08* did not fail as a result of a mechanical overload, i.e. it did not fail as a result of the accident.
 - The fuse box/wiring assembly/support structure was not ideal to prevent failure as a consequence of the following:
 - a) The fuse box will have seen significant vibration as it was mounted in a stiff bracket that was directly bolted to the engine in the jet boat.
 - b) Unsupported wiring could flex backward and forward as a result of resonance.
 - c) The fuse box was not ideal in that the flexure of the wires could introduce significant torsional movement on the legs of the fuses and the fuses were made of zinc. Ideally it should not be possible for the movement of the wires to cause any movement in the legs of the fuses.

Previous occurrences

2.45 The Commission has been unable to find a previous occurrence of a jet boat engine failure caused by a fuse subjected to mechanical fatigue or electrical overload. There were no reported cases found in the international jet boat community nor any contained in the MNZ accident database.

⁵ The natural vibrating frequency of an object.

- 2.46 The Commission also contacted the Transportation Safety Board of Canada, a country where jet boating is well established, to gauge how systemic this type of occurrence might be. Their accident database contained 208 cases of water jet propulsion system occurrences. Of these 208 only three were engine failures, but none were as a result of a fuse being subjected to mechanical fatigue or electrical overload.
- 2.47 KEM Equipment, the company in the USA responsible for marinising *KJet 8*'s engine, was also contacted to establish whether they had received reports about mechanical fatigue of fuses or loss of power caused by the excessive vibration of the wiring assembly. This occurrence was the first incident brought to their attention.
- 2.48 Inspection of KJet's own incident log showed that there were 37 incidents recorded between 1 March 2020 and 31 March 2021. Of these, six were recorded as electrical incidents, but none were related to fuses or wiring assembly.

Industry regulation

Maritime Rules Part 80

- 2.49 Maritime Rules Part 80: Marine Craft Involved in Adventure Tourism came into force in August 1998 and was superseded by Maritime Rules Part 82: Commercial Jet Boat Operations River in August 2012. Part 80 incorporated codes of practice for various types of marine craft used in the adventure tourism industry, including commercial jet boats on rivers.
- 2.50 Part 80 required, in part, that the operator "draw a safe operational plan related to the specific operations of the owner's boat or boats". Part 80 laid out various requirements that the Safe Operational Plan (SOP) must address, including a planned maintenance schedule and operational checks of the vessel.
- 2.51 Two jet boat accidents occurred in 1999.⁶ The Commission investigated the accidents and made 15 recommendations. One of the recommendations was directed at Part 80 and is relevant to this inquiry:

...a change to Rule Part 80 that will require commercial jet boat operators to identify on each jet boat all components that are critical to the safe operation of the boat, and to have a documented inspection and maintenance system in place that covers those critical components. The inspection and maintenance system should complement rather than replace any system of daily checks. (104/99)

With the change to Part 80, there was an expectation from the Maritime Safety Authority⁷ that operators would address this issue in their own SOP. Maritime Rules Part 80 was subsequently superseded in 2012 when Part 82: Commercial Jet Boat Operations – River came into force.

Maritime Rules Part 82

2.52 Part 82 did not explicitly address recommendation 104/99. However, it included a section 'Managing hazards' (Appendix 2), which refers the jet boat operator to "its

⁶ MO-1999-213 Jet boat Shotover 15 collision with canyon wall, Shotover River, Queenstown, 12 November 1999 and MO-1999-212 Jet boats Shotover 14 and Shotover 15 separate collisions with canyon wall Shotover River, Queenstown, 21 October and 12 November 1999.
⁷ The Maritime Safety Authority was the predecessor to MNZ.

health and safety responsibilities under the Health and Safety in Employment Act 1992, by including, without being limited to, the following [in part]:

(a) the process used by the operator to identify the operational hazards that may cause harm to a person; and

(b) the process used by the operator to review operational hazards and how they are to be controlled, including how drivers are made aware of new hazards before drivers and passengers are exposed to them (for example, the day-to-day changes in river conditions); and...

(c) the process for reporting significant hazards, accidents, incidents, and mishaps; and \dots "

2.53 On 23 February 2019, the Commission opened a further inquiry into a commercial jet boat accident,⁸ which involved one passenger suffering a significant injury and eight passengers minor injuries when a jet boat's steering failed and it made contact with a rock face.

The subsequent report recommended to the Director of MNZ that:

They ensure all operators working under Maritime Rules Part 82 have identified on each jet boat all systems that are critical to the safe operation of the boat, and to have a documented inspection and maintenance system in place that covers those critical systems and also ensures they meet manufacturers' specifications. The inspection and maintenance system should complement rather than replace any existing system of daily checks. (010/19)

Maritime NZ's response to recommendation 10/19 was in part:

Maritime NZ agrees with this recommendation...

Maritime NZ is currently developing a programme to extend areas within an operation that are audited under Part 82 requirements. The audits will be covering a wide range of topics but will specifically cover two key items:

- The adequacy of the driver competency programmes required by the rule, and checking that they have been properly implemented by each operation.
- The adequacy of the maintenance programmes required by the rule, and checking that they have been properly implemented by each operation.

As part of this programme of work Maritime NZ is also exploring working with commercial jet boat operators to develop critical systems maintenance guidance.

2.54 In 2020, the responsibility for auditing operator's SOP was transferred from a third party to MNZ and an audit checklist for Part 82 was introduced. The checklist can be seen in Appendix Part 82 Audit Checklist (MSF293). The maintenance section of the audit checklist (figure 12) mentions "critical systems" as a checklist item, although that term is not defined. MNZ's work in this area is ongoing.

⁸ Marine inquiry MO-2019-201, Jet boat Discovery 2 contact with Skippers Canyon wall, 23 February 2019.

Operational decisions including the control and scheduling of maintenance and internal quality assurance

Requ	Requirement		uirement		Requirement NA 🗸 OBS		✓ OBS	NC	NC
10	Maintenance programme								
	 (MR 82, Appendix 1.3.5 (b) Check the contents of the maintenance programme Check the adequacy of the programme Ask the operator if there have been any amendments to the programme. Is the programme being complied with? SOP should cover all critical systems as well as routine maintenance for each vess 	el							

Figure 12: Maintenance section of Maritime Rules Part 82 audit checklist

Maintenance and inspection

Maritime New Zealand (MNZ)

- 2.55 In accordance with Part 82 of the Maritime Rules, Kawarau Jet Service Holdings Limited (operating as KJet) were issued with a Jet Boat Operator Certificate on 13 December 2019. The certificate was valid until 28 September 2022 subject to audits required in accordance with section 54 of the Maritime Transport Act 2013 and the requirements of Maritime Rules Part 82 being met.
- 2.56 The Jet Boat Operator Certificate showed that the boats being operated had been inspected, the operator's SOP had been approved, and the operation had been audited and found to be in accordance with the Code of Practice for the Safety of Jet Boats Operating on Rivers (Appendix 1 of Part 82 of the Maritime Rules).
- 2.57 The audit conducted on 23 September 2019 found that pages 26 and 27 of the SOP showed that the operator had applied a maintenance programme for every commercial jet boat and propulsion unit.
- 2.58 The most recent MNZ inspection check sheet for *KJet 8* was dated 21 October 2020, and the inspection found the jet boat 'Fit for Purpose' and there were no deficiencies.

The operator

2.59 Section 4 of the SOP described the planned maintenance requirements, namely:

All boats are checked and maintained on daily and weekly basis. As well as these routine checks, they are also maintained according to the operational hours they have had. The forms used for these checks are listed below: KJet Daily Checklist

Spanner Check Sheet A

Spanner Check Sheet B

Spanner Check Sheet C

KJet Spanner Check Log.

- 2.60 Relevant to this accident the check sheets describe the checks required on the engine, jet unit and electrical system.
- 2.61 Examination of servicing records for *KJet 8* between January 2020 to March 2021 showed that the servicing requirements as defined in the SOP had been carried out.

3 Analysis Tātaritanga

Introduction

- 3.1 At the time of the accident the commercial jet boat *KJet 8* was operating on the Shotover River and there were 12 passengers and a driver on board. Common with this type of adventure activity the vessel was proceeding at high speed down the river when the engine stopped and control of the boat was lost.
- 3.2 The boat impacted with a low overhanging tree branch on the bank of the river. One passenger and the driver were airlifted to hospital with head injuries and some other passengers suffered minor injuries.
- 3.3 Commercial jet boating can be a high-risk activity and in the event of an accident the consequences can be severe. The Commission has opened several inquiries and made recommendations to help improve jet boating safety. Jet boat operators (including KJet) have been proactive around improving safety systems and MNZ have improved the regulatory environment.
- 3.4 At the time of the accident, *KJet 8* was on its return journey and approaching a righthand bend in the river when its single engine stopped. The petrol-driven engine required a constant power supply to operate. However, the failure of a 20 ampere fuse resulted in a loss of the power supply and the engine was unable to function. Failure of the fuse is discussed in more detail below.
- 3.5 The jet unit water pump relied on the engine to drive the impeller and draw water through an intake under the hull and force it out through a pipe and steering nozzle mounted on the transom. This in turn provided the thrust and directional control of the jet boat.
- 3.6 Immediately after the fuse failed the engine stopped and it was unable to drive the impeller. Without a supply of water, the jet unit stopped and was unable to provide the thrust required for steering, forward and reverse power, and braking.
- 3.7 Consequently, the jet boat driver was unable to steer clear of any dangers or reduce the effect of any impact by slowing down or reversing. The Commission found that the actions of the jet boat driver were not contributory.
- 3.8 The following section analyses the circumstances around why *KJet 8*'s engine stopped and control of the boat was lost.

Single point of failure

- 3.9 When the 20 ampere fuse was replaced, the engine started and operated normally.
- 3.10 To confirm that the failed fuse was the cause, and that there were no other contributory factors, the investigation examined other parts of the operating system that could potentially have prevented the engine from functioning correctly.
 - A fuel supply failure was eliminated. The engine would not have stopped instantly, the low fuel indicator on the dashboard was not lit, there were no fuel leakages observed and the quality of the fuel was satisfactory.

- There was no evidence of a mechanical failure before or after the accident. When the engine was eventually restarted it ran satisfactorily without any repair or modification work being undertaken, other than replacing the failed fuse.
- About the complete electrical system, it was determined that the circuit from the battery to the point of fuel ignition was fully operational both before and after the accident. An electrical relay fitted in line with the failed 20 ampere fuse was tested and found to be operating satisfactorily.
- 3.11 The Commission found that it is **virtually certain** the cause of the unexpected and instant engine stop, resulting in total loss of vessel control, was mechanical failure of the powertrain relay fuse as described in section 2.
- 3.12 The mechanical failure of the fuse was **very likely** a result of a load being imparted onto the leg of the fuse from the wire of the engine wiring loom as shown in figure 13. That load was cyclic because it was also subject to engine vibrations.



Figure 13: Image of fuse with wiring attached

Regulation

Safety Issue: The regulatory requirements for commercial jet boat operations do not fully mitigate the inherent risk of single point failure of the propulsion and control systems resulting in a total loss of control of the jet boat.

3.13 Adapting readily available automobile engines for use in a marine environment is not uncommon. In the case of *KJet 8* the Kodiac engine had been marinised by KEM in the USA. KEM conduct validation testing on their designs, which includes vibration endurance tests. They have also delivered thousands of marinised engines similar to the engine installed on *KJet 8*, which in turn have accumulated thousands of operational hours.

- 3.14 There have been no known previous incidents recorded where the mechanical failure of a single fuse has resulted in loss of control. As a result, manufacturers, designers and builders have likely been oblivious to the potential problem.
- 3.15 The rare nature of this fuse failure means it is unlikely it represents a systemic safety issue. However, given the mechanical failure of the fuse was attributed to the effects of vibration and the arrangement of the connecting wires (both of which were original design factors), over time similar incidents could potentially occur on any vessel where such an engine and fuse box is fitted.
- 3.16 To prevent similar occurrences, operators should ensure that flexing of the wires at the back of the fuse connections cannot apply a mechanical load to the fuse connectors.
- 3.17 A recommendation would have been made to KJet to ensure the safety of the fuse arrangement in their vessels. However, the Commission is satisfied that the safety action taken to date by the company has addressed the safety factors identified during the investigation (see section 5).
- 3.18 On this occasion it was an unforeseen mechanical failure that caused the fuse to fail but equally, and by design, the fuse could have failed as a result of an electrical overload. The consequences for passenger safety would be exactly the same. Likewise, there are many other potential points of failure which could lead to immediate and total loss of control of the jet boat.
- 3.19 It is therefore important to recognise that resolving the safety issue directly associated with the fuse arrangement does not in itself address the wider systemic issue of identifying single point failures on critical control systems. This accident occurred as a result of a single piece of equipment failing, and there was no redundancy in the operating system from which a recovery could be made.
- 3.20 Identifying critical systems and single points of failure in a control system is a key risk mitigation requirement to ensure that a jet boat is "adequate for the nature of commercial jet boat operation" as required in Maritime Rules Part 82.
- 3.21 This incident, and the incident at Skipper's Canyon,⁹ indicates a need for operators to improve passenger safety by proactively carrying out more thorough and detailed technical assessments by identifying both potential single point failures critical to the safe operation of individual vessels and the necessary mitigation measures.
- 3.22 The process should be an integral part of meeting the Maritime Rule requirements for jet boats to be "adequate for the nature of commercial jet boat operation". To provide a reasonable level of reassurance that the process has been considered in-depth it should be fully documented in the operator's SOP, made available for inspection by the regulator, and be inspected as part of the auditing process.
- 3.23 In 2019, as a result of the inquiry MO-2019-201, the Commission recommended to the Director of MNZ that:

...they ensure all operators working under Maritime Rules Part 82 have identified on each jet boat all systems that are critical to the safe operation of the boat, and to have a documented inspection and maintenance system in place that covers those critical systems and also ensures they meet manufacturers' specifications. The inspection and maintenance system should complement rather than replace any existing system of daily checks. (010/19)

⁹ TAIC inquiry MO-2019-201 Skippers Canyon.

- 3.24 MNZ have ongoing work on this, and to date have strengthened the governance of commercial jet boat compliance auditing, and also introduced an audit checklist as described in section 2. The Commission welcomes the progress already made by MNZ.
- 3.25 The KJet accident highlights the vulnerability of jet boats to single point failure and loss of control, and the need to identify and mitigate single points of failure for a jet boat's control system. The Commission has therefore made a recommendation to the Director of MNZ that:

They engage with operators working under Maritime Rules Part 82 to identify jet boat systems which carry the risk of single point failure that would result in a total loss of control of the jet boat, and discuss possible measures that could be taken to reduce the risk to passengers and crew to as low as reasonably practicable.

Driver incapacitation

- 3.26 The driver was incapacitated and a passenger reported the accident using the boat's radio. The ability of passengers to raise an alarm cannot always be guaranteed. In the event of a driver becoming incapacitated a system of alerting rescue services is required.
- 3.27 Since the accident, KJet have installed an emergency button on all jet boats for passengers to use in the event the jet boat driver is incapacitated. The button triggers an alarm at the Marine Base to alert shoreside management of an issue with the jet boat. The pre-departure brief for passengers includes an introduction to the purpose, location and operation of the emergency button.

4 Findings Ngā kitenge

- 4.1 The actions of the jet boat driver were not contributory.
- 4.2 In the event of a driver becoming incapacitated a foolproof system of contacting rescue services is required.
- 4.3 The fuse failure resulted in a loss of power to the jet boat's propulsion and control system. As a result, there was an immediate and total loss of control of the jet boat.
- 4.4 It is **virtually certain** that the single cause of the engine stopping was the mechanical failure of a 20 ampere fuse fitted inside the fuse box and mounted to the engine.
- 4.5 Mechanical failure was **very likely** caused by a load being imparted onto the leg of the fuse by unsupported wiring, which was susceptible to resonating with engine vibrations back and forwards.
- 4.6 Regulatory requirements for commercial jet boat operations do not fully mitigate the inherent risk of a single point failure of the propulsion and control systems.
- 4.7 Had the fuse failed as a result of an electrical overload the consequences for passenger safety would be exactly the same as a mechanical failure.
- 4.8 Operators can improve passenger safety by: proactively carrying out more thorough and detailed technical assessments; and identifying both potential single point failures critical to the safe operation of individual vessels and the necessary mitigation measures.

5 Safety issues and remedial action Ngā take haumanu me ngā mahi whakatika

General

- 5.1 Safety issues are an output from the Commission's analysis. They typically describe a system problem that has the potential to adversely affect future operations on a wide scale.
- 5.2 Safety issues may be addressed by safety actions taken by a participant, otherwise the Commission may issue a recommendation to address the issue.

Safety Issue: The regulatory requirements for commercial jet boat operations do not fully mitigate the inherent risk of single point failure of the propulsion and control systems resulting in immediate and total loss of control of the jet boat.

5.3 On 12 December 2019, the Commission recommended to the Director of MNZ that:

...they ensure all operators working under Maritime Rules Part 82 have identified on each jet boat all systems that are critical to the safe operation of the boat, and to have a documented inspection and maintenance system in place that covers those critical systems and also ensures they meet manufacturers' specifications. The inspection and maintenance system should complement rather than replace any existing system of daily checks. (010/19)

5.4 In response to recommendation 010/19 the Director of MNZ responded in part that they had taken the following safety actions to address this issue:

Maritime NZ is currently developing a programme to extend areas within an operation that are audited under Part 82 requirements. The audits will be covering a wide range of topics but will specifically cover two key items:

- The adequacy of the driver competency programmes required by the rule, and checking that they have been properly implemented by each operation.
- The adequacy of the maintenance programmes required by the rule, and checking that they have been properly implemented by each operation.

As part of this programme of work Maritime NZ is also exploring working with commercial jet boat operators to develop critical systems maintenance guidance.

- 5.5 The Commission welcomes the safety action to date about that recommendation. However, it believes more action needs to be taken to ensure the safety of future operations, specifically the need for operators to identify and document thorough assessments on critical systems and single points of failure, including the measures taken to reduce the risk to passengers and crew to as low as reasonably practicable. Therefore, the Commission has made a recommendation in section 6 to address this issue.
- 5.6 MNZ has taken further action since recommendation 010/19 was issued, as described below:

Since our response to Draft Report MO-2019-201 in December 2019, MNZ has undertaken a significant overhaul of the system for auditing SOPs under Part 82.

Previously, an MNZ-delegated third party was responsible for compliance activities under Part 82, including:

Inspecting all the vessels requiring an inspection;

Assessing jet boat driver's license applicants; and Auditing operator SOPs.

In 2020, the responsibility for auditing operator SOPs was transferred to MNZ staff, with third party delegation limited to vessel inspections and assessing some license applications. The criteria and processes for this limited delegation are still being finalised. Having MNZ staff responsible for auditing all operator SOPs allows for:

Certainty that audits are of high quality; and Strong oversight of the operators as well as the performance of any delegated third parties.

Please see attached our Part 82 Audit Checklist (MSF293). As you can see, audits are in-depth and cover the adequacy of driver competency and maintenance programmes.

For your information, we are also working toward closing TAIC Rec. 010/19, the recommendation that came out of Report MO-2019-201, and hope to be in a position to do that soon.

Other safety actions

- 5.7 The following safety actions have been taken by KJet to address key safety factors identified during the investigation and therefore the Commission has not made a recommendation.
 - Heavy Duty Fuses and Relays The investigation into the cause of the engine shutting down identified the 20-amp fuse for the powertrain relay on the engine to be the fault. The fuse did not blow; but fractured internally creating an open circuit, resulting in the engine shutting down. The fuse/relay box is mounted directly onto the engine as supplied by Kodiak. The fuses and relays are of the micro style, so they have much smaller pins with a lot less contact into the receiver in the fuse box.
 - After consultation with Kem equipment and with our auto electrician as to what the best way is to prevent this from happening again and looking at the options of remote mounting, redundancies etc, we decided to change from push in fuses to a bolt in style fuse, and to change from Micro Relays to standard size blade HD Bosch relays, and mount these all on vibration dampers on to the factory mount point.
 - We are installing the above set up on all our Kodiak D.I. engines in the fleet. [a photo of the new arrangement is shown below see figure 14]
 - Centre Bars We have designed and fabricated centre bars to protect both staff and customers should a boat come into contact with tree branches, they are designed to deflect branches and debris away from the occupants of the boat.
 - This safety bar system is being installed through-out our fleet.
 - Emergency Button We have installed an emergency button specifically for passengers to use in case of an emergency if the driver has been incapacitated, this button when pushed activates an alarm located at the Operations Base which is monitored at all times.
 - The Emergency Button is being installed through-out the fleet as well.
 - We have replaced our safety signage both on board the boats and the safety boards used by the drivers to reflect the new emergency button
 - In an instance when the Emergency Button is pushed, we would then log on to the onboard surveillance camera system from the Operations Base and get real time camera footage and the GPS location of the boat.¹⁰

¹⁰ Official safety action response from KJet.



Figure 14: KJet's new arrangement for fuse installation

6 Recommendations Ngā tūtohutanga

General

- 6.1 The Commission issues recommendations to address safety issues found in its investigations. Recommendations may be addressed to organisations or people, and can relate to safety issues found within an organisation or within the wider transport system that have the potential to contribute to future transport accidents and incidents.
- 6.2 In the interests of transport safety, it is important that recommendations are implemented without delay to help prevent similar accidents or incidents occurring in the future.

New recommendations

6.3 On 27 April 2022, the Commission recommended to the Director of MNZ that they engage with operators working under Maritime Rules Part 82 to identify jet boat systems which carry the risk of single point failure that would result in a total loss of control of the jet boat, and discuss possible measures that could be taken to reduce the risk to passengers and crew to as low as reasonably practicable. (008/22)

On 5 May 2022, the Director of MNZ replied:

We thank you for amending the draft version of this recommendation based on our feedback of 13 April 2022.

We accept this recommendation. In response, building on actions taken in response to recommendation 010/19 (as detailed in paragraph 5.6 of the draft report), we will empower Maritime NZ staff and delegated parties to engage on issues related to single point failure during systems audits, vessel inspections, and other routine engagement. Additionally, at this year's New Zealand Commercial Jet Boating Association (NZCJBA) annual national conference, we will make sure that discussions include issues related to single points of failure. Finally, Maritime NZ is working with the NZCJBA to develop guidance to support operators to identify and reduce risks related to single point failure.

Thank you again for this notification and opportunity to comment. Yours sincerely Peter Brunt Deputy Director, Regulatory Systems Design Maritime New Zealand

7 Key lessons Ngā akoranga matua

- 7.1 When a boat is under the control of a single crew member it is imperative that in the event of them becoming incapacitated there is a system in place to alert rescue services.
- 7.2 It is essential that operators have a robust process in place to identify critical systems and single points of failure that, if defective, can have significant impacts on the safety of the operation.
- 7.3 While the Maritime Rules provide a minimum safety standard, operators are still responsible for identifying and mitigating risks and hazards specific to their own operations and should endeavour to use that process to improve their safety standards over and above the minimum required.

8 Data summary Whakarāpopoto raraunga

Vehicle particulars

	Name:	KJet 8
	Туре:	Aluminium jet boat
	Class:	Commercial
	Limits:	Lake Wakatipu, Shotover River and Kawarau River
	Classification:	MNZ 131144
	Length:	6.5 metres
	Built:	2003
	Propulsion:	Hamilton 212 jet unit
	Service speed:	95 kilometres per hour
	Owner/operator:	Kawarau Jet Service Holdings Limited (KJet)
	Minimum crew:	1
Date and	time	21 March 2021 1200
Location		Shotover River, Queenstown
Persons	involved	One driver and 12 passengers
Injuries		Driver and one passenger airlifted to hospital with head injuries, minor injuries to some of the remaining passengers
Damage		Minor

9 Conduct of the inquiry He tikanga rapunga

- 9.1 On 21 March 2021, MNZ notified the Commission of a jet boat accident occurring on the Shotover River near Queenstown resulting in injuries to some of the persons on board. The Commission subsequently opened an inquiry under section 13(1) of the *Transport Accident Investigation Commission Act 1990* and appointed an Investigator-in-Charge.
- 9.2 On 22 March 2021, a protection order was put in place to protect evidence related to the jet boat.
- 9.3 Also on 22 March 2021, three investigators travelled from Wellington to Queenstown to gather evidence. One returned on 25 March and the other two on 26 March.
- 9.4 On 16 April 2021, Quest Integrity were engaged to assist with identifying the circumstances and causes of the accident.
- 9.5 On 27 April 2021, one investigator and a representative from Quest Integrity travelled to Queenstown to inspect the jet boat and gather evidence and they returned on 28 April.
- 9.6 On 22 February 2022, the Commission approved a draft report for circulation to six interested persons for their comment.

Abbreviations Whakapotonga

MNZ	Maritime New Zealand
SOP	Safe Operational Plan
USA	United States of America



Marinisation environment

the process of modifying an engine to be used in the marine

Appendix 1 MNZ Commercial Jet Boat

Form last updated – 22/01/2020

Part 82: Commercial Jet Boat Operations River Audit checklist (MSF293)

Audit information

Use this form to audit commercial jet boat operations against Maritime Rules Part 82: Commercial Jet Boat Operations – River. The questions in the checklist are a prompt for Maritime Officers carrying out the audit.

Name of Part 82 operation or trading name (as per the certificate)	
Place of audit	
Date of audit	
People in attendance	
Name of vessel(s) attended	
Next audit due	

Time recording

The project code for this audit is _____.

Record the number of hours taken to complete each of the items below.

Planning and preparation	
Audit visit (excluding travel)	
Non-conformity	
Report writing	

Background information

Navigator

For each vessel, review the relevant Navigator tabs as indicated. Check for the name of the authorised person in the visits tab. SOP Checks:

SOP Number:	
Authorised Person / Surveyor:	
Date of Expiry of Certificate:	
Last Audit Date:	
Last AP Visit:	
Other Notes or File M8 entries:	

Triton

Check Triton for any information about the operator and other key personnel.

Were any accidents or incidents reported and any recommendations made? Are there any case files you should look at? Were there any prosecutions?

Is there anything you need to follow up or check when you audit the operation?

Vessel name	Previous visits	Previous inspections	Detentions or imposition of	Accident/ Incidents	Case files	Prosecutions	Comments

Vessel name (continued)	Previous visits	Previous inspections	Detentions or imposition of	Accident/ Incidents	Case files	Prosecutions	Comments

Other Prep Notes

Previous Audit Notes

Non conformities	
HSWA Notices	
HOWA Notices	
Observations	

Opening Meeting

Explain audit process

Discuss any NC's / IOCs / HSWA notices from previous audit - Ensure closed out

Discuss any observations from previous audit - note any improvements

Overview of operation

Operator certification

Requ	uirement	NA	~	OBS	NC
1	Display of certificate (lasts 4 years)				
	(MR 82.23) Each commercial jet boat operator must display a copy of its Comm a form acceptable to the Director, in a prominent position at its normal place of b	ercial Jet ousiness a	Boat Oper t all times.	ator Certif	icate, in

Responsible persons

Requ	uirement	NA	\checkmark	OBS	NC
2	Changes made to responsible persons MR 82 Appendix 1.1				
	Person responsible for the jet boat operation MR 82 Appendix 1.1.4 (a)				
	Person responsible for resourcing the operation MR 82 Appendix 1.1.4 (b)				
	Person responsible for crew training and competency assessments MR 82 Appendix 1.1.4 (c)				
	Person responsible for operational decisions including maintenance and quality assurance MR 82 Appendix 1.1.4 (d)				

Commercial Jet Boating – River operation

Requ	uirement	NA	\checkmark	OBS	NC
3	Operational awareness and resource allocation				
	Discuss how the Responsible person stays aware of operational requirements o have a closed loop reporting system)	f business	s (a larger	operation	might
	Discuss how the operation remains current with industry best practice, law or re-	gulation cl	nanges.		
	Does the operation run cameras on their boats to review driver and vessel beha	viour?	0		

Driver training and competency assessments

Requ	uirement	NA	~	OBS	NC					
4	Driver training programme and training needs									
	 MR 82.27 (2) and MR 82.62 (f) (i). The SOP must describe an adequate driver training programme. Drivers cannot s Should include: Pre-op checks (MR 82 App 1.8) Refuelling (MR 82 App 1.8) Pax screening (MR 82 App 1.9) Safety brief (MR 82 App 1.9) Comms with shore (MR 82 App 1.10) Planned route (MR 82 App 1.1.9) 	self-asses	55.							
5	Driver details									
	MR 82 – Appendix 1.4.1 & 1.4.2 (a – d). Check all current drivers are listed.									
6	Competency and assessment awareness MR 82.27 (3) (a - c) MR 82.68 (Each driver must be competent to drive in a commercial jet boat operation to the extent that the driver is adequately and properly trained, current, and proficient for each area, type of jet boat, and nature of operation in which the driver serves.) • Ask to see training records for drivers • If driver present, Q&A against the planned route in the SOP to demonstrate knowledge.									
7	Training needs									
	How are individual driver's training needs identified? How often are assessments (Refer to the training programme and training records.) What resources are used to train the drivers? (smaller operations might just use have training programmes in place) Are there identified risks specific to this operation that require specific driver train	and refre	esher train , larger op	ing condu perations r	cted? nay					
8	Currency of qualifications									
	MR 82.65 $(1 - 3)$ What procedures are in place to ensure that qualifications (licenses, logs, first aid	d, medical	s) are kep	ot current?	9					

Requ	uiren	nent	NA	~	OBS	NC
9	Sa	mple qualification documents				
	MR •	82 Appendix 1.4.2, MR 82.65 Ask the operator to show you for each driver: New Zealand Commercial Jet Boat Driver (River) Licence (valid for 10 years required under rule 82.27 (3)(b), Driver logbook – verified by operator every 6 months First aid cert Medical cert	s), compe	tency asso	essments	

Operational decisions including the control and scheduling of maintenance and internal quality assurance

Requ	Jirement	NA	~	OBS	NC
10	Maintenance programme				
	 (MR 82, Appendix 1.3.5 (b) Check the contents of the maintenance programme Check the adequacy of the programme Ask the operator if there have been any amendments to the programme. Is the programme being complied with? SOP should cover all critical systems as well as routine maintenance for each systems as well	ch vessel			

Safety equipment and spare parts list

Requ	uirement	NA	~	OBS	NC
11	Safety equipment				
	Checks should be completed on, but not limited to, the following safety equipment fire extinguishing systems, Portable fire extinguishers, Personal flotation devices Towing eye & tow rope.	nt on each , Commur	n jet boat s nications e	ampled: F equipment	Fixed
	Does the operator hold any exemptions?				

Accidents, incidents, mishaps

Requ	uirement	NA	\checkmark	OBS	NC
12	Accident, incident and mishap procedures				
	MR 82 Appendix 1.22 (a) (b) (c) What happens after an incident or accident ie is a driver stood down for cause a Who retests driver?	nalysis / f	urther trair	ning if requ	uired?
13	Notification to MNZ				
	(MTA s31 and HSWA s56 and 57)			<u> </u>	

Harm prevention

Safe operating procedures

Requ	uirement	NA	~	OBS	NC					
14	Operating procedures and programmes									
	MR 82 Appendix 1.7, 1.8, 1.9, 1.10, 1.11, 1.12, 1.13, 1.14, 1.15, 1.16, 1.17, 1.18, 1.19, 1.20, 1.21, 1.22 and 1.23 The SOP should detail the route and identified safe places for Hamilton turns									
15	Managing safety risks									
	MR 82 Appendix 1.20.1 (a – f)									
16	Conditions in which jet boat operation is conducted									
	MR 82, Appendix 1.2.1 – 1.2.3 (Ask to see the maps or plans detailing the environs operated in.)									
	Ask the operator if cargo is carried (check there are procedures for carriage of ca Appendix 1.19)	argo as re	quired by;	(MR 82						
	Check recreational use If multiple rivers are used by the operation, check for separate plans for each rive	er run.								

Emergency preparedness

Requirement		NA	\checkmark	OBS	NC
17	Emergency plans				
	MR 82 Appendix 1.21 The commercial jet boat operator must have an emergence (a) Identifies potential emergencies; and (b) Outlines procedures to minimise the adverse consequences of these events; (c) Includes procedures for – (i) Situation management; and (ii) Call-out; and (iii) Evacuation; and (iv) Identification and allocation of resources; and (v) Notification of police and rescue services (including responsibility for no standardised terminology within the commercial jet boat operation's organi services; and (d) Specifies training and exercises to ensure the effectiveness of the plan and p emergency.	ey plan that and btification sation an prepare er	at – and the us d with poli nployees l	se of ce and re before any	scue /
18	Operating requirements				
	MR 82.28 (a – h) Is the SOP consistent with the operation, is the plan being applied, and continue Part. Check for: amendments, storage, and reviews	s to meet	the requir	ements o	f this

Vessel Checks – (Appendix 2, Part 82)

Vessel name: ______ (attended at the audit)

Requirement		NA	✓	OBS	NC
1	General overall visual condition of vessel				
	MR 82 Appendix 2.1 Check overall condition no obvious defects. Tidy, no sharp or protruding objects that might Ask if there have been any modifications since last survey visit	contact a	passenge	r	
2	Freeboard line present				
	MR 82 Appendix 2.3				
3	Seating				
	MR 82 Appendix 2.4 Secure, backrests, be upholstered, all face forward				
4	Handholds and footrests				
	MR 82 Appendix 2.5 Handholds for all seats, footrests in new boats, except driver				
5	Towing eye				
	MR 82 Appendix 2.6 Must have towing eye on bow Must have 4 m of 12 mm rope attached to a bow eye, but stowed so it cannot foul				
6	Bilge pumps				
	MR 82 Appendix 2.9 Check function if required				
7	Steering gear				
	MR 82 Appendix 2.10 Look for rubbing, look for redundancies, look for D-shackles				
8	Throttle cable				
	Look for redundancies Can stowed equipment interfered with foot pedal or cable?				
9	Portable fire extinguishers				
	MR 82 Appendix 2.15 Minimum of 1 x 2kg CO2 or 1 x 2kg AFFF MR 42B applies				
10	PDFs				
	MR 82 Appendix 2.18				
11	Equipment				
	MR 82 Appendix 2.18 Minimum of 1 x 2kg CO2 or 1 x 2kg AFFF MR 42B applies				

Closing discussion

At the end of the audit, meet with the operator and relevant personnel to discuss the audit findings. These questions are a prompt for the auditor.

Requirement		Y	N	N/A	Comments
1	Are all relevant personnel present?				
2	Have you outlined all the observations and non- conformities as appropriate?				
3	Are there any potential NCs that need to be discussed internally with MNZ or with shore-based management?				
4	If a major NC is issued, have you agreed on the corrective / preventative action to be taken?				
5	Have you explained the process of responding to NCs within 14 days and to action any approved responses between 1 and 3 months?				
6	Does the operation continue to meet the requirements of the SOP, Maritime Rules and Maritime Transport Act?				

Audit completed

Maritime Officer

Kōwhaiwhai - Māori scroll designs

TAIC commissioned its four kōwhaiwhai, Māori scroll designs, from artist Sandy Rodgers (Ngāti Raukawa, Tūwharetoa, MacDougal). Sandy began from thinking of the Commission as a vehicle or vessel for seeking knowledge to understand transport accident tragedies and how to avoid them. A 'waka whai mārama' (i te ara haumaru) is 'a vessel/vehicle in pursuit of understanding'. Waka is a metaphor for the Commission. Mārama (from 'te ao mārama' – the world of light) is for the separation of Rangitāne (Sky Father) and Papatūānuku (Earth Mother) by their son Tāne Māhuta (god of man, forests and everything dwelling within), which brought light and thus awareness to the world. 'Te ara' is 'the path' and 'haumaru' is 'safe' or 'risk free'.

Corporate: Te Ara Haumaru - the safe and risk free path



The eye motif looks to the future, watching the path for obstructions. The encased double koru is the mother and child, symbolising protection, safety and guidance. The triple koru represents the three kete of knowledge that Tāne Māhuta collected from the highest of the heavens to pass their wisdom to humanity. The continual wave is the perpetual line of influence. The succession of humps represents the individual inquiries.

Sandy acknowledges Tāne Māhuta in the creation of this Kōwhaiwhai.

Aviation: Ngā hau e whā - the four winds



To Sandy, 'Ngā hau e whā' (the four winds), commonly used in Te Reo Māori to refer to people coming together from across Aotearoa, was also redolent of the aviation environment. The design represents the sky, cloud, and wind. There is a manu (bird) form representing the aircraft that move through Aotearoa's 'long white cloud'. The letter 'A' is present, standing for a 'Aviation'.

Sandy acknowledges Ranginui (Sky father) and Tāwhirimātea (God of wind) in the creation of this Kōwhaiwhai.

Maritime: Ara wai - waterways



The sections of waves flowing across the design represent the many different 'ara wai' (waterways) that ships sail across. The 'V' shape is a ship's prow and its wake. The letter 'M' is present, standing for 'Maritime.

Sandy acknowledges Tangaroa (God of the sea) in the creation of this Kowhaiwhai.

Rail: rerewhenua - flowing across the land



The design represents the fluid movement of trains across Aotearoa. 'Rere' is to flow or fly. 'Whenua' is the land. The koru forms represent the earth, land and flora that trains pass over and through. The letter 'R' is present, standing for 'Rail'.

Sandy acknowledges Papatūānuku (Earth Mother) and Tāne Mahuta (God of man and forests and everything that dwells within) in the creation of this Kōwhaiwhai.



Recent Maritime Occurrence reports published by the Transport Accident Investigation Commission (most recent at top of list)

MO-2021-203 Collision between fishing vessel 'Commission; and container ship 'Kota Lembah', 84 nautical miles northeast of Tauranga, Bay of Plenty, New Zealand, 28 July 2021 MO-2020-202 Bulk log carrier Funing, Loss of manoeuvrability while leaving port, Port of Tauranga, 6 July 2020 MO-2018-206 Bulk carrier Alam Seri, loss of control and contact with seabed, Port of Bluff, 28 November 2018 MO-2020-201 Collision between bulk carrier Rose Harmony and fishing vessel Leila Jo, Off Lyttelton, 12 January 2020 MO-2019-204 Capsize of water taxi Henerata, Paterson Inlet, Stewart Island/Rakiura, 12 September 2019 Bulk log carrier Coresky OL, Crew fatality during cargo-securing operation, Eastland MO-2019-203 Port, Gisborne, 3 April 2019 MO-2018-205 Fatality on board the factory trawler San Granit, 14 November 2018 MO-2019-202 Fatal jet boat accident, Hollyford River, Southland, 18 March 2019 MO-2019-201 Jet boat Discovery 2, contact with Skippers Canyon wall, 23 February 2019 MO-2018-202 Accommodation fire on board, fishing trawler Dong Won 701, 9 April 2018 MO-2018-203 Grounding of container ship Leda Maersk, Otago Lower Harbour, 10 June 2018 MO-2018-204 Dolphin Seeker, grounding, 27 October 2018 MO-2017-204 Passenger vessel *Seabourn Encore*, breakaway from wharf and collision with bulk cement carrier at Timaru, 12 February 2017 MO-2017-203 Burst nitrogen cylinder causing fatality, passenger cruise ship Emerald Princess, 9 February 2017

Price \$19.00

ISSN 1173-5597 (Print) ISSN 1179-9072 (Online)