



Transport Accident
Investigation
Commission

Final report

Tuhinga whakamutunga

Maritime inquiry MO-2022-201
Charter fishing vessel Enchanter
Capsize
North Cape, New Zealand
20 March 2022

August 2023



The Transport Accident Investigation Commission

Te Kōmihana Tiro tiro Aituā Waka

No repeat accidents – ever!

“The principal purpose of the Commission shall be to determine the circumstances and causes of accidents and incidents with a view to avoiding similar occurrences in the future, rather than to ascribe blame to any person.”

Transport Accident Investigation Commission Act 1990, s4 Purpose

The Transport Accident Investigation Commission is an independent Crown entity and standing commission of inquiry. We investigate selected maritime, aviation and rail accidents and incidents that occur in New Zealand or involve New Zealand-registered aircraft or vessels.

Our investigations are for the purpose of avoiding similar accidents in the future. We determine and analyse contributing factors, explain circumstances and causes, identify safety issues, and make recommendations to improve safety. Our findings cannot be used to pursue criminal, civil or regulatory action.

At the end of every inquiry, we share all relevant knowledge in a final report. We use our information and insight to influence others in the transport sector to improve safety, nationally and internationally.

Commissioners

Chief Commissioner	Jane Meares
Deputy Chief Commissioner	Stephen Davies Howard (recused from this inquiry)
Commissioner	Richard Marchant (until 31 October 2022)
Commissioner	Paula Rose, QSO
Commissioner	Bernadette Roka Arapere (from 1 December 2022)
Commissioner	David Clarke (from 1 December 2022)

Key Commission personnel

Chief Executive	Martin Sawyers
Chief Investigator of Accidents	Naveen Kozhupakalam
Lead Investigator for this inquiry	Jeremy Dann
Commission General Counsel	Cathryn Bridge

Notes about Commission reports

Kōrero tāpiri ki ngā pūrongo o te Kōmihana

Citations and referencing

The citations section of this report lists public documents. Documents unavailable to the public (that is, not discoverable under the Official Information Act 1982) are referenced in footnotes. Information derived from interviews during the Commission's inquiry into the occurrence is used without attribution.

Photographs, diagrams, pictures

The Commission owns the photographs, diagrams and pictures in this report unless otherwise specified.

Verbal probability expressions

For clarity, the Commission uses standardised terminology where possible.

One example of this standardisation is the terminology used to describe the degree of probability (or likelihood) that an event happened, or a condition existed, in support of a hypothesis. The Commission has adopted this terminology from the Intergovernmental Panel on Climate Change and the Australian Transport Safety Bureau models. The Commission chose these models because of their simplicity, usability, and international use. The Commission considers these models reflect its functions. These functions include making findings and issuing recommendations based on a wide range of evidence, whether or not that evidence would be admissible in a court of law.

Terminology	Likelihood	Equivalent terms
Virtually certain	> 99% probability of occurrence	Almost certain
Very likely	> 90% probability	Highly likely, very probable
Likely	> 66% probability	Probable
About as likely as not	33% to 66% probability	More or less likely
Unlikely	< 33% probability	Improbable
Very unlikely	< 10% probability	Highly unlikely
Exceptionally unlikely	< 1% probability	



Figure 1: Fishing charter vessel *Enchanter*
(Credit: Enchanter Fishing Charters Ltd)




Figure 2: Area of capsized as calculated by the Commission

(Credit chart NZ51: Land Information New Zealand)

Contents

Rārangi take

1	Executive summary	1
	What happened.....	1
	Why it happened	1
	What we can learn.....	2
	Who may benefit	2
2	Factual information	3
	Background.....	3
	Narrative.....	3
	Search and rescue	5
	Salvage.....	8
	Meteorological information.....	10
	Vessel information.....	12
	New Zealand search and rescue system.....	13
	Assets	15
	Helicopters.....	15
	Fixed-wing aircraft.....	16
	Vessels.....	16
	RCC asset database.....	16
3	Analysis	17
	Introduction	17
	What happened.....	17
	<i>Location of capsized</i>	22
	Weather and wave theory	24
	Vessel stability and construction	27
	Survivability.....	32
	Life jackets	32
	Life rafts	34
	Lifebuoys	35
	Emergency Position-Indicating Radio Beacon (EPIRB)	37
	Vessel-tracking systems	38
	Search and rescue.....	40
4	Findings	49

5	Safety issues and remedial action	51
	General.....	51
	Safety issues.....	51
6	Recommendations	53
	General.....	53
	Notice of recommendations.....	54
7	Key lessons	55
8	Data summary	56
9	Conduct of the Inquiry	57
	Abbreviations	59
	Glossary	61
Appendix 1	Wave formation and characteristics	63
Appendix 2	The <i>Enchanter's</i> stability information	67
Appendix 3	Maritime Rules Part 40C	70
Appendix 4	Post-salvage inspection	73
Appendix 5	Expert analysis of EPIRB data	75
Appendix 6	Rescue helicopter flight data (TracPlus data)	88

Figures

Figure 1:	Fishing charter vessel <i>Enchanter</i>	iii
Figure 2:	Area of capsiz e as calculated by the Commission	iv
Figure 3:	Annotated part of Chart NZ 23	3
Figure 4:	Search and rescue locations	6
Figure 5:	The <i>Enchanter's</i> hull on the beach at Houhora Heads	9
Figure 6:	Map showing MetService forecast sea areas	10
Figure 7:	Situation weather map for New Zealand valid at about 50 minutes before the accident occurred	11
Figure 8:	Map of the New Zealand search and rescue region	13
Figure 9:	Organisation of the New Zealand search and rescue system	14
Figure 10:	Structure of the New Zealand SAR network and the agencies involved in it	15
Figure 11:	Screenshot from a chart plotter, representing the skipper's intended route around Murimotu Island (taken from another company-owned vessel)	18
Figure 12:	Part of Chart NZ51 showing the track of the EPIRB encoded GNSS positions (green rectangles, representing location area of certainty) and <i>Enchanter's</i> track as estimated by the skipper (red)	21
Figure 13:	Portion of Navionics chart for North Cape showing encoded GPS positions transmitted by the EPIRB marked by key times.	22
Figure 14:	Combined tide and current drift modelling for 20 minutes before the accident (top) and 100 minutes after (bottom), conducted by the RCC during the SAR operation	23

Figure 15: Marked up portion of Navionics chart for North Cape	27
Figure 16: Extract from the Enchanter’s stability manual showing the modelled watertight boundary	28
Figure 17: Representation of a vessel floating on its side with openings near the centreline (not to scale)	29
Figure 18: The inverted flybridge with a rescue swimmer and three survivors sitting atop what had been the ceiling of the main saloon and the floor of the flybridge	30
Figure 19: The Enchanter after salvage	30
Figure 20: Non-SOLAS life raft fitted to the Enchanter	35
Figure 21: The Enchanter’s lifebuoys (top left and right) and a typical compliant lifebuoy (bottom right)	37
Figure 22: EPIRB automatic release sequence	38
Figure 23: Organisation chart showing the relationship between the air ambulance sector and the RCC. (The green arrows represent funding lines.)	42
Figure 24: Coastguard Houhora vessel	48
Figure 25: Significant wave height	64
Figure 26: Changes in orbital characteristics of water when waves transition to shallow water. 65	
Figure 27: Wave changes as waves approach the shore	65
Figure 28: Relationship between buoyancy, weight and centre of gravity	67
Figure 29: GZ curve for the Enchanter, representative of its	68
Figure 30: Sample calculation representing a typical load case for the Enchanter	69
Figure 31: The Enchanter being prepared for towing after raising (top left); being winched up the beach (top right); on the beach after salvage (bottom)	73
Figure 32: The Enchanter showing damage to bow sustained during salvage (top); overview of what had been the main saloon (middle); and detail of failed connection between the hull and superstructure (bottom).	74
Figure 33: Flight data showing helicopter hovering over EPIRB encoded position (green dots) 88	
Figure 34: Close up of helicopter flight path hovering over EPIRB encoded position (green dot).	88

1 Executive summary

Tuhinga whakarāpopoto

What happened

- 1.1 The charter fishing vessel *Enchanter* was on a five-day fishing trip from Mangōnui in Northland to the Three Kings Islands with eight passengers and two crew on board. On 20 March 2022, it was heading back from the Three Kings Islands towards Murimotu Island off North Cape, where the skipper intended to anchor for the night.
- 1.2 At about 1950 the vessel was broadly east of Murimotu Island when it was struck on its port side by a large steep wave, rapidly rolling the vessel onto its side. The superstructure comprising the main saloon and the flybridge separated from the hull and the *Enchanter* capsized.
- 1.3 The New Zealand Rescue Coordination Centre (the RCC) was alerted to the accident by the crew activating their Emergency Position-Indicating Radio Beacon (EPIRB) and initiated a search and rescue response.
- 1.4 Only five of the ten people survived the accident. The survivors were retrieved from the upturned hull and other floating debris by the first rescue helicopter to arrive at the scene. The bodies of the remaining five people were recovered after an almost two-day search and rescue operation involving multiple aircraft and surface vessels.

Why it happened

- 1.5 The *Enchanter* should easily have coped with the sea conditions off North Cape at the time of the accident. However, it is **about as likely as not** the vessel had strayed into shallower water off Murimotu Island, an area that is prone to occasional, naturally occurring, larger waves peaking as they entered the shallowing water.
- 1.6 When the *Enchanter* rapidly rolled onto its side, the force of the water exceeded the design parameters of the vessel's superstructure. This caused the superstructure to separate from the hull, resulting in the *Enchanter* fully capsizing.
- 1.7 Due to the suddenness of the capsize none of the people were wearing or had access to life jackets, and the life rafts **likely** did not automatically deploy, which left those in the water with no or limited means of flotation.
- 1.8 None of the four lifebuoys on board had effective retroreflective tape and only two had a strobe light attached. Add to this the absence of life jackets with their strobe lights and retroreflective markings, it would have been difficult to detect the missing people in the water at night.
- 1.9 There was a significant delay in the search for the five missing people while fuel for the rescue helicopters was sourced. Three of the missing people were alive in the water when last seen by the survivors but were later found deceased.
- 1.10 Although we cannot determine with any certainty whether it would have changed the outcome in this particular situation, the chances of survival after an accident are greater if search and rescue operations are conducted promptly.

What we can learn

- 1.11 For any forecast or actual sea conditions, mariners should at any time expect to encounter occasional waves up to twice the average size.
- 1.12 Mariners should, if possible, avoid navigating in shallow water in adverse wave conditions. If shallow water cannot be avoided, they should be particularly vigilant and expect waves much larger and steeper than those expected in deeper water.
- 1.13 It is important that passengers either practise putting on a life jacket or are given a demonstration of how to do so during a safety briefing, rather than having to work this out under the pressure of an emergency.
- 1.14 Safety will be better served if life jackets are distributed in several places around a vessel where they will be more accessible in a sudden emergency.
- 1.15 Wearing an inflatable life jacket or similar buoyancy aid will enhance the safety of people when fishing from open decks in open and exposed waters.
- 1.16 There is safety benefit in wearing a personal locator beacon as a backup to the EPIRBs required on commercial vessels, in case the circumstances of an accident prevent the use of the latter.
- 1.17 Fitting an Automatic Identification System (AIS) or equivalent tracking device to a vessel will significantly improve the likelihood of being found and reduce the time for being rescued, particularly if the primary life-saving equipment fails or cannot be activated.

Who may benefit

- 1.18 All mariners, maritime regulatory agencies, and agencies and operators involved in search and rescue operations.

2 Factual information

Pārongo pono

Background

2.1 The *Enchanter* was a 16.2-metre charter fishing vessel operated by Enchanter Fishing Charters, primarily out of Mangōnuī in Northland, New Zealand. A group of eight people had booked a five-day fishing charter out of Mangōnuī to the Three Kings Islands, beginning on Thursday 17 March 2022.

Narrative

2.2 The eight people (passengers) arrived on board the *Enchanter* on Wednesday 16 March 2022 and spent the night on board at the berth in Mangōnuī. The next morning 17 March 2022, the skipper gave the passengers a safety briefing, which included the location and operation of the various life-saving apparatus. The passengers were told that all the life jackets were stowed under the bunks in the forward passenger cabin but were not shown what they looked like or how to put them on.

2.3 The *Enchanter* departed Mangōnuī at about 0830 with the skipper, first mate and the eight passengers on board. The *Enchanter* towed fishing lures¹ for the trip to the Three Kings Islands and anchored in Northwest Bay on Great Island for the night (see Figure 3). The weather was fine with light winds.




Figure 3: Annotated part of Chart NZ 23

2.4 On 18 March 2022 the *Enchanter* went to Middlesex Bank to fish for the day and returned to Northwest Bay on Great Island for the night. Again, the weather was fine with light winds.

¹ Hooked objects attached to a fishing line, designed to move and resemble prey.

- 2.5 On 19 March 2022 the *Enchanter* went to King Bank to fish for the day and returned to Little Bear Bay on Great Island for the night. Again, the weather was fine with light winds.
- 2.6 The skipper chose Little Bear Bay on the southwest side of Great Island to shelter from forecast northeast conditions associated with a weather system that was to pass over the area during the night.
- 2.7 The weather system passed through the area as forecast. At about 0600 on 20 March 2022 it was still raining and the winds were strong from the northeast. The *Enchanter* remained at the Little Bear Bay anchorage while the passengers breakfasted and fished in the bay. The weather began to ease, so at about 1030 the *Enchanter* left Little Bear Bay and headed for the Princes Islands about five nautical miles (nm) to the northwest. There they fished in the lee of the islands until 1330, at which time the skipper judged the sea conditions had eased sufficiently to make the journey to North Cape. Their intention was to anchor for the night in the lee of Murimotu Island (see Figure 2).
- 2.8 The weather conditions for the first part of what was to be about a seven-hour trip were described as between two- and three-metre waves with the wind still blowing about 20 knots from the northeast.
- 2.9 By 1700 the weather had cleared, and the sea conditions eased enough for the skipper to allow the passengers to open the side windows to the main saloon. They also deployed the towed fishing lures.
- 2.10 At 1940 the skipper called Far North Radio on the VHF radio and advised of their intention to anchor for the night 'under' Murimotu Island. It was agreed that the skipper would call Far North Radio once the *Enchanter* was anchored, in approximately one hour.
- 2.11 As the *Enchanter* closed with the coastline near North Cape, six of the passengers were relaxing in the saloon, one was asleep in the forward cabin and one was seated on the aft deck monitoring the fishing rods. The first mate was in the galley cooking the evening meal and the skipper was on the flybridge navigating the vessel. The *Enchanter* was being steered by autopilot. During an initial interview the skipper said that they had "just started to turn to get us down" (indicating a change in heading to head more southerly). This was when the vessel was broadly north-northeast of Murimotu Island and before it reached a waypoint² on the chart plotter, which the skipper indicated was broadly east-southeast of Murimotu Island. The skipper later clarified that only one course adjustment of about 10 degrees in a southerly direction had been made on the automatic pilot, and that this was to regain the track to this waypoint.³
- 2.12 The sky was clear, and it was just on dark. At about 1950 the vessel encountered a large steep wave on its port side. The wave rolled the vessel to starboard in an instant. The superstructure and windows on the starboard side were forced into the water and imploded. The vessel continued to roll and capsized. During the capsize sequence the superstructure comprising the main saloon and flybridge separated from the hull. The

² A specified point on a chart for a planned passage

³ The autopilot was not linked to the chart plotter, so it did not automatically follow the tracks on the chart plotter.

hull remained inverted but afloat. The floor of the flybridge (which was the roof of the main saloon below) lay inverted, floating next to the capsized hull.

- 2.13 Seven of the eight passengers and the first mate were either ejected or escaped from the vessel into the water. The passenger who was sleeping in the forward cabin was trapped there. The skipper was able to escape from the inverted flybridge.
- 2.14 Within minutes of the accident, the first mate climbed on top of the inverted hull and made a headcount. Including the first mate, nine people had survived the initial capsizing. Two (the skipper and one passenger) had climbed on top of the inverted flybridge, the first mate and two passengers were on the inverted hull, and four passengers were in the water. One of those four in the water had retrieved a lifebuoy, which they had placed over their head and under their armpits.
- 2.15 Within minutes the first mate noticed another of the four passengers in the water floating face down. The first mate entered the water and attempted revival while swimming the passenger to the inverted flybridge. Despite the combined efforts of those on the inverted flybridge, the passenger remained unresponsive. Sometime later the body drifted away from the flybridge despite attempts to secure it to the flybridge.
- 2.16 Sometime before 2017, the *Enchanter's* Emergency Position-Indicating Radio Beacon (EPIRB)⁴ surfaced next to the skipper. The EPIRB had been secured in a float-free bracket on the deck at the back of the flybridge (now underneath the inverted flybridge floor). The EPIRB was designed to float free from its bracket when submerged and automatically activate. However, the EPIRB had not activated so it was manually activated and tied to the inverted flybridge.
- 2.17 Meanwhile the inverted hull and flybridge had drifted apart. At that time the situation was:
 - two passengers were on the inverted hull (2)
 - the skipper, first mate and one passenger were on the inverted flybridge (3)
 - three passengers were last seen alive in the water, one with a lifebuoy (3)
 - one passenger was assumed deceased and in the water (1)
 - one passenger was unaccounted for. (1)

Search and rescue

- 2.18 At 2017 the New Zealand Rescue Coordination Centre (the RCC) received an initial beacon alert from the *Enchanter's* EPIRB, indicating a distress off North Cape. Using the registration details for the EPIRB the RCC contacted the *Enchanter's* shore base and established that the *Enchanter* was operating near North Cape. At about 2020 the RCC received the first encoded⁵ transmission from the EPIRB, which included global positioning system (GPS) coordinates.
- 2.19 At 2030 the RCC directed the Marine Operations Centre to issue mayday relays on VHF Channel 16, requesting all vessels in the vicinity to aid in the response. There were no vessels in the immediate area at that time.

⁴ An Emergency Position-Indicating Radio Beacon (EPIRB) is designed to transmit its location and verification data to a rescue coordination centre and thus alert search and rescue authorities that an emergency exists.

⁵ See Appendix 5 for a detailed description of the data obtained from the EPIRB.

2.20 At about 2035 the RCC briefed the Coastguard New Zealand (Coastguard) Duty Officer, who was based in Auckland. Coastguard's northernmost unit, Coastguard Houhora, was then tasked to respond. The RCC also tasked⁶ the Northland Emergency Services Trust (NEST)⁷ helicopter crew based in Whangarei. The NEST crew gave an estimated time to departure of 20–30 minutes.



Figure 4: Search and rescue locations

2.21 At 2109 Coastguard advised the RCC that, having conducted a risk assessment, they would not be able to respond at night due to the limitations of their vessel and the severity of the weather forecast. They also believed that there would be no air support in the area until the weather abated. At 2110 NEST advised the RCC there would be a delay while they assembled the appropriate helicopter crew. NEST also requested the RCC to task another helicopter from the Auckland Rescue Helicopter Trust (ARHT) to assist with the response, which the RCC completed at approximately 2200.

2.22 At 2205 the NEST helicopter departed from Whangarei. NEST maintained a fuel trailer at Kaitia Hospital.⁸ As this was the most northerly point where fuel would be available, both helicopter crews planned to land and refuel from the trailer to maximise their time on scene at North Cape (see Figure 4).

2.23 At 2250 the NEST helicopter arrived at Kaitia Hospital to refuel and at 2313 departed Kaitia, heading for the position coordinates transmitted by the *Enchanter's* EPIRB. Meanwhile the ARHT helicopter departed from Ardmore Aerodrome in Auckland at 2252. The NEST helicopter arrived on scene at about 2340 and immediately detected

⁶ Assigned as an asset to be used for the SAR event.

⁷ Northland Emergency Services Trust and Auckland Rescue Helicopter Trust had at the time merged to become one company, Northern Rescue Helicopter Limited (NRHL). However, they were still in the process of aligning the two previous entities operationally. For the purposes of this report, we have retained their original names for clarity of the narrative.

⁸ About 95 per cent of their work was in relation to air ambulance services.

two light sources. The first was a strobe light in the water. However, it was not attached to anything.

- 2.24 The second light source was from the vessel's EPIRB attached to the inverted flybridge, to which the skipper, first mate and one passenger were clinging. The helicopter crew conducted a risk assessment and then lowered a rescue swimmer to the water. The three survivors were then winched on board one-by-one, accompanied by the rescue swimmer.
- 2.25 By now, New Zealand Police (NZ Police) had been briefed and had set up a forward command post at Te Hapua, the closest point to the search area with road access. At 0013 the NEST helicopter departed the scene and flew the three rescued survivors to Te Hapua, where they were transferred to ambulance staff. While in flight the helicopter crew learned from the survivors that: two people were last seen sitting on the inverted hull; three were in the water; one was in the water (but likely deceased); and one was unaccounted for (but was likely trapped in the inverted hull).
- 2.26 The NEST helicopter returned immediately to the scene to resume the search. They detected another light source that proved to be from the two passengers on the inverted hull. One of the passengers had used the light from a mobile phone to attract their attention. They had earlier tried to make an emergency 111 call but were unsuccessful because of poor mobile coverage in the area. In a similar fashion to the first retrieval the two passengers were retrieved by 0108. The helicopter crew decided to fly these two survivors directly to Kaitaia Hospital as the helicopter was running low on fuel.
- 2.27 Meanwhile, the ARHT helicopter had stopped at North Shore Aerodrome to pick up a more experienced winch operator, then at Dargaville to top up with fuel, and again at Kaitaia Hospital to top up with fuel from the NEST trailer before heading to the scene. The two helicopters passed each other in flight and exchanged information.
- 2.28 The NEST helicopter landed at Kaitaia Hospital and transferred the two passengers to medical staff. The helicopter crew then refuelled from the fuel trailer. However, there was not enough fuel remaining to return to the scene, so that helicopter remained at Kaitaia Hospital.
- 2.29 The ARHT helicopter arrived on scene at 0130 to begin the search for the five missing people. Meanwhile, the RCC had also tasked a Royal New Zealand Airforce P3 Orion aeroplane (P3) to assist in the search. The P3 arrived on scene at about the same time as the ARHT helicopter. The RCC assigned the P3 as on-scene coordinator⁹ circling at a higher altitude. The helicopter searched at a lower level in the dark for about an hour and 20 minutes before it too ran low on fuel and landed at the Te Hapua forward command post at 0257.
- 2.30 Meanwhile, a fuel tanker had been sourced at Kerikeri and was sent northwards, arriving at Kaitaia Hospital at 0511. The NEST helicopter was refuelled, but by then the helicopter crew had exceeded the limits of their work/rest operational hours, thus preventing them from rejoining the search effort. The fuel tanker then travelled north to Te Hapua forward command post, arriving there at about 0700. The ARHT helicopter refuelled and departed for the search area again at 0733. For 4 hours and 36 minutes there were no helicopter air assets able to search because no fuel was available.

⁹ Coordinator of all search and rescue assets at the scene. The RCC still retained responsibility for overall coordination of the search.

- 2.31 Meanwhile, several vessels had responded to the mayday relay calls. Another of the operator's fishing charter vessels *Pacific Invader* had departed Mangōnui and arrived at the search area at 0400. A commercial fishing vessel *Florence Nightingale*, which had been out at the Three Kings Islands at the time of the accident, arrived soon after 0400. Another commercial fishing vessel *Katrina* arrived at the search area at about 0612. All three vessels were coordinated into a search pattern or directed to items of interest by the P3 circling above.
- 2.32 At about 0710 (first light) the body of one of the passengers was located and recovered by one of the surface search vessels. When the refuelled ARHT helicopter had returned on scene, it took over as the on-scene coordinator from the P3, which was by then getting low on fuel. The bodies of another two passengers were recovered over the next 40 minutes, leaving two people still missing.
- 2.33 Meanwhile, preparing for an extended search operation, the RCC had tasked a second rescue helicopter from AHRT. This second helicopter arrived at the forward command post at 0907 and relieved the first helicopter.
- 2.34 When the mayday relays had been broadcast, the inshore patrol vessel *HMNZS Taupo* had been operating in the Hauraki Gulf. It diverted to the search area, arriving on scene at 1110. The RCC assigned *HMNZS Taupo* with the role of on-scene coordinator, tasked with ensuring all marine assets were searching the designated areas assigned by the RCC. However, the *HMNZS Taupo* misunderstood the meaning of on-scene coordinator and assumed the naval warfare role of on-scene command, effectively taking control of the search away from RCC.
- 2.35 Over the following hours multiple assets joined the search including Coastguard Houhora, two other commercial helicopters from Kerikeri and another P3.
- 2.36 At 1319 the body of a fourth passenger was located and recovered, leaving one passenger still missing. By 1527 the RCC had realised that air assets were not following their assigned search patterns. *HMNZS Taupo* had directed all assets to search another area, based on their own drift-modelling calculations. After some discussion with *HMNZS Taupo*, the RCC took back control of the search area.
- 2.37 Meanwhile the RCC had tasked the NZ Police Dive Squad to fly up from Wellington to dive on the hull in anticipation of locating the final missing passenger. The Dive Squad arrived in the area by 1953 and prepared to dive at first light the following morning, 22 March 2022.
- 2.38 By 2020 all assets on site had been stood down for the evening. *HMNZS Taupo* had marked the hull by attaching a rope with a white buoy earlier in the afternoon. The P3 recorded the GPS coordinates of the hull before leaving the scene.
- 2.39 However, the following morning the inverted hull could not be located. A helicopter was tasked with searching for the upturned hull. At 1239 the hull was located and the vessel with the NZ Police Dive Squad on board was directed to that location. The body of the last missing passenger was recovered from the hull at 1654, marking the end of the search and rescue task.

Salvage

- 2.40 In the days after the completion of the search and rescue task, the inverted hull of the *Enchanter* was taken under tow, as it was considered a danger to surface navigation.

However, as soon as the tow began, the hull rolled back upright and then sank in about 24 metres water depth.

- 2.41 The tow vessel then attempted to drag the hull across the seabed into deeper water.¹⁰ However, the manoeuvre was unsuccessful and, according to divers who were on board the tow vessel, the hull sustained significant damage when it was dragged into an underwater rocky outcrop. Survivors and search and rescue personnel described the bottom of the hull as being undamaged before it sank.
- 2.42 On 31 March 2022, the sunken hull was raised to the surface and towed to a private launching ramp just inside the entrance to Houhora Harbour. The hull was grounded in the mud at high water. When the tide receded, the hull was winched through the mud to a point where the Commission was able to conduct a thorough inspection. (See Figure 5 and Appendix 4 for photographs taken during this inspection.)



Figure 5: The *Enchanter*'s hull on the beach at Houhora Heads

- 2.43 Neither the flybridge from which three survivors were rescued nor any of the structure that formed the main saloon and supported the flybridge was recovered.
- 2.44 The suite of navigation equipment located on the flybridge was also lost. A second GPS located in the skipper's cabin was retrieved. Despite having been submerged in salt water for several days, the Commission was able to extract data from the memory chip. However, the GPS was an older model, so the data was encrypted in a format that yielded no useful track coordinates.

¹⁰ The wreck was considered to be at a depth where it would be a hazard to recreational divers.

Meteorological information

2.45 The location of the accident off North Cape lay between two MetService forecast sea areas. The Three Kings Islands lay within the Kaipara forecast area and the destination anchorage behind Murimotu Island lay just within the Brett forecast sea area (see Figure 6).



Figure 6: Map showing MetService forecast sea areas
(Source: MetService)

- 2.46 On the day of the accident the weather situation consisted of a low-pressure system, which was lying in the Tasman Sea to the west of North Island extending a series of fronts across Northland. There was a strong northeast flow ahead of these fronts (see Figure 7).
- 2.47 The forecast for the sea area Kaipara issued by MetService at 2248 on 19 March 2022 (the evening before the accident) was:

Sunday 20 March 2022

Northeast 25 knots, rising to 35 knots this morning, changing northerly 15 knots north of Kaipara Harbour this evening. Sea becoming very rough, easing in the north. Long period southwest swell 2 metres developing. Northeast swell rising to 2 metres in the north. Poor visibility in scattered rain, with possible thunderstorms.

Monday 21 March 2022

Becoming northerly 10 knots everywhere early, rising to 20 knots offshore late. Very rough sea in the south easing. Moderate southwest swell easing. Moderate northeast swell in the north.

2.48 The forecast for the sea area Brett issued by MetService at 2248 on 19 March 2022 (the evening before the accident) was:

Sunday 20 March 2022

Northeast 25 knots, rising to 30 knots early afternoon. Sea becoming very rough.
Northeast swell rising to 2 metres. Poor visibility in rain with possible thunderstorms from afternoon.

Monday 21 March 2022

Becoming northerly 10 knots early. Very rough sea easing. Moderate northeast swell.




Figure 7: Situation weather map for New Zealand valid at about 50 minutes before the accident occurred

(Source: MetService)

- 2.49 The skipper had access to the MetService information, but primarily relied on the PredictWind subscription weather service, specifically the Global Forecast System (GFS).¹¹ The skipper frequently monitored these resources and concluded that the weather forecast was suitable for the fishing charter trip to proceed.
- 2.50 The skipper had previously discussed the weather forecast with the charter group organiser. They acknowledged the frontal system that was predicted to pass over Northland over-night on Saturday 19 March 2022 with associated strong winds and rain. They agreed they had various options available should the predicted adverse weather eventuate.
- 2.51 The weather conditions for the first three days of the trip were as predicted: fine weather with low swell and little wind. The skipper frequently monitored the weather forecast as the trip progressed and kept the passengers well informed. On Saturday 19 March 2022 the skipper noted that the cold front associated with the low pressure in the Tasman Sea was still predicted to pass the Three Kings Islands from the

¹¹ A USA-based National Center for Environmental Prediction weather forecast model that generates data for, among others, wind. The system couples four separate models (atmosphere, ocean, land/soil and sea ice) to work together and predict global weather conditions.

northwest early on the morning of Sunday 20 March 2022. The skipper adjusted the plan. The *Enchanter* remained in the sheltered anchorage until mid-morning and then, as the front was still passing, they travelled to and fished in the lee of the Princes Islands.

- 2.52 By 1330 the weather had cleared, the wind had backed¹² to approximately north-northeast¹³ direction and dropped to 15 to 20 knots. The *Enchanter* left the Princes Islands for the six-hour trip to North Cape, essentially following the weather system that had passed through.
- 2.53 There are no wave-recording devices located in the sea area around North Cape and the Three Kings Islands. The survivors' estimates of the wave conditions for the trip back were reasonably consistent: about 2.5 metres average at the start and easing to about 1.5 metres average as the *Enchanter* progressed towards North Cape. (See Appendix 1 for a description of wave formation and characteristics.)
- 2.54 The seawater temperature round the North Cape area was about 22 degrees Celsius.

Vessel information

- 2.55 In 1981 the *Enchanter* was designed initially as a 14.2-metre motorsailer but before it was built the owner altered the design to a Class X commercial fishing vessel. The *Enchanter* was built as such in 1982. The vessel was built using fibreglass over double-diagonal kauri plank with a single-deck superstructure built in marine plywood (no flybridge).
- 2.56 In 1984 the *Enchanter* was modified to be a passenger vessel, and it is thought that a semi-open flybridge was added on top of the main saloon at that time.¹⁴
- 2.57 In 1993 the vessel was lengthened by two metres at the stern. The *Enchanter* was purchased by the current owner in 2004.¹⁵
- 2.58 In 2009 the vessel was resurveyed to allow it to operate further from the coast, within Coastal¹⁶ and Restricted Offshore¹⁷ Limits. The flybridge was enclosed with glass windows and the helm station in the main saloon was removed, leaving the only control console located on the flybridge.
- 2.59 The *Enchanter* had sleeping quarters for eight people in the cabin below and forward of the main saloon and for two crew in a cabin behind and below the main saloon.
- 2.60 Propulsion was by twin diesel engines giving a service speed of about eight knots.

¹² The wind direction changed or trended anticlockwise.

¹³ Blowing from about 25 degrees.

¹⁴ Records were hard copy at that time and not always complete.

¹⁵ Initially the vessel was purchased by the current owner as part of a partnership, before forming a company.

¹⁶ Maritime Rules Part 20 Operating Limits, Section 20.2(a) Coastal Limits [50 nautical miles off the coastline].

¹⁷ Maritime Rules Part 20 Operating Limits, Section 20.2(a) Offshore Limits [outside Coastal Limits out to 200 nautical miles off the coastline but restricted by the surveyor in this case to 100 nautical miles]

New Zealand search and rescue system

2.61 New Zealand is responsible for one of the largest search and rescue (SAR) regions in the world, covering over 30 million square kilometres (see Figure 8).



Figure 8: Map of the New Zealand search and rescue region

2.62 The coordination of SAR operations for the region is divided into two categories. Category I SAR operations are coordinated by NZ Police at a local level, covering searches within New Zealand on land, inland waterways and close-to-shore marine operations. Category II SAR operations are coordinated at a national level by the RCC. These operations typically involve missing aircraft, aircraft in distress and offshore marine operations within New Zealand's SAR region.

2.63 The New Zealand Search and Rescue Council (NZSAR Council) and the NZSAR Secretariat provide strategic oversight and governance for the SAR sector. The NZSAR Council comprises leaders from the Ministry of Transport, the Civil Aviation Authority, Fire and Emergency New Zealand, Maritime New Zealand, New Zealand Defence Force, NZ Police, Department of Conservation, as well as an independent member.

2.64 The NZSAR Secretariat provides the NZSAR Council with advice and support services, as well as providing leadership to the sector by implementing measures to promote strategic coordination (see Figure 9).




Figure 9: Organisation of the New Zealand search and rescue system

(Source: NZSAR Council)

2.65 SAR coordinators are provided by NZ Police or the RCC depending on the category of the SAR operation. They can task several types of assets provided by several agencies and private operators. These include helicopters, fixed-wing aircraft, vessels, land vehicles and people. The majority of SAR personnel are volunteers. According to the NZSAR Annual Report 2021 the sector consists of 11,561 personnel, of which 91 per cent are volunteers (see Figure 10).




Figure 10: Structure of the New Zealand SAR network and the agencies involved in it
(Source: NZSAR Council)

Assets

Helicopters

- 2.66 For SAR operations, NZSAR coordinators can task helicopters from the New Zealand Defence Force, NZ Police and civilian operators.
- 2.67 The initial responding helicopters tasked by the RCC to search for the *Enchanter* were medical service helicopters provided by NEST and ARHT. The helicopters are civilian operated and have operational agreements with the National Ambulance Sector Office (NASO) to serve as regional air ambulances.
- 2.68 For operators to maintain their NASO agreement, they must meet the criteria outlined in the NZ Aeromedical and Air Rescue Standard. This document was created by NASO to enforce standardisation of aircraft, equipment and training among the different civilian operators to better serve the health sector.
- 2.69 To better serve New Zealand, the NASO agreement allows for air ambulances to be used for the purposes of search and rescue when they are not being used for medical purposes.
- 2.70 Other civilian operators may also be tasked for search and rescue operations depending on the needs of the operation and availability of aircraft. These assets may

be lacking some of the equipment and/or personnel that come with a NASO aircraft, such as not being winch capable and/or not having paramedics onboard.

New Zealand Defence Force and NZ Police

- 2.71 The RNZAF's No. 3 Squadron is equipped with a fleet of eight NH-90 helicopters based at RNZAF Base Ohakea, Manawatu. The No. 3 Squadron always has one aircraft and crew on 24-hour standby and can be airborne within two hours of notification.
- 2.72 NZ Police operate the Eagle fleet of three Bell 429 helicopters all based out of Auckland. They are used for a variety of NZ Police operations including search and rescue. However, their uses are limited by not being winch capable.

Fixed-wing aircraft

- 2.73 The RNZAF maintained a fleet of P-3K2 Orion aircraft (No. 5 Squadron), and C-130 Hercules aircraft (No. 40 Squadron) both of which were long-range aircraft.¹⁸ These large aircraft were essential in providing coverage for New Zealand's broad search and rescue region extending from Antarctica to several Pacific islands. One aircraft was on 24-hour standby and could be airborne within two hours of notification.
- 2.74 Coastguard New Zealand operates two small Cessna 182 aircraft, which are crewed by volunteers. These aircraft provide a visual search platform and are based in Auckland (Ardmore) and Northland (Kerikeri).

Vessels

- 2.75 Coastguard New Zealand is a volunteer-based charity comprising 58¹⁹ units serving communities around the country. Coastguard New Zealand operate 107 vessels, the size and type of which varies between locations, but the average size is between 9 and 10 metres in length.
- 2.76 The Royal New Zealand Navy (RNZN) maintains one vessel on 24-hour standby, which can be deployed within 12 hours of notification.
- 2.77 NZ Police are equipped with two purpose-built response vessels, to aid in a variety of police work including search and rescue operations and NZ Police diver support. The vessels are crewed by police specially trained in maritime operations, are located in Auckland and Wellington and can be deployed on 24 hour's notice.

RCC asset database

- 2.78 The RCC maintains a countrywide database of all assets and their capabilities, which they use to make efficient decisions when tasking assets to SAR operations throughout the region.

¹⁸ At the time of publication of this report the P3-K2 had been replaced by the P-8A, a more modern similar-sized jet aircraft suited for long-range SAR operations.

¹⁹ At the time of the accident.

3 Analysis

Tātaritanga

Introduction

- 3.1 The *Enchanter's* hull was well-constructed and in an apparent good state of repair. There is no evidence of any mechanical or equipment failure that could have contributed to the accident.
- 3.2 Although earlier on the day of the accident the sea conditions in the area had been adverse, the skipper had planned to seek shelter when required and judged the timing of the return trip to North Cape to coincide with the forecast and observed easing of the wind and sea conditions. The general sea conditions in the area off North Cape at the time of the accident should normally have been well within the capabilities of the vessel.
- 3.3 The *Enchanter* was knocked down by a wave, resulting in the destruction of its main cabin and flybridge, and total capsizing. The accident was initially survived by nine of the ten people on board, yet five people tragically died.
- 3.4 The following section analyses the circumstances surrounding the accident to identify those factors that increased the likelihood of the event occurring. It also discusses factors that increased the severity of the outcome, such as the suitability and performance of survival equipment and the efficiency of the subsequent search and rescue response.
- 3.5 Other non-contributory safety issues that have the potential to adversely affect future operations are also discussed.

What happened

- 3.6 By the time the *Enchanter* was approaching North Cape the sea conditions there had moderated with the passing of a cold front over the area from the north. The wind had eased and backed²⁰ towards the north. The sea conditions had eased to an estimated 1.5 to 2.0 metre waves.
- 3.7 Almost three hours before the accident the sky had cleared, and sea conditions had eased sufficiently for the skipper to allow passengers to move around and open the side windows in the main cabin. The lures were also deployed around this time.
- 3.8 The *Enchanter* was on automatic pilot for the trip to North Cape. The skipper was navigating from the flybridge, where the only helm and control console were located. The skipper was using a chart plotter²¹ to navigate. The chart plotter ran a 'Time Zero' charting software program²². In addition, the standalone radar and depth sounder were running. The skipper told the Commission there was a planned route displayed on the chart plotter from their departure point at the Princes Islands to the intended anchorage behind Murimotu Island via a series of waypoints,²³ that, if followed, would have taken the *Enchanter* around Murimotu Island in deep water. The skipper

²⁰ A backing wind is a shift of wind direction in an anti-clockwise manner, for example from north to west.

²¹ A chart plotter is a navigational device that uses electronic charts to display navigational information.

²² 'Time Zero' is a manufacturer of navigation software.

²³ Specified points on a chart for a planned passage.

described one of these waypoints (the 'turn waypoint') as being about 1.4 nautical miles off Murimotu Island (about 0.8 nautical miles outside the 10 metre depth contour), where the skipper intended to begin taking the *Enchanter* south. (See Figure 11 for a screenshot representing the skipper's planned track, taken from another company-owned vessel.) The skipper said they were adjusting the autopilot to broadly follow this track. If the track was followed, they would have kept the vessel in about 50 metres water depth as the *Enchanter* closed with the coastline and reached the turn waypoint.²⁴ The skipper was aware that it was risky to pass too close to the coastline when sea conditions were adverse, particularly when the waves were from the northeast quarter.

- 3.9 In their interview, the skipper indicated that before reaching the turn waypoint, they had begun adjusting the autopilot to change course to "head down" (indicating to head south). The skipper later clarified that only one adjustment had been made on the autopilot to the south and that was to bring the *Enchanter* back on track to the turn waypoint. The skipper said that it was not their intention to begin altering course to round Murimotu Island until after the *Enchanter* had reached the turn waypoint. The skipper placed the location of the capsized at a point north-northeast of Murimotu Island, where the *Enchanter* was still on its planned route and before it reached the turn waypoint.




Figure 11: Screenshot from a chart plotter, representing the skipper's intended route around Murimotu Island (taken from another company-owned vessel)

(Credit: Skipper)

- 3.10 In the period leading up to the capsized, the skipper had briefly walked to the rear of the flybridge to check on the trawls and then returned to the helm where the chart plotter was located. The skipper was seated there for an undetermined period. It was while seated there that the skipper noticed, in the fading light, the "wall of water" about to meet with the vessel from the port side. The time of the accident was

²⁴ As the GPS was not recovered, its exact coordinates are not known. The location of the planned waypoint was derived from the skipper's description on the chart during interview.

approximately 1950, which was when the first mate had just looked at a mobile phone to view a text message.

- 3.11 The Commission was not able to establish an accurate track for the *Enchanter* leading up to the accident. The main GPS and chart plotter were in the separated flybridge structure, which was not recovered. The Globalstar spot-tracking device that had been installed by the owner had a habit of dropping offline. It did not transmit position reports for most of the trip from the Princes Islands to North Cape, except for five occasions, the last two of which were at 1806 and 1906 (about 43 minutes before the accident).
- 3.12 The second GPS unit retrieved from the skipper's cabin during the salvage of the hull revealed no location data.
- 3.13 The skipper advised the Commission that the accident happened north-northeast of the awash rock near Murimotu Island in about 50 metres depth of water. This was based on the skipper's perception of where the vessel was, the observations of water depth using the echosounder, that they could see the gap between the mainland and Murimotu Island before and after the capsizing, and the estimated time of arrival at the anchorage.
- 3.14 The Commission has reached a different conclusion from the skipper as to the location of the accident. The Commission bases its view on an analysis of the EPIRB data, and drift modelling conducted by the RCC (*refer to paragraphs 3.23 and 3.24*).
- 3.15 The Commission acknowledges that the skipper and first mate recall seeing the gap between Murimotu island and the mainland both before and after the accident. These recollections could give a broad indication of orientation; however, they do not give an indication of distance from the land. The profile of the gap between the island and mainland (the outline in the fading light) would be visible across a broad area including the Commission's calculated area of capsizing (*see Figure 12*), but that profile would alter when viewed from different locations as the flybridge drifted north.

The EPIRB data

- 3.16 The Commission engaged an expert in EPIRB data analysis and functionality to explain the various forms of location data that the *Enchanter's* EPIRB transmitted. See Appendix 5 for the expert report containing a detailed description of the EPIRB data.
- 3.17 The location data received at the RCC from the EPIRB was a combination of three data sources: firstly, medium-altitude earth orbiting search and rescue (MEOSAR) satellite data; secondly, the encoded Global Navigation Satellite System (GNSS) location data from the internal GPS; and thirdly, location data from an internal AIS, all transmitted directly from the EPIRB. The MEOSAR data is based on satellites receiving the generic 406/121.5-megahertz signal transmitted by the EPIRB. This signal will provide an initial alert to an EPIRB activation followed by an initial location, but its accuracy is limited. The accuracy of the MEOSAR location improves with time and the number of satellites passing overhead. For GPS-enabled EPIRBs (such as the one installed on the *Enchanter*) an internal GPS provides an encoded position that is transmitted to the satellite, providing RCC with an accurate location of the EPIRB to within an area of certainty of plus or minus two seconds of latitude and longitude. This means the GNSS coordinates provided identify a central position within a rectangle measuring 123 metres north to south, and 102 metres east to west. The EPIRB can be located anywhere within the rectangle at the time of transmission. This area of certainty is demonstrated in

Figure 12 where each encoded position is centred within a green rectangle. Approximately 30 minutes after capsizing, the first encoded GNSS GPS position transmitted by the EPIRB placed the *Enchanter's* flybridge within 620 metres (inclusive of the area of certainty) of Murimotu Island at position S34 24.864', E173 03.534'. The estimated area of capsizing provided by the skipper was approximately 0.91-1.0 nautical miles east-northeast of this position (see Figure 12).

- 3.18 After the EPIRB had surfaced, the first mate made several attempts to manually activate the EPIRB in the dark, before successfully activating it between 2015 and 2016.²⁵ After it was activated, it was tied to the floating flybridge. The RCC received the first MEOSAR beacon alert at 2017 and the first transmission of the beacon's encoded GPS position at 2020. In Figure 12 the green track shows the encoded positions of the EPIRB, and thus the location and drift direction of the flybridge, which the skipper, first mate and one passenger were sitting atop.
- 3.19 The accuracy of the encoded GPS positions transmitted by the EPIRB is also confirmed by comparing it with the TracPlus flight data²⁶ from the first responding rescue helicopter. During the initial rescue of the three surviving passengers on top of the flybridge, the flight data shows the rescue helicopter hovering in close vicinity to the encoded position transmitted by the EPIRB at the same time.
- 3.20 Rescue helicopters are equipped with a homing device that helps locate an activated EPIRB in the event the position is not known. On the evening of 20 March 2022, the NEST rescue helicopter crew did not use their homing device. They flew to the flybridge using the encoded GPS position transmitted by the EPIRB, which was provided to them by RCC, and visually identified the EPIRB by its flashing strobe light. This demonstrates that the encoded GPS position transmitted by the EPIRB was accurate, as it led the helicopter directly to the scene.
- 3.21 The red dotted line in Figure 12 represents the skipper's estimate of the *Enchanter's* track and the red shaded area represents the area where the skipper estimated the accident occurred.
- 3.22 Figure 13 is an enlarged portion of Figure 12, showing the individual times and GPS positions for successive EPIRB encoded GNSS transmissions to the RCC. Figure 13 uses a chart from the Navionics charting software,²⁷ which shows depth contours in more detail.

²⁵ Time of activation is based on data received by the RCC. According to the EPIRB manufacturer, an EPIRB is expected to transmit at approximately 50 seconds after activation.

²⁶ The TracPlus flight data is included in Appendix 6.

²⁷ Navionics product-SonarChart™ collects sonar log data recorded from users operating in the area to keep charts updated.




Figure 12: Part of Chart NZ51 showing the track of the EPIRB encoded GNSS positions (green rectangles, representing location area of certainty) and *Enchanter's* track as estimated by the skipper (red)




Figure 13: Portion of Navionics chart for North Cape showing encoded GPS positions transmitted by the EPIRB marked by key times.

Location of capsiz

- 3.23 During the SAR operation the RCC was using drift-modelling software to help coordinate the search effort to the most likely area.²⁸ The drift modelling calculated the net drift to be northward at the time and the location of the accident, mainly influenced by the tide. High water at North Cape occurred at 2234. With the pending change in tide, by 2130 (70 minutes after the EPIRB activation) the calculated drift pattern turned to become easterly (see Figure 14).
- 3.24 Objects in the water will drift in different directions depending on their characteristics. A lightweight object floating on the surface is more likely to be influenced by the wind and surface wave action, whereas objects floating deeper in the water will more likely be influenced by the tide and current. This phenomenon was observed during the SAR operation. The hull of the upturned vessel drifted more in a southerly direction. What is thought to have been a strobe light attached to a lifebuoy appeared to the survivors, relative to their own drift rate, to be drifting closer to the shoreline under the influence of the wind. The drift rate of the mostly submerged flybridge was accurately tracked by the EPIRB that was attached to it. The RCC drift modelling is consistent with the observed track of the EPIRB once it had been activated, which was initially northward and then turned east.
- 3.25 Using the encoded positions transmitted by the EPIRB, the initial drift of the flybridge was northward at about 0.14 knots. Taking into consideration the encoded positions area of certainty, as shown by the green rectangles in Figure 12, the EPIRB's rate of drift was between about 0.06 to 0.17 knots.

²⁸ The current data is obtained via an Environmental Data Server (based at the RPS group in Australia) that receives data from various sources globally. The data shown in this model was sourced from MetOceans Solutions and incorporates the MetOcean drift current forecasting with an underlying RPS tidal model. It is the most accurate hydrodynamic current model available for coastal New Zealand within the SARMAP system.




Figure 14: Combined tide and current drift modelling for 20 minutes before the accident (top) and 100 minutes after (bottom), conducted by the RCC during the SAR operation

- 3.26 When considering all the factors that could affect the drift of the flybridge, the Commission concluded it was **about as likely as not** that its rate and direction of drift after the EPIRB had been activated was similar to the 30 minutes prior to the EPIRB being activated (noting the EPIRB was attached to the flybridge). Therefore, it is **about as likely as not** that the location of the capsized vessel would have been within an area about 0.07 nautical miles (about 130 metres) south of the first encoded position, as shown in Figure 12.
- 3.27 Both the first GNSS position transmitted by the EPIRB and this calculated area of capsized vessel were within the 10 metre depth contour as shown in Figure 13.
- 3.28 These shallower water depths correlate more closely with the description of the wave that caused the *Enchanter* to capsize. This is discussed in more detail in the following section on weather and wave theory.

- 3.29 As stated previously, the skipper's estimate of capsizing location is approximately 0.91 to 1 nautical mile from where the EPIRB was activated. While this scenario was considered, the mostly submerged flybridge would need to have travelled that distance in 30 minutes, being driven by the current at an average rate of 1.8 to 2 knots in an opposing direction to the drift modelling provided by the RCC as well as the drift of the EPIRB post activation. The Commission considers this **unlikely** given the local conditions at the time of the accident.
- 3.30 The skipper's estimated location of capsizing is in a similar location to where the flybridge was located by the NEST rescue helicopter using the EPIRB's encoded position, four hours later. For the skipper's capsizing location to be correct, there would have had to have either been little to no drift in the four-hour period between the capsizing and rescue, or the direction of drift would have had to reverse after the EPIRB was activated, taking the flybridge back out to where the skipper estimated the capsizing occurred. Neither hypothesis is consistent with the RCC drift modelling, which broadly correlated with the observed track of the EPIRB after it had been activated.
- 3.31 Weather systems can affect local conditions such as the direction and velocity of surface currents. The underwater topography can add a level of complexity to the various tides and currents if near shore. These factors add an element of uncertainty to any backdrift analysis. Reliable data sources recording such local conditions at North Cape do not exist. Therefore, to determine the approximate drift rate of the flybridge after EPIRB activation and the area of capsizing, the Commission has used time and distance calculations based on the only reliable data available, the EPIRB transmissions, as these transmissions most accurately reflect the approximate drift rate of the flybridge after EPIRB activation.
- 3.32 Given the distance between the position of the EPIRB activation and the estimated capsizing position provided by the skipper, the storm system would have needed to produce a current in excess of 2 knots opposing the predicted northern tidal flow, which is not supported by the initial drift pattern of the EPIRB.
- 3.33 The Commission has not been able to establish the reason for the disparity between where the skipper estimated the capsizing happened in deep water, and where the encoded EPIRB data indicates the capsizing occurred inshore in shallower water.

Weather and wave theory

- 3.34 The forecast for the sea area Brett (see Figure 6) for Sunday 20 March 2022 was for rough seas and a northeast swell rising to 2 metres ahead of a frontal weather system passing over the area from the North. The only actual recordings of the sea state in the general area were from two waverider buoys²⁹. One was a wave spotter buoy³⁰ which had been drifting above North Cape from 17 to 24 March 2022. The other was a Northland Regional Council waverider buoy located off the Puruerua Peninsular near the Bay of Islands, some 70 nautical miles southeast of North Cape and some 120 nautical miles southeast of the Three Kings Islands. The data from the Northland Regional Council waverider buoy is considered more representative of the general conditions off Murimotu Island as it was not affected by the weather pattern off the west coast of North Island.

²⁹ Scientific buoys used to record weather conditions at sea level.

³⁰ A drifting waverider buoy.

- 3.35 On the day of the accident the wave spotter buoy had generally drifted in a westerly direction. At 1420 the buoy was located approximately 15 nautical miles northwest of Murimotu Island, recording a peak significant wave height³¹ of 4.2 metres with a period³² of about 8 seconds. By 1910 the buoy had drifted west to within 3 nautical miles of Cape Reinga recording significant wave heights of 3.2 metres, broadly demonstrating that conditions had started to ease during the *Enchanter's* voyage to North Cape.
- 3.36 The Northland Regional Council waverider buoy recorded a peak in significant combined (wind and swell) wave height of about 4 metres with an average period of 7 seconds³³ between 1300 and 1400 on the day of the accident. The maximum recorded wave height for the same period was about 6 metres. These peaks coincide with the passing of the same frontal system that had passed over the Three Kings Islands earlier that morning. They also coincided with the time that the *Enchanter* departed the Three Kings Islands. By 2000 (about the time of the accident) the significant wave height off the Bay of Islands had fallen to 2.7 metres, with a maximum wave height of 4.3 metres. The wave height at North Cape had likely decreased more, being 70 nautical miles further northwest of the weather system.
- 3.37 Observers noted the presence of a smaller secondary swell coming from a southeast direction (head-on to the *Enchanter's* direction). This secondary swell was considered much smaller than the main waves coming from the northeast sector. Waves from different directions can combine to form larger peaks and troughs.
- 3.38 Survivors from the *Enchanter* estimated the main wave heights were in the range of 1.5 to 2 metres³⁴ off North Cape at the time of the accident. These estimates broadly correlate with the wave heights recorded off the Bay of Islands as the frontal system moved further south and the winds eased.
- 3.39 For a significant wave height of 2 metres in deep water, mariners can expect at least one in every 3,000 waves (or 3 every 24 hours) to reach 4 metres, twice the significant wave height (see Appendix 1 for more detail on wave formation and characteristics). In deep water a wave of this size should not pose a threat to a vessel of the *Enchanter's* size, construction and stability.
- 3.40 The amount of energy a wave possesses is representative of its height and length. If a wave enters shallow water, its wavelength³⁵ decreases with a consequential increase in height while maintaining the same energy. When waves reach water depths less than half of their wavelength, they interact with the seabed, causing them to slow, rise and steepen (referred to as peaking). The waves eventually break as the water depth decreases further to about 1/20th of its wavelength.
- 3.41 Therefore, waves with a longer wavelength will interact with the seabed earlier, than those with a shorter wavelength. Within a spectrum the waves will vary in height and length and thus energy. The average period of the waves recorded on the waverider buoy was about 7 seconds. For normal deep-water waves with a 7-second period their wavelength is calculated to be about 76 metres. Such waves would begin to interact

³¹ The average wave height, from trough to crest, of the highest one-third of the measured or observed waves.

³² The time it takes two successive wave crests to pass a specified point.

³³ The wave period created by this weather system, in deep water, is unlikely to change significantly over the 70 nautical miles between the waverider buoy and the accident area.

³⁴ These observations are likely based on what they were seeing, rather than a significant wave height.

³⁵ The distance from the trough in front of the wave and the trough behind the wave.

with the seabed and start to peak at a depth of 38 metres. The shallower the water gets, the more they will peak until they begin to break at a water depth of about 4 metres.

- 3.42 Only one survivor saw the wave approaching and was able to give a detailed description of the wave that capsized the *Enchanter*. That survivor was a passenger sitting out on the aft fishing deck observing the trawling lures at the time. That passenger described seeing a 'larger wave' approaching from the port side from the same direction as the prevailing swell. This wave's form did not initially cause concern, but then as the wave neared the vessel it appeared to rise into a near-vertical wall. This observation is consistent with a wave peaking as it enters shallow water.
- 3.43 The underwater topography off Murimotu Island matches the wave performance observed by the passenger. From seaward, the seabed off Murimotu Island slopes steeply from 50 to 10 metres water depth over 0.7 nautical miles (1300 metres). The seabed slopes very steeply from 30 to 2 metres water depth (see Figure 15). To the observer on the *Enchanter's* aft deck a larger wave would have begun visibly peaking in the distance, with a sharp rise when the wave met with the 10-metre contour.
- 3.44 This analysis of the wave form supports the hypothesis founded on the EPIRB data, that the capsize occurred much closer inshore and in shallower water than estimated by the skipper.
- 3.45 Consideration was given by the Commission to whether the formation of what has been referred to as a 'rogue wave' was a factor in the capsize. In recent decades scientists have accepted the concept of rogue waves. The United States National Oceanic and Atmospheric Administration refers to rogue waves as those that are large, unexpected and dangerous; are nominally greater than twice the significant wave height; are very unpredictable; and often come from directions other than the prevailing wind and waves.³⁶ Because these waves are uncommon, measurement and analysis of this phenomenon is rare.³⁷
- 3.46 As mentioned above, a wave within the spectrum of the significant wave height present off North Cape could, in less than 10 metre water depth, cause the capsize and damage that occurred to the *Enchanter*. So too would an even larger wave. Therefore, determining whether the wave that capsized the *Enchanter* was within or higher than the spectrum of significant wave height in the area is of little relevance because either could have caused the vessel to capsize in less than 10 metre water depth.
- 3.47 Regardless of where and how the vessel capsized, this accident raises significant safety issues about preparing for and increasing chances of surviving such an accident. We discuss these safety issues in the following sections.

³⁶ <https://oceanservice.noaa.gov/facts/roguewaves.html>

³⁷ Appendix 1 contains further information relating to rogue waves.




Figure 15: Marked up portion of Navionics chart for North Cape

Vessel stability and construction

3.48 When a vessel is knocked down by a wave and capsizes, its stability and construction are factors to consider. The *Enchanter* was resurveyed for restricted offshore limits in 2009. Then it underwent an inclining experiment³⁸ and stability assessment to ensure it complied with the requirements of Maritime Rules Part 40C (Rules Part 40C)³⁹. The *Enchanter's* stability characteristics well exceeded the minimum requirements of Rules Part 40C. However, compliance with Rules Part 40C is no guarantee against a vessel capsizing. The *Enchanter's* stability manual included the following warning to the master:

Safety Information – Compliance with stability and freeboard criteria required under Maritime Rule[s] 40C does not ensure avoidance of capsizing regardless of the circumstances. It is the master's responsibility to execute prudence and good seamanship with due regard to weather forecasts, navigation zone, speed, headings, load distribution and watertight integrity, so the vessel is operating in the safest mode possible against the prevailing conditions at all times.

3.49 The stability analysis process involved modelling the form of the hull's watertight boundary and calculating certain criteria for comparison with those required under Rules Part 40C. The watertight boundary included the spaces below the *Enchanter's* main deck and the raised foredeck (see Figure 16). It did not include the superstructure, comprising the main saloon, galley and flybridge.

³⁸ A process that involves causing a vessel to heel to small angles by moving known weights transversely to determine its stability, lightship weight and the coordinates of its centre of gravity.

³⁹ Maritime Rules Part 40C – Design, Construction and Equipment – Non-passenger Ships that are not SOLAS Ships -Section 1, 13(1)




Figure 16: Extract from the *Enchanter's* stability manual showing the modelled watertight boundary

- 3.50 The modelled boundary was not watertight in the true sense of the word. Inside the main saloon there were openings leading to the sleeping quarters under the foredeck, the engine room, and the crew's accommodation aft, all of which would allow down-flooding⁴⁰ to occur should water enter the main saloon or, as in this instance, if the entire superstructure was lost when the vessel was knocked down.
- 3.51 The naval architect conducting the stability analysis explained that the basis for considering the hull as watertight was that these openings would remain above the waterline when the vessel was heeled to its maximum angle before losing positive stability. The three main openings through which down-flooding could occur were all located around the centreline of the vessel and were calculated to be well above the waterline if the vessel were floating on its side (see Figure 17).
- 3.52 Statical stability is the ability of a vessel to return upright after removal of an external factor which caused the vessel to heel (in static or calm water). The *Enchanter*, when loaded as it typically would be nearing the end of a voyage, could heel over to an angle of about 77 degrees before it lost positive stability (often referred to as the point of vanishing stability). At this point the risk of capsizing would be high, based on statical stability.⁴¹ However, a vessel's ability to return upright when heeled by wind and/or waves at large angles of heel is not linear – it changes as the vessel progressively rolls. Therefore, a vessel's dynamic stability is also assessed as part of the stability analysis. Dynamic stability in this context is the vessel's overall resistance to being pushed over in response to waves and reaching that point of vanishing stability (see Appendix 2 for more detail on stability).
- 3.53 A vessel with low dynamic stability is easily rolled past the point where it loses stability. A vessel with high dynamic stability will take a lot more wave energy to reach that point. The *Enchanter* had relatively high dynamic stability, easily exceeding the minimum requirements of Rules Part 40C.

⁴⁰ The entry of seawater through any opening into the hull of an undamaged vessel.

⁴¹ If the vessel were very slowly pushed over to 77 degrees.




Figure 17: Representation of a vessel floating on its side with openings near the centreline (not to scale)

- 3.54 From the survivors' accounts the *Enchanter's* final roll to starboard was rapid. The wave that struck the vessel had sufficient energy to roll the vessel immediately on to its side with sufficient force to implode the windows and structure forming the main saloon. Wave energy of this magnitude is generated as much from the wave's steepness and profile as its size.
- 3.55 The *Enchanter's* superstructure appears to have offered little resistance to the capsizing energy of the wave. Within seconds the entire superstructure separated from the hull. This allowed water to down-flood into the 'watertight' hull through the internal openings, thus contributing to the total capsizing.
- 3.56 The flybridge separated from what had been the supporting structure beneath it – the four bulkheads⁴² of the main saloon including all windows. The flybridge was discovered floating upside down close to the capsized hull. It was this structure that three of the survivors climbed onto, from which they were later rescued (see Figure 18).

⁴² Nautical term for a wall



Figure 18: The inverted flybridge with a rescue swimmer and three survivors sitting atop what had been the ceiling of the main saloon and the floor of the flybridge

(Credit: Northland Emergency Services Trust)

3.57 Post-salvage inspection confirmed that the separation of the superstructure from the hull was not because of poor maintenance. The timber around this connection was in good condition and the method of connection was generally in accordance with the standards of wooden boat building for the era of build. The wooden material had failed from simple overload. Figure 19 shows the *Enchanter* after it had been salvaged. Note the total absence of the main superstructure (see Appendix 4 for details of the post-salvage inspection.)



Figure 19: The Enchanter after salvage

3.58 We now consider whether the outcome would have been different if the superstructure had been strong enough to withstand the initial knock down by the wave. If the superstructure had remained intact, it is **about as likely as not** that the vessel would not have capsized immediately. With the vessel floating on its side, part of the

superstructure would have provided buoyancy and thus contributed to the dynamic stability of the vessel (see Figure 17). It is not possible to say definitively whether it would still have eventually capsized. That would depend on whether the vessel righted itself with successive waves and what openings there were in the superstructure to allow seawater to invade the saloon space – for example, open windows and the main rear door.

- 3.59 Nine of the ten people on board escaped to the water alive. It is **likely** that the person trapped in the forward sleeping quarters would have had a better chance of survival if the superstructure had remained intact. If the vessel had remained floating upright or on its side, the chance of survivors having access to the various life-saving aids would have been significantly improved. Three people who were known to have survived the initial capsize were later found deceased. Survivability was **likely** affected by swim failure. Having access to life jackets or a life raft would have reduced the onset of swim failure.
- 3.60 It would not be practicable to require superstructures on all vessels be able to withstand the vessel being knocked down by a wave. A vessel is built to a certain specification for a particular purpose. Its intended purpose will determine its design and what standards it must meet, if any. Some are built as recreational vessels, in which case their design is often specified by the owner. Some are built to a standard hull design, but the superstructure and fitout is varied at the owner's request. Others (for example, a tug) are designed for a specific purpose.
- 3.61 Vessels often change ownership several times during their life and consequently their purpose often changes. Commercial vessels are required to be surveyed. If their purpose changes, they must undergo a survey to determine whether they are fit for their new intended purpose.
- 3.62 The variation in vessel design and purpose is therefore infinite. It would not be practicable to have one standard applicable to all vessels.
- 3.63 The *Enchanter's* purpose changed several times over the life of the vessel. Each time it was resurveyed and deemed fit for that purpose. The *Enchanter* was originally built for a private owner to a standard Haag design and method of construction. It was initially designed as a motorsailer, then a Class IV launch, and ultimately was built as a Class X fishing vessel.⁴³ Two years later in 1984 it was modified to carry passengers. Nine years later in 1993 the *Enchanter* was lengthened by two metres. It changed ownership several times (exactly how many is undetermined). It was in commercial operation as a charter sport-fishing vessel when the current owner purchased the vessel in 2004. Under its current ownership it was resurveyed, enabling it to operate further offshore. The changes required to achieve these new limits – an upgrade to the equipment to be carried and a stability assessment – mainly related to how far from assistance it could be if an incident occurred.
- 3.64 Charter sport-fishing vessels are not required to withstand a knock down or capsize but are required to have adequate stability to reduce the likelihood of such an occurrence. Ocean-going yachts on the other hand are usually designed with minimal superstructure which is stronger and can easily be made watertight as they are more susceptible to being knocked down by wind alone. The *Enchanter* had been repurposed to accommodate passengers on multi-day fishing charters. Its survival

⁴³ These classifications refer to the standards applicable at that time

relied on its inherent stability and being operated at appropriate times and places, in suitable weather conditions and in an appropriate manner, as emphasised by the note to masters in the vessel's stability manual.

- 3.65 In that context, the skipper had taken shelter until the adverse weather system had passed over the area. The residual sea conditions for the trip from the Three Kings Islands to North Cape should have been within the *Enchanter's* capabilities. However, the vessel's stability and structural resilience would have been tested under the prevailing conditions if operated in shallower waters where steep breaking waves were more likely to occur and capsize the vessel.
- 3.66 Under similar circumstances a more modern vessel of the same design and built from contemporary materials would be less likely to suffer the same degree of destruction. However, that does not assume the *Enchanter* was not fit for its intended purpose, provided it was operated in accordance with its Marine Transport Operators Plan. A vessel's survival is never reliant on the quality of its design and build alone, nor only on the way it is operated. It will always be a combination of both.

Survivability

Safety Issue: Maritime New Zealand's system for auditing and assessing the performance of accredited vessel surveyors is not ensuring they are interpreting and applying maritime rules correctly when surveying vessels.

- 3.67 The *Enchanter* carried on board a variety of life-saving apparatus for the purpose of reducing the consequences of an accident by improving survivability. The purpose of each apparatus falls into three broad categories:
1. to aid in people's survival if they are required to abandon the vessel or the vessel is lost through a catastrophic event
 2. to alert potential responders to the event
 3. to assist responders in locating and rescuing the people.
- 3.68 The *Enchanter* was required to meet the standards set out in Rules Part 40C for non-passenger vessels that do not have to comply with SOLAS⁴⁴ standards. Appendix 3 of Rules Part 40C outlines the required standards for life-saving equipment onboard.

Life jackets

Safety Issue: New Zealand maritime rules do not adequately address the need for proper stowage of life jackets on board passenger vessels so that passengers have access to a life jacket in the event of a sudden catastrophic event.

- 3.69 Regardless of what other life-saving apparatus is carried on board, people will inevitably spend time in the water if a vessel is lost or abandoned. Life jackets⁴⁵ are fundamental to survival in the water. As well as providing flotation, the type of life jacket provided on the *Enchanter* was designed to aid detection by searchers through their bright orange colour, reflective tape, whistle and a self-activating light. Life jackets

⁴⁴ International Maritime Organization (IMO) standards for vessels that undertake international voyages (The IMO Convention for Safety of Life at Sea)

⁴⁵ Various referred to as buoyancy aids, life preservers and personal flotation devices, depending on their type and use.

reduce the onset of swim failure by supporting the person in the water. They also slow any onset of hypothermia by allowing the wearer to 'huddle' instead of swimming, thereby reducing the loss of body heat.

- 3.70 The *Enchanter* had life jackets on board for 30 people⁴⁶. All 30 life jackets were stowed under the bunks in the forward passenger cabin. When the sudden capsizing occurred nobody had time to access the life jackets. Consequently, none of the nine people who initially survived the capsizing was wearing a life jacket.
- 3.71 Of the five people who lost their lives, one is thought to have died almost immediately in the cabin and another soon after entering the water. For the remaining three it is not possible to determine how long they survived before succumbing. One chanced on a lifebuoy and was later found deceased still wearing it. Little is known about the remaining two. All passengers and crew sustained injuries of some degree during the initial knock down and escape from the hull. Some of the injuries to those who lost their lives would have hampered their ability to swim. Some had pre-existing medical conditions that could also have hampered their ability to survive unassisted in the water. Both factors likely contributed to earlier swim failure, something a life jacket would have helped to prevent.
- 3.72 Standard offshore life jackets are bulky. Storage on board smaller vessels capable of carrying many people is problematic. However, operators should make all efforts to spread the life jackets across several locations to increase the likelihood of people accessing them when needed. On the *Enchanter*, no more than 10 people could be carried on coastal and offshore trips. Ten life jackets could have been stowed in more accessible locations around the vessel. This would have been a reasonable way to manage the foreseeable risk of a sudden event. The Commission has made a **recommendation** to the Director of Maritime New Zealand to address this safety issue.
- 3.73 Having access to a life jacket is important; so too is being able to put it on quickly in an emergency. The *Enchanter's* passengers were told the location of the life jackets during a safety briefing before departing Mangōnui. However, they were not shown what one looked like and did not practise putting one on. The method of putting on and securing life jackets differs between types and manufacturers and not everyone is familiar with the practice. In an emergency and in the dark is not the time to be acquiring these skills. Although there was no opportunity to access life jackets on this occasion, there may well be under different circumstances, particularly if they are made more readily accessible. Skippers ensuring that passengers are familiar with and practised at putting on a life jacket is a key **safety lesson** arising from this inquiry.
- 3.74 Not directly relevant to this accident, but important nevertheless, is the issue of when people should wear a life jacket or other personal flotation devices. Under normal circumstances it wouldn't be considered necessary to wear one when occupying the internal spaces of a vessel of the *Enchanter's* size and construction.
- 3.75 However, it is evident that on these coastal and offshore charters, fishing for large species occurs on the open deck when conditions are not calm. The risk of someone falling overboard deserves consideration. SOLAS life jackets would not be suitable for this type of activity due to their bulk and the risk of them becoming damaged. However, fully compliant inflatable life jackets are available that would not compromise

⁴⁶ The vessel was approved to carry 28 passengers when operating within Inshore Limits.

the activity. On the *Enchanter* there was no requirement to wear a life jacket of any sort when on the open deck, and none were supplied by the skipper. Lifebuoys were available on either side of the *Enchanter* to throw to someone who may have fallen overboard. However, these take time to deploy and there is no guarantee that they will reach a non-swimmer in the water in time, particularly if the vessel is trawling at the time. While not a maritime rule requirement, skippers should consider having and enforcing a policy that covers when passengers must wear a life jacket and should make them available.

Life rafts

- 3.76 Life rafts too are important for survival. They offer a more effective solution than life jackets, particularly in situations where the time before rescue may be longer. Life rafts offer a sheltered haven free from immersion in water, all but negating the risk of swim failure and hypothermia.
- 3.77 It is uncertain what happened to the *Enchanter's* life rafts. They were not recovered and there is no evidence of them having deployed. There were two life rafts secured by a hydrostatic release⁴⁷ to the aft deck of the flybridge. The deck of the flybridge was the platform to which three of the survivors were clinging when rescued. This flybridge structure was also not recovered.
- 3.78 The hydrostatic release is designed to activate and release the life rafts if they reach a water depth of between 1.5 and 4 metres. If the vessel were to sink, the life rafts would release, float to the surface and inflate. However, the flybridge broke free from the hull and remained afloat. It is feasible that the life rafts never reached water depths of more than 1.5 metres during the capsize sequence and thus remained attached to the underside of the platform that the survivors were clinging to. If that was the case the survivors could have, in hindsight, reached under and manually released the life rafts.
- 3.79 Because the vessel was classed to operate in Coastal and Restricted Offshore limits, maritime rules⁴⁸ required that the two life rafts on board the *Enchanter* be SOLAS-type rafts. However, survey records show that both life rafts were of the non-SOLAS type (see Figure 20). This non-compliance had gone undetected by successive surveyors for several years. Although not directly relevant to this accident (because the life rafts were never deployed), the non-compliance is of concern. The difference between SOLAS and non-SOLAS life rafts relates mainly to the way they are constructed, the amount of insulation from temperature extremes the rafts must provide, and equipment available for longer-range SAR assets to detect the raft.
- 3.80 The Commission has made a **recommendation** to the Director of Maritime New Zealand to implement a formal system of notifying surveyors of current and emerging changes to maritime rules for the construction, maintenance and surveying of vessels, and provide clarification where needed of the intent and application of maritime rules.

⁴⁷ A pressure-activated mechanism designed to automatically deploy a life raft when certain conditions are met.

⁴⁸ Maritime Rules Part 42A-Safety Equipment – Life Saving Appliances




Figure 20: Non-SOLAS life raft fitted to the Enchanter
 (Source: 2020 survey records)

Lifebuys

- 3.81 Like life jackets, lifebuys serve two purposes: they provide flotation and aid detection by searchers through their bright orange colour, retro-reflective⁴⁹ tape and, in some cases, a self-activating light. They should be fitted with a grabline to aid retrieval and to facilitate support for more than one person. Some are fitted with a buoyant line to enable them to be secured to other floating items or to enable someone to be pulled towards a vessel in the case of a person overboard.
- 3.82 The *Enchanter* was equipped with four lifebuys. One was located either side of the flybridge, and the other two on top of the flybridge roof (see Figure 21).
- 3.83 According to Appendix 3 of Rules Part 40C,⁵⁰ all four were required to be fitted with a grabline. Two were required to be fitted with a self-igniting strobe light and two with an additional length of buoyant line.
- 3.84 Section 52(2) of Rules Part 40C requires all life-saving appliances to meet the performance standards prescribed in Maritime Rules Part 42A (Rules Part 42A)⁵¹. Section 4 of Rules Part 42A – General requirements for life-saving appliances states that any life-saving appliance must meet the requirements set out in paragraphs 1.2.2.1 to 1.2.2.8 and paragraph 1.2.2.10 of section 1.2 of the International Life-Saving Appliance Code⁵². Section 1.2.2.7 required all life-saving appliances be fitted with retro-reflective tape where it will assist in detection and in accordance with the recommendations of the IMO.

⁴⁹ Reflects light back to its source instead of reflecting away in another direction.

⁵⁰ Maritime Rules Part 40C, Appendix 3, Section 3.2 – Lifebuys

⁵¹ Maritime Rules Part 42A: Safety Equipment – Life-Saving Appliances – Performance, Maintenance and Servicing.

⁵² Code adopted by the Maritime Safety Committee of the International Maritime Organization in Resolution MSC.48(66)

- 3.85 All four lifebuoys on the *Enchanter* were therefore required to be fitted with retro-reflective tape.
- 3.86 The two lifebuoys fitted either side of the flybridge had self-igniting strobe lights and all four had additional buoyant lines. However, possibly only one was fitted with a grab line, two did not have retro-reflective tape and two had the remnants of retro-reflective tape that was so deteriorated as to be ineffective.⁵³ As with the non-compliant life rafts, these non-compliances had gone undetected by successive surveyors for several years. While this omission alone cannot be considered evidence of a wider issue with the standard of surveying, the Commission has made a **recommendation** to Maritime New Zealand to ensure it has an adequate system for monitoring the standards of marine surveying. Retro-reflective tape is an important feature of life-saving equipment. It aids in the detection of survival equipment and people in water, particularly at night.
- 3.87 Shortly after the *Enchanter* capsized, survivors noted one of the passengers in the water with a lifebuoy. The passenger had placed the lifebuoy over their head and under their arm pits. After the five survivors had been rescued from atop the hull and flybridge, the second helicopter on scene searched the area in the dark without success for an hour and 25 minutes until it ran short of fuel and returned to the forward command post. The same passenger was found shortly after sunrise when, after refueling, the helicopter resumed on task 4.7 hours later. The passenger was found deceased but still in the lifebuoy.
- 3.88 Rescue personnel who recovered the passenger from the lifebuoy noted its poor condition, having no retro-reflective tape. The air crew commented on how retro-reflective tape stands out "like a beacon" when using night-vision goggles, even without direct contact from a search light.
- 3.89 It cannot be said for certain that the people in the water would have been detected during the helicopter night search before they succumbed. However, their chances of detection would have been significantly better had the various life-saving apparatus been available and been appropriately fitted with the required light sources and retro-reflective tape.

⁵³ Source – survey records and video from search and rescue aircraft.




Figure 21: The Enchanter’s lifebuoys (top left and right) and a typical compliant lifebuoy (bottom right)

(Source: 2020 survey records)

Emergency Position-Indicating Radio Beacon (EPIRB)

- 3.90 An EPIRB is critical for quickly and accurately alerting authorities to an emergency situation. They come in a variety of sizes and forms. There were two EPIRBs on the *Enchanter*. The main unit was required to be float-free and automatically activate if submerged. It was an upgrade requirement when the *Enchanter* was resurveyed for limited offshore operations. The owner had kept the original EPIRB on board as a backup to the main one. This older unit was stowed on a bracket in the main saloon. It was not of the float-free type and had to be manually activated. This backup EPIRB was lost together with the debris of the main saloon.
- 3.91 The main EPIRB was the unit that fortuitously surfaced next to the skipper soon after escaping the inverted flybridge. It had been stored in its float-free enclosure next to the float-free life rafts at the rear of the flybridge. Like the life rafts it was designed to release from its enclosure and float to the surface when submerged to a depth between 1.5 and 4 metres (see Figure 22).
- 3.92 The life rafts did not float free, but the EPIRB did. However, after it had floated free, the EPIRB did not activate automatically as designed. The EPIRB manufacturer was unable to explain why it did not automatically activate, other than the possibility of a fault in the switching mechanism. They report that they had no record of the switch having

failed previously. Once the EPIRB was manually switched on it performed as designed. The fact that it did not automatically activate is of concern. Had it not surfaced right next to the skipper, it may never have activated, which would have significantly delayed the start of the search and rescue response.




Figure 22: EPIRB automatic release sequence

(Source: McMurdo EPIRB user manual)

- 3.93 The failure of the EPIRB to automatically activate highlights the importance of having multiple means of raising the alarm and for authorities to have access to a vessel's track history if it is reported overdue. As said, EPIRBs come in a variety of types and sizes. Personal locator beacons can provide a useful backup to other alerting systems. They are relatively inexpensive and small enough to fit in a pocket. While not as robust as the larger commercial type-approved EPIRBs, they may well save lives following a rapid and catastrophic event in which the commercial systems prove ineffective in the circumstances, such as the *Enchanter* accident ([safety lesson](#)).

Vessel-tracking systems

Safety issue: *There is no requirement for commercial vessels that carry passengers to be fitted with any form of tracking device such as an automatic identification system (AIS) or other commercially available tracking systems.*

- 3.94 The owner of *Enchanter* Fishing Charters had installed the Globalstar spot-tracking device on all three of its vessels. The system was primarily to allow the owner/skipper's partner at the shore base to track where the three vessels were. The system worked most of the time, but the transmitter unit on the *Enchanter* did drop offline from time to time and required resetting. Consequently, the system was of little use to the RCC when coordinating the search and rescue. Had the main EPIRB been lost and not manually activated by the survivors, the *Enchanter's* plight may not have been truly understood for several hours. It would have taken longer for a search and rescue effort to begin based only on the *Enchanter's* missed check call with Far North Radio.

- 3.95 An AIS uses transponders to transmit real-time data about a vessel's identity, position and movement, either directly from the vessel to another VHF transceiver or via satellite. This data is recorded and can be retrieved by the RCC to help establish a vessel's position and status or, as in this case, the last known position.
- 3.96 The system was initially introduced worldwide to assist in collision avoidance but its worth as a search and rescue tool and a marine traffic control system was soon realised and these have become its primary uses over time. Currently, only international SOLAS ships and certain classes of domestic ships are required to be fitted with AIS. Currently, vessels such as the *Enchanter* are not required to have it fitted.
- 3.97 In the Commission's view there is significant benefit in requiring certain classes (like passenger-carrying vessels) to be fitted with AIS. The safety benefits are likely to far outweigh the minimal cost. Using the *Enchanter* case as an example, if an EPIRB had not been activated and the system was reliant on an overdue check call to raise the alarm, retrieving the AIS data for the *Enchanter* (had one been fitted) would have led searchers directly to where the signal was lost, which would be where the capsizing occurred.
- 3.98 In 2015 the Commission published the *Technologies to Track and to Locate* watchlist item,⁵⁴ in which the Commission suggested that transport regulators encourage and, where reasonable, require operators of transport vehicles to use tracking and location technologies.
- 3.99 In the maritime context the watchlist item draws on two fatal maritime accidents, the circumstances of which are not too dissimilar to the *Enchanter* accident,⁵⁵ In both cases the consequences of each accident could have been reduced had tracking technologies such as an EPIRB or AIS been available. No recommendations were made in either of these reports to mandate the installation of AIS on these small commercial vessels because having it would not necessarily alert authorities that an accident had occurred.
- 3.100 However, we now recognise the potential benefit of AIS as a SAR tool to guide searchers directly to the scene (as an EPIRB would when activated), particularly with the increased use of satellite-based AIS and the much broader coverage around the coast that it affords. AIS units have also become much smaller and cheaper to install. They are increasingly being installed on smaller commercial and recreational craft.
- 3.101 The Commission has made a **recommendation** to the Director of Maritime New Zealand to mandate the installation of AIS on certain categories of vessels, with a focus on those that present a higher risk – those that carry passengers outside inshore limits.

⁵⁴ TAIC, Watchlist, Technologies to track and locate, first published January 2015, last updated October 2021

⁵⁵ Maritime Inquiry MO-2006-204, Fishing Vessel *Kotuku*, Capsized, Foveaux Strait, 13 May 2006 (six fatalities) and Maritime Inquiry MO-2012-201, Fishing Vessel *Easy Rider*, Capsize and Foundering. Foveaux Strait, 15 March 2012

Search and rescue

Safety Issue: *New Zealand does not have readily available and suitable resources that can be assigned to search and rescue operations in the following operational areas:*

- *helicopters that are fully equipped and crewed for extended SAR operations across New Zealand and its coastal waters*
- *medium-range fixed-wing aircraft designed, equipped and crewed for SAR operations across New Zealand coastal waters and the exclusive economic zone (EEZ)*
- *vessels that are designed, equipped and manned by crew practised at conducting SAR operations out to offshore limits.*

Safety Issue: *There is currently no dedicated programme that requires organisations that operate SAR assets and might routinely be assigned on-scene coordinator status to engage in joint training with the RCC to ensure consistency in knowledge of the SAR framework and terminology.*

3.102 It is generally accepted that no two SAR operations are the same, making it difficult to follow a single standard SAR procedure. Consequently, there are almost always new lessons arising out of every SAR operation that can be applied to continuously improve future SAR operations. The following analysis should be read in that context.

3.103 In New Zealand, coordinating SAR events is made more difficult because there are few readily available air and surface assets fit for extended SAR operations, particularly for remote areas. There is also a shortage of people trained to common standards to crew those assets.

3.104 If these two issues were remedied, then SAR operations could be streamlined, more efficient and therefore more effective. There may be opportunities to do so if synergies between potential multiple-user agencies were to be explored. We discuss this in relation to each sector in the following section. First though, there needs to be an acknowledgement of the RCC's performance in managing the challenging *Enchanter* SAR operation and that of the various participating parties. Whilst there are some lessons arising from the operation, these need to be taken in context of the current structure of the SAR system and the challenges this can pose for the various participants.

3.105 The NEST helicopter based at Whangarei was the first asset to be tasked.⁵⁶ NEST prepared the aircraft and assembled its crew based on what they had been told. They assumed the worst case and took the time to prepare accordingly. It is generally acknowledged that locating and winching people from the water into a helicopter in the dark during inclement weather is a high-risk activity. This rescue of the survivors was probably on the edge of the helicopter and crew's capability. The NEST helicopter crew's expertise was instrumental in five people from the *Enchanter* surviving.

3.106 The *Enchanter* SAR operation is considered by those involved as at the upper end of challenge and complexity, and yet it only involved one 16-metre vessel with 10 people on board, very close to the New Zealand coast. At any time in New Zealand, there are likely to be much larger vessels with more people on board operating in even more remote areas than North Cape. The Commission has considered the accident on that premise.

3.107 It is also important to acknowledge that very little was known in the initial stages of the *Enchanter* SAR operation. The operation started with a single activation of the

⁵⁶ When an asset is 'tasked' it is allocated a role in the SAR operation.

Enchanter's EPIRB, with no indication whether it was real or an inadvertent EPIRB activation. Once it had been established that the emergency was real, the response plan was formed – but still with little information about the situation. The broad plan evolved and was refined as more information was received. In those initial stages there was no indication that it could evolve into an almost two-day SAR operation involving multiple air and surface assets.

SAR helicopters

- 3.108 New Zealand's fleet of air ambulance/rescue helicopters is primarily used for air ambulance work (95 per cent). The other 5 per cent is for SAR work. The rescue helicopter fleet is divided into three sectors: Helicopters South Island, Helicopters Lower North Island and Helicopters Upper North Island. Each helicopter operator is contracted to the National Ambulance Sector Office (NASO). NASO set up the Airdesk mainly to coordinate the dispatch of rescue aircraft in support of NASO (see Figure 23).
- 3.109 The NASO contracts outlined the availability and capability that helicopter operators must provide to NASO. Consequently, rescue helicopters are of the type and configuration that supports air ambulance work, rather than SAR work. Also, air ambulance work is the main priority. If the RCC requests a rescue helicopter to be tasked to a SAR operation, it may or may not be available for SAR work depending on what air ambulance work is in progress or planned.
- 3.110 When the RCC contacted the Airdesk and requested a rescue helicopter based out of Whangarei, the NEST helicopter was not engaged on air ambulance work, so was immediately available. The ARHT helicopter that was requested and tasked to support the NEST helicopter was returning from an air ambulance task and was then made available. The second AHRT helicopter that was later tasked had been engaged in air ambulance work but was also available after sourcing an appropriate crew.
- 3.111 There were delays in dispatching all three helicopters as each operator reconfigured the aircraft from air ambulance work to SAR work and sourced the appropriate crew for winching over water.




Figure 23: Organisation chart showing the relationship between the air ambulance sector and the RCC. (The green arrows represent funding lines.)

- 3.112 Rescue helicopters are limited in size because of the maximum weight restriction for most hospital helipads. This affects their SAR people-carrying capability and flight range. For example, when the NEST helicopter retrieved the first three survivors from the inverted flybridge, its seating capacity was exceeded, with one survivor having to be seated unrestrained on the floor. There was no room for retrieving the other two passengers from the inverted hull without making the return trip to the Te Hapua forward command post.
- 3.113 Another issue is the funding of SAR specific equipment for helicopters. The onboard medical equipment is mostly funded by NASO for air ambulance work. Any additional SAR-related equipment is funded by the helicopter operator. With SAR work providing only 5 per cent of operational time, it can be difficult for the operator to recover the additional cost of this equipment.
- 3.114 Most rescue helicopter crew use night-vision goggles for flying and searching at night. None of the aircraft tasked to the *Enchanter* SAR operation were equipped with fixed gyro-stabilised or portable thermal-imaging equipment, which is particularly useful when searching for living people in large spans of water. Fixed gyro-stabilised thermal-imaging equipment creates a significant weight penalty on helicopters that are often already up to all-up maximum weight with the medical equipment, medical personnel and patients on board.
- 3.115 The RNZAF operates a fleet of eight NH90 helicopters that are larger and have a longer range than most standard NASO-contracted rescue helicopters. Although winch capable, they were not rated for 'wet winching'⁵⁷ at the time of this accident. The RNZAF helicopter crews are trained in and routinely practise search and rescue. They are tasked by RCC from time to time but not as often as they once were. There used to

⁵⁷ Retrieval of people from water

be an NH90 permanently located in South Island that was used almost exclusively for SAR operations. Anecdotally a policy has evolved, or a directive made, that they should not be tasked when a commercial helicopter is available and can be used. It is not clear by whom and when this policy was put in place.

3.116 Currently all eight NH90s are located at the RNZAF Ohakea Air Force Base in North Island. The RNZAF has a performance agreement to have one NH90 helicopter always available for SAR work at two hours' notice. There is an opportunity to explore potential synergies between RNZAF and SAR to make better use of the NH90 fleet (or any other fleet operated by Defence Joint Forces) to enhance New Zealand's SAR capability.

SAR helicopter crews

3.117 With the current SAR framework, air crews for NASO-contracted operators comprise pilots, co-pilots, doctors and critical care paramedics. It can at times be unclear whether a task is related to air ambulance or SAR work, or both. For example, when a rescue helicopter is tasked to search for and recover a person known to be injured, there can be an element of search and, because it is known that a person requires medical attention, there is the requirement for an air ambulance, which the helicopter fulfils as well. Therefore, there can be an obvious crossover of roles within the helicopter crew.

3.118 The crew roles that are specific to SAR work are rescue swimmers and winch operators although, in the scenario described above, the winch operator can be required for both air ambulance and SAR work. One issue that arises is the cost of training and retaining crew specifically for SAR work, particularly when it represents only five per cent of revenue-earning helicopter operations. A second issue is the standardisation of training for these roles.

3.119 To resolve this issue some critical care paramedics also train as rescue swimmers and/or winch operators. This creates another potential issue – critical care paramedics are often employed by air ambulance operators for NASO, thus creating a potential tension in assigning tasks and responsibility.

3.120 All three rescue helicopters tasked to the *Enchanter* SAR operation encountered issues assembling a complete crew with sufficient experience for the high-risk task. There were consequential delays. The reasons varied from there being a general shortage of experienced winch operators and rescue swimmers, to several being given annual leave at the same time by their primary employers, who are primarily concerned with ambulance services.⁵⁸ If the first rescue helicopter tasked had been responding to air ambulance work, it would likely have been airborne within about 20 minutes. By the time the helicopter had been transitioned from air ambulance to SAR mode and the appropriate crew assembled, it departed 85 minutes after having been tasked. This is not a criticism of the crew. They were rightfully assessing the risks of the operation and doing the best allowed by the system in which they were operating.

3.121 Training of crew for rescue helicopters is conducted and funded by the helicopter operator to meet the standards set out in the NASO Aeromedical and Air Rescue Standard. The Standard provides detailed requirements for medical operations, but not for winch operators and rescue swimmers. They are simply required to have

⁵⁸ NRHL has since acquired full-time critical care paramedics.

'completed a course of training that meets current accepted practice and be certified by an approved person, with competency checks completed at 12-month intervals and recorded'. An approved person is an operator's check and training pilot or winch operator, as designated within the company's operating exposition approved by the Civil Aviation Authority.

- 3.122 There is no definition of 'current accepted practice'. There is no mandated or recommended training syllabus. This means the training standards may vary significantly between operators across the country. This has proven to be problematic when crew move between operators.
- 3.123 The issue arises because of a regulatory gap. Medical staff are governed by ambulance and NASO standards. Flight crew (pilots) are governed by civil aviation rules. Rescue swimmers and winch operators are not governed by any specific standards. The NZSAR Council and the NZSAR Secretariat only provide strategic oversight and governance for the SAR sector. They do not currently have the mandate to set standards for the sector.
- 3.124 In contrast, the Australian SAR framework operates to a strict set of standards that ensures there is consistency and safety across the entire sector.

Fuel supply

Safety Issue: *The national availability of fuel for helicopters likely to be engaged in extended SAR operations in remote areas is not well documented or understood by the SAR coordinating authorities.*

- 3.125 NEST had purchased a 1200 litre fuel trailer to be kept at Kaitaia Hospital. Fuel supply for helicopters in the Far North was limited and its scarcity was affecting their air ambulance operation, which was essentially based around Kaitaia Hospital. This fuel trailer was the furthest north permanent supply of Jet A1 fuel available to aircraft.
- 3.126 Helicopter pilots are responsible for ensuring their aircraft have sufficient fuel to safely conduct their tasks. Helicopter operators are responsible for ensuring their total fleet has a sufficient supply of fuel to support their operations. This is not difficult for routine tasking. However, SAR operations are anything but routine. The *Enchanter* SAR operation began as a one-helicopter and then two-helicopter operation with an unknown end point. It grew into a multiple-aircraft multi-day operation.
- 3.127 While individual pilots and helicopter operators can manage their fuel on a task-by-task basis, they do not have the oversight that the RCC has as the SAR plan evolves. There is therefore some responsibility on the RCC's part to prompt pilots/operators about fuel supply before it becomes an issue for the aircraft it is tasking and renders them inoperative with consequential delays to the SAR plan.
- 3.128 The RCC began inquiring about sourcing fuel shortly after midnight on the day of the accident. Fuel was eventually sourced once the RCC learned that the NEST helicopter was grounded at Kaitaia Hospital, but it took several hours before fuel reached the two helicopters at Kaitaia Hospital and the Te Hapua forward command post. During the 46-hour SAR operation the RCC made 29 phone calls trying to source fuel, adding to the already full workload of the coordinating staff.
- 3.129 The lack of available fuel in the region resulted in a four-and-a-half-hour period in which helicopters were unable to search for the remaining five people in the water.

3.130 Caching fuel for extended air operations in remote areas is not straight forward. Fuel has a shelf life and can deteriorate over time. The quantity and quality of fuel require careful management. However, there will be opportunities to synergise the requirement of caching fuel in remote areas with routine aircraft operations. The Commission has **recommended** that the Secretary for Transport work with SAR coordinators and providers of SAR air assets across New Zealand to identify opportunities for caching fuel for extended SAR operations in remote areas, and to establish and maintain a database of identified stored fuel and fuel supply logistics.

Fixed-wing aircraft

3.131 Fixed-wing aircraft are important for SAR operations. While they do not have the rescue capability of helicopters, they provide an important cost-effective search function. The *Enchanter* SAR operation has highlighted issues with the availability of suitable fixed-wing aircraft for SAR operations.

3.132 The P-3K2 provided an ideal communications platform, making it suitable as an on-scene coordination asset. The P-3K2 crew were able to relay information to the RCC, and direct other assets to search various debris fields. The aircraft also had a thermal imaging suite capable of detecting large objects in the water such as vessels. However, the suite was not ideally suited for detecting small objects in the water such as people. The P-3K2 was ideally suited for long-range SAR operations, which is important considering New Zealand's vast SAR area.

3.133 On the night of the response, rain squalls were moving through the area. The associated cloud hindered the view from the P-3K2, requiring them to fly at low altitude beneath the cloud. Operating a large aircraft at low altitude at night meant it had to stay further offshore than the actual scene, to maintain a safe clearance from terrain.

3.134 The Coastguard operates two Cessna aircraft, one based at Ardmore in Auckland, and one based at Kerikeri in the Far North. The RCC tasked these aircraft during daylight hours. The aircraft offered a cost-effective⁵⁹ search solution for the *Enchanter* SAR operation. They were able to fly close to shore in areas that the P-3K2 could not. However, they have limitations. There are only two and they are both based to cover the Auckland and Far North areas only, thus limiting their use for other regions. The aircraft are restricted to daylight operations, and subject to visual flight rules.⁶⁰ Their SAR capability is limited to visual observation and radio direction-finding equipment.

3.135 New Zealand has a long coastline to cover for SAR operations. There is an opportunity to introduce a medium-sized aircraft suitably equipped for SAR operations at a lower operational cost than the larger aircraft available. Such an aircraft would be better suited to SAR operations such as with the *Enchanter* and could also prove more efficient for medium-range SAR operations to South Pacific islands. There is also an opportunity to use these aircraft for other NZDF operations, and those of other Government departments, such as Fisheries New Zealand and New Zealand Customs.

⁵⁹ They are both totally funded through Coastguard New Zealand

⁶⁰ Civil Aviation Authority criteria essentially limit their use to good weather when the pilot can navigate visually without the aid of instruments.

3.136 The Commission raised this possibility in its Preliminary Report to the Royal Commission of Inquiry into the sinking of the interisland passenger and freight ferry *MV Princess Ashika* on 5 August 2009.⁶¹ The recommendation was:

[New Zealand] to explore the possibility of dedicated search and rescue aircraft fitted with SAR equipment and trained crew being made available to conduct search and rescue operations in the New Zealand and Fiji SAR areas. Such an aircraft could be multi-purpose to conduct other maritime and land-based activities such as customs and Fisheries.

3.137 Australia uses such an aircraft for its SAR operations, which has proven successful. The Commission has made a **recommendation** for the Ministry of Transport to explore this opportunity.

Surface vessels

3.138 There is an issue with New Zealand having sufficient readily available and suitable surface vessels for participating in challenging and extended SAR operations, not dissimilar to the issue with aviation assets described above.

3.139 The NZ Police has two maritime units, one based in Auckland and one in Wellington. These assets are primarily for addressing crime and supporting the NZ Police Dive Squad. They are suitable for SAR operations, but their availability is limited to the areas where they happen to be located, primarily the Greater Auckland and Wellington areas. The Auckland NZ Police launch did not participate in the *Enchanter* SAR operation.

3.140 The RNZN also has several assets suitable for SAR operations, but again their availability will be determined by their current location. The RNZN's service agreement requires it to have one vessel available for deployment out of Auckland at 12 hours' notice.

3.141 The *HMNZS Taupo* was coincidentally operating in the Hauraki Gulf, Auckland at the time of the *Enchanter* accident. The commander responded to the mayday relays and proceeded to the area, sailing into heavy weather and arriving on scene at 1110 the following day.

3.142 When the *HMNZS Taupo* did arrive, the RCC handed over the on-scene coordinator role to the commander. However, the RNZN was not familiar with the term and assumed the naval warfare role of on-scene commander, which effectively took control away from the RCC. The issue was eventually realised and addressed but not before the coordination of the search patterns had been disrupted for a number of hours.

3.143 The issue is likely due in part to the lack of joint SAR training between the RNZN and the RCC. RNZN personnel are trained in basic SAR techniques, but not in rescue coordination. Ideally, it should be standard practice for organisations routinely used as on-scene coordinators to be trained in and familiar with RCC procedures, and that practice be documented in the overarching SAR system. The Commission has made a **recommendation** for the Ministry of Transport to address this issue.

3.144 Coastguard has multiple assets spread strategically across all New Zealand regions. The organisation is a charity relying entirely on volunteers and raises approximately 70 per cent of its operating income from donations, membership, and grants. (The remaining 30 per cent of costs is met by a government service level agreement.) While the organisation is considered to be the primary SAR service in New Zealand, most of

⁶¹ Maritime Inquiry MO-2009-209, Final Preliminary Report prepared by the Commission for the Royal Commission of Inquiry into the sinking of the *MV Princess Ashika*.

its work involves responding to recreational boat events, providing fuel for boaters who have run out or towing to safety those that have broken down.

- 3.145 The funding model does not support the build and operation of larger craft capable of operating offshore. Consequently, their craft are primarily designed for inshore events and less so for serious complex extended SAR operations, as is the training provided to their volunteer crew. That is not a criticism of their performance. They are renowned for providing a good and efficient service. The rescues they perform will often prevent an event escalating to one requiring a SAR response.
- 3.146 There are two other limiting factors: not all Coastguard boats are surveyed to operate outside of inshore or restricted coastal limits; and the qualification that Coastguard can issue to their volunteer skippers restricts them to operating within 12 miles of the coast.⁶²
- 3.147 Houhora is home to the northernmost Coastguard unit in the country. Coastguard Houhora relies on volunteers to maintain and operate a 9.5-metre rigid-hull inflatable boat (RHIB)⁶³ to provide services from Cape Reinga to Doubtless Bay (see Figure 24).
- 3.148 Coastguard Houhora had received the initial notification of the distress at 2035, while Houhora was still experiencing heavy winds associated with the passing storm system.
- 3.149 As with any notification, the Coastguard Houhora unit conducted a risk assessment to ensure their own safety. After consulting with local operators, and with the duty officer and SAR coordinator at Coastguard New Zealand operations centre, it was determined that the risk of responding would be too high. The decision not to deploy was appropriate in the circumstances.
- 3.150 With Coastguard Houhora unable to respond that night, *HMNZS Taupo* being some distance away, and there being no commercial vessels in the immediate area, there were no surface vessels available to participate in the *Enchanter* SAR operation until about eight hours after the accident.

⁶² Coastguard vessels may be granted permission by Maritime New Zealand to go beyond restricted limits for the purposes of SAR if required.

⁶³ This has since the accident been replaced with a 10-metre RHIB



Figure 24: Coastguard Houhora vessel

Commercial Vessels

3.151 The use of commercial vessels of opportunity during SAR operations is common practice throughout the world as they are often likely to be nearest to the scene. International law under the United Nations Convention on the Law of the Sea (UNCLOS) Article 98 also requires masters of vessels to respond to distress unless it endangers the vessel and/or its crew.

3.152 During a SAR operation the RCC will use any available asset that is able to assist. The lack of professionally crewed marine assets suitable for offshore SAR operations means SAR coordinators have fewer options for surface assets, which increases their dependency on untrained civilian vessels of opportunity. Using commercial vessels in a weather-related event like the capsizing of the *Enchanter*, often means that other vessels may not be in the immediate area.

3.153 During the *Enchanter* SAR operation, the RCC had tasked five commercial vessels to aid in the search. Of the five vessels, one was another charter fishing boat owned by *Enchanter* Fishing Charters, while the other four were commercial fishing boats.

3.154 The crews of these vessels (some of whom had children on board), had the challenge of searching for long periods of time and sighting and recovering deceased victims from the sea.

3.155 Professional SAR personnel have resources and support available to help them to deal with the mental toll this type of work can take. Civilians do not necessarily have access to that same support. It should be noted that at the conclusion of the *Enchanter* search, individuals who were involved were made aware of available mental health services.

4 Findings

Ngā kitenga

- 4.1 There were no known mechanical or equipment failures that contributed to the accident.
- 4.2 It is **about as likely as not** that the accident occurred around the 10 metre depth contour off Murimotu Island, North Cape.
- 4.3 It was not the skipper's intention to navigate close to the shore in shallower water. The reason for the *Enchanter* being there was not established.
- 4.4 It was reasonable for a vessel of the *Enchanter's* size, design, stability and construction to be operating in the weather and sea conditions around North Cape at the time of the accident, provided it was operated in accordance with its Maritime Transport Safety System and Marine Transport Operator Plan.
- 4.5 The *Enchanter* was knocked down by a wave that was larger and with a steeper profile than the average wave conditions it had been encountering, because of one or a combination of the following factors:
- waves up to twice that of the significant wave height can naturally occur in deep water
 - the convergence of two different wave patterns can cause random large waves
 - reflection of waves off the shoreline
 - the tendency for waves to increase in height and steepen when they enter shallower water.
- 4.6 The *Enchanter* exceeded all stability parameters required under Maritime Rule Part 40, and all its maritime documents were current at the time of the accident.
- 4.7 The *Enchanter* was unable to recover from the knock down because it was **very likely** tipped past its point of vanishing stability and its superstructure failed allowing down-flooding of its internal spaces.
- 4.8 It is **virtually certain** that the connection between the *Enchanter's* superstructure and hull was in good condition – the connection failing in overload when hydrodynamic forces sustained during the knock down exceeded its design parameters.
- 4.9 Nine of the ten people onboard are known to have survived the initial capsizing, but four of them later died. It is **virtually certain** that one or a combination of the following factors had an effect on survivability:
- time immersed in the water with associated hypothermia and swim failure
 - limited flotation support (except for one person who was retrieved from a lifebuoy)
 - injuries sustained during the capsizing
 - pre-existing medical conditions.

- 4.10 None of the people on board were able to put on a life jacket because of the suddenness of the capsizing and because all life jackets were stowed below in the forward cabin, which was difficult to access.
- 4.11 Opportunities to increase survivability were missed for the following reasons:
- the life rafts likely did not automatically deploy
 - only two of the four lifebuoys were fitted with automatic lights
 - two of the lifebuoys were not marked with retro-reflective tape and the reflective tape on the other two was degraded and of limited effectiveness.
- 4.12 The crew of the first helicopter on scene managed the high-risk task of wet winching in the dark over water with skill. Their expertise was instrumental in saving the lives of five people from the *Enchanter*.
- 4.13 There were delays in the deployment of rescue helicopters to the *Enchanter* scene while appropriately qualified and experienced crew were assembled.
- 4.14 Although helicopters were made available for the *Enchanter* SAR operation, the current New Zealand SAR system does not ensure that readily available, appropriately equipped and crewed, air resources will be available for future SAR operations, particularly in remote areas.
- 4.15 There was a period of 4 hours and 36 minutes when the lack of available fuel prevented helicopters searching for the remaining five people in the water, which was attributable in part to fuel supply being based on air ambulance services and not on extended SAR operations in remote areas.
- 4.16 The current New Zealand SAR system does not guarantee that dedicated, appropriately equipped and fixed-wing aircraft resources will be available for future SAR operations.
- 4.17 The current New Zealand SAR system does not adequately provide for dedicated, appropriately equipped surface vessels to be available for future SAR operations.

5 Safety issues and remedial action

Ngā take haumanu me ngā mahi whakatika

General

- 5.1 Safety issues are an output from the Commission's analysis. They may not always relate to factors directly contributing to the accident or incident. They typically describe a system problem that has the potential to adversely affect future transport safety.
- 5.2 Safety issues may be addressed by safety actions taken by a participant. Otherwise the Commission may issue a recommendation to address the issue.

Safety issues

Safety issue – Maritime New Zealand's system for auditing and assessing the performance of accredited vessel surveyors is not ensuring they are interpreting and applying maritime rules correctly when surveying vessels.

- 5.3 The consequence of this safety issue is the risk of vessels either intentionally or inadvertently operating outside maritime rule requirements.
- 5.4 No action has been taken to address this safety issue. Therefore, the Commission has made a **recommendation** in Section 6 to address this issue.

Safety Issue – New Zealand maritime rules do not adequately address the need for proper stowage of life jackets on board passenger vessels so that passengers have access to a life jacket in the event of a sudden catastrophic event.

- 5.5 The consequence of this safety issue is that passengers and crew will not be able to access a life jacket following a sudden and catastrophic event.
- 5.6 No action has been taken to address this safety issue. Therefore, the Commission has made a **recommendation** in Section 6 to address this issue.

Safety issue – There is no requirement for commercial vessels that carry passengers to be fitted with any form of tracking device such as AIS or other commercially available tracking systems.

- 5.7 The consequence of this safety issue is potential delay in the start of SAR operations and compromise in their efficiency.
- 5.8 No action has been taken to address this safety issue. Therefore, the Commission has made a **recommendation** in Section 6 to address this issue.

Safety Issue – New Zealand does not have readily available and suitable resources that can be assigned to SAR operations in the following operational areas:

- *helicopters that are fully equipped and crewed for extended SAR operations across New Zealand and its coastal waters*
 - *medium-range fixed-wing aircraft designed, equipped and crewed for SAR operations across New Zealand coastal waters and the EEZ*
 - *vessels that are designed, equipped and manned by crew practised at conducting SAR operations out to offshore limits.*
- 5.9 The potential consequence of this safety issue is the failure of the SAR system to respond to a major accident adequately and efficiently in remote areas with the potential for avoidable loss of life.

5.10 No action has been taken to address this safety issue. Therefore, the Commission has made a **recommendation** in Section 6 to address this issue.

Safety Issue – There is currently no dedicated programme that requires organisations that operate SAR assets and might routinely be assigned on-scene coordinator status to engage in joint training with the RCC to ensure consistency in knowledge of the SAR framework and terminology.

5.11 The potential consequence of this safety issue is a potential breakdown in the framework and structure of a SAR operation.

5.12 No action has been taken to address this safety issue. Therefore, the Commission has made a **recommendation** in Section 6 to address this issue.

Safety Issue – The national availability of fuel for helicopters likely to be engaged in extended SAR operations in remote areas is not well documented and understood by SAR coordinating authorities.

5.13 The consequence of this safety issue is that SAR operations could be delayed or prevented because tasked assets have insufficient fuel supplies to perform their task.

5.14 No action has been taken to address this safety issue. Therefore, the Commission has made a **recommendation** in Section 6 to address this issue.

6 Recommendations

Ngā tūtohutanga

General

- 6.1 The Commission issues recommendations to address safety issues found in its investigations. Recommendations may be addressed to organisations or people, and can relate to safety issues found within an organisation or within the wider transport system that have the potential to contribute to future transport accidents and incidents
- 6.2 In the interests of transport safety, it is important that recommendations are implemented without delay to help prevent similar accidents or incidents occurring in the future.

New recommendations

To the Ministry of Transport

- 6.3 On 13 July 2023, the Commission recommended that the Secretary for Transport:
- Delegate responsibility to one or more entities, for the remit, jurisdiction and resources to set standards for search and rescue (SAR) assets and the training of their SAR crews and enter into service level agreements with other agencies and operators for the provision of search and rescue assets. **[012/23]**
 - Coordinate across government and other appropriate agencies to identify and source air and maritime assets that are appropriately designed, equipped and crewed to meet New Zealand's full SAR requirements. Government agencies that have a potential dual use for these assets or who have existing assets that could provide a dual role should be considered **[013/23]**
 - Work with SAR coordinators and providers of SAR air assets across New Zealand to identify opportunities for the supply and, if necessary, the storage of fuel for extended SAR operations in remote areas, and maintain a database of identified stored fuel and fuel supply logistics. **[014/23]**
 - Work with SAR coordination entities to ensure they have procedures for prompting the operator of air assets about the maximum range of operation and opportunities for refueling for sustained SAR operations. **[015/23]**
 - Work with SAR coordination authorities to identify SAR assets that are likely to be routinely called on to act as on-scene coordinators and develop a joint training programme that will ensure that they work to the same framework and use the same terminology as the coordinating authorities. **[016/23]**

To Maritime New Zealand

- 6.4 On 13 July 2023, the Commission recommended that the Director of Maritime New Zealand:
- implements a formal system that:
 - notifies surveyors of current and emerging changes to maritime rules for the construction, maintenance and surveying of vessels

- clarifies, where needed, the intent and application of maritime rules and other relevant standards **[017/23]**

Ensures that Maritime New Zealand has an adequate system for monitoring the performance of marine surveyors. **[018/23]**

Ensures that appropriate rules and/or guidance is available to marine surveyors and vessel operators about the risk of having all life jackets stowed in one place that might not be accessible during foreseeable events. **[019/23]**

Introduces the requirement for commercial vessels to be fitted with automatic identification system (AIS) or equivalent when carrying passengers outside inshore limits. **[020/23]**.

Notice of recommendations

- 6.5 The Commission has given notice to the New Zealand Search and Rescue Council Secretariat that it has issued recommendations [017/23, 018/23, 019/23 and 020/23] to the Ministry of Transport and that this recommendation will require the involvement of the New Zealand Search and Rescue Council.

7 Key lessons

Ngā akoranga matua

- 7.1 For any forecast or actual sea conditions, mariners should expect to encounter waves up to twice the average size at any time.
- 7.2 Mariners should, if possible, avoid navigating in shallow water in adverse wave conditions or, if shallow water cannot be avoided, be particularly vigilant and expect waves much larger and steeper than those that would be expected in deep water.
- 7.3 It is important that passengers either get to practise putting on a life jacket or are given a demonstration of how to do so during a safety briefing, rather than having to work this out under the pressure of an emergency.
- 7.4 It would be safer if life jackets were distributed in several places throughout a vessel where they will be more accessible in a sudden emergency.
- 7.5 Wearing an inflatable life jacket or similar buoyancy aid will enhance the safety of people when fishing from open decks in open and exposed waters.
- 7.6 There is some safety benefit in wearing a personal locator beacon as a backup to the EPIRBs required on commercial vessels, in case the circumstances of an accident prevent the use of the EPIRB.
- 7.7 Fitting an AIS or equivalent tracking device to a vessel will significantly improve the likelihood of being found and reduce the time for being rescued, particularly if the primary life-saving equipment fails or cannot be activated.

8 Data summary

Whakarāpopoto raraunga

Vehicle particulars

Name:	<i>Enchanter</i>
Type:	Wooden monohull fishing charter vessel
Class:	Passenger/non passenger (depending on limits)
Limits:	New Zealand: all Enclosed and Inshore Limits, Coastal and Restricted Offshore Limits (out to 100 nm)
Construction:	Glass over double-diagonal kauri planks
Length:	16.26 m
Breadth:	4.6 m
Displacement:	30.5 tonnes (loaded)
Built:	In Tauranga to HAAG Boat designs in 1982
Propulsion:	Two 253 kw diesel engines
Service speed:	8 knots
Owner/operator:	Enchanter Fishing Charters
Home port:	Mangōnui
Minimum crew:	2

Date and time 20 March 2022 1950

Location North Cape, New Zealand

People involved 8 passengers and 2 crew

Injuries 5 fatal
5 moderate

Damage Vessel destroyed

9 Conduct of the Inquiry

He tikanga rapunga

- 9.1 On 21 March 2022, Maritime New Zealand notified the Commission of the occurrence. The Commission subsequently opened an inquiry under section 13(1) of the Transport Accident Investigation Commission Act 1990 and appointed an investigator-in-charge.
- 9.2 On 21 March 2022 the Commission issued an Order to Produce and Protect the *Enchanter*, including any debris, objects or items originating from the vessel.
- 9.3 The Commission deployed a team of four investigators to Northland on 21 March 2022, who spent four days conducting interviews and gathering evidence.
- 9.4 On 31 March 2022, two investigators were redeployed to Northland to oversee the salvage and towing of the *Enchanter* wreck to Houhora, Northland. A GPS was recovered from the wreck during the salvage and retained by the Commission for analysis. The investigators conducted a thorough inspection of the *Enchanter* wreck on the shores of Houhora Harbour, after which permission was given for the wreck to be dismantled and transported to a location in Houhora.
- 9.5 On 25 May 2022, the Commission authorised release of the dismantled wreckage of the *Enchanter* to the vessel's insurers for disposal by marked (GPS) burial in a registered landfill, and release of the two recovered diesel engines for on selling. The Commission's Order to Produce and Protect remained in place for debris, objects or items originating from the vessel.
- 9.6 From 01 to 02 June 2022, three investigators travelled to Northland and Auckland to conduct interviews with several companies and agencies involved in the SAR operation for the *Enchanter*.
- 9.7 On 07 June 2022, two investigators conducted interviews with staff from the Rescue Coordination Centre at Wellington.
- 9.8 On 14 June 2022, two investigators conducted an interview with representatives from the EPIRB manufacturer.
- 9.9 From 05 to 07 July 2022, two investigators attended a search and rescue seminar at Wellington to gather further information about the responsibilities and interaction between providers of SAR assets. During this period investigators conducted an interview with staff from the Ministry of Health's National Ambulance Sector Office in relation to the provision of helicopter services for SAR operations.
- 9.10 On 26 October 2022 the Commission approved a draft report for circulation to ten Interested Parties for their comment.
- 9.11 Submissions were received from eight Interested Persons, with the Ministry of Transport delegating their response to the NZSAR Council. One of the submissions included a report from an independent expert. Any changes as a result of these submissions have been included in the final report.
- 9.12 On 13 January 2023, investigators engaged an expert in EPIRB data and functionality to provide an analysis of the data. The expert is an employee of the EPIRB manufacturer. However, their analysis is based on past experience as an operator with the United Kingdom Mission Control Centre and does not reflect the opinion of the manufacturer.

- 9.13 On 22 February 2023, the Commission considered the final report but deferred approval pending further enquiries in relation to some further late submissions received.
- 9.14 On 22 March 2023, the Commission approved a second draft report for circulation to two Interested Parties to comment on a single issue.
- 9.15 Submissions were received from one interested party, which included three reports (one prepared by an independent expert, one by a classification society, and one by a meteorological organisation). Any changes as a result of this submission have been included in the final report.
- 9.16 On 12 July 2023, the Commission approved the final report for publication.

Abbreviations

Whakapotonga

AIS	Automatic Identification System
ARHT	Auckland Rescue Helicopter Trust
EEZ	Exclusive Economic Zone
EPIRB	Emergency Position-Indicating Radio Beacon
GFS	Global Forecast System
GPS	Global Positioning System
HMNZS	Her/His Majesty's New Zealand Ship
IMO	International Maritime Organisation
m	metres
NASO	National Ambulance Sector Office
NZDT	New Zealand Daylight Time
NZSAR	New Zealand Search and Rescue
NEST	Northland Emergency Services Trust
nm	nautical miles
RCC	Rescue Coordination Centre
RHIB	rigid hull inflatable boat
RNZAF	Royal New Zealand Air Force

RNZN	Royal New Zealand Navy
SAR	search and rescue
SOLAS	International Maritime Organization Convention for the Safety of Life at Sea
UNCLOS	United Nations Convention on the Law of the Sea
VHF	very high frequency

Glossary

Kuputaka

Aft	The back or rear of a vessel.
AIS	Automatic Identification System is an automated, autonomous tracking system designed to be capable of providing position, identification and other information about the ship to other ships and coastal authorities automatically.
Backing (wind)	The wind direction changes or trends anticlockwise.
Bow	The front of a vessel.
Bulkhead	Nautical term for a wall
Carline	Fore and aft beam that provides an attachment between the hull and the sides of cabins, hatches and cockpits on a boat.
Down-flooding	The entry of seawater through any opening into an undamaged hull of a vessel.
EPIRB	Emergency Position-Indicating Radio Beacon (EPIRB) designed to transmit its location and verification data to a rescue coordination center and thus alert SAR authorities that an emergency exists.
Fishing lures	Hooked objects attached to a fishing line designed to move and resemble prey.
Flybridge	An additional deck that sits on top of the main superstructure, often used as a viewing point or additional control station.
Freeboard deck	The uppermost complete deck exposed to the weather and the sea which has permanent means of closing all openings in it.
Galley	Nautical term for a kitchen

GNSS	Global Navigation Satellite System: A satellite system that provides location data for navigation purposes; one of Compass, Galileo, Glonass, or GPS.
GPS	Global Positioning System: A GNSS system that is operated by the United States of America.
MEOSAR	medium-altitude earth orbit search and rescue satellite system for distress alerting and position determination of 406 MHz beacons.
Motorsailer	A boat designed primarily as a motor launch but fitted with rigging and sails as an alternative means of propulsion.
Port	Left-hand side of a vessel when looking forward.
Significant wave height	The average wave height, from trough to crest, of the highest one-third of the measured or observed waves.
Starboard	Right-hand side of a vessel when looking forward.
Superstructure	Structures built on top of a vessel's freeboard deck.
Swim failure	A person is no longer able to swim or remain afloat.
Watertight	Capable of preventing the passage of water in any direction under the head of water likely to occur.
Waverider buoy	A buoy fitted with instruments that precisely measure directional waves for direction, heights, periods and energy data.
Wavelength	The distance from the trough in front of the wave and the trough behind the wave.
Wave period	The time between successive wave peaks to pass a given point.
Waypoint	Specified point on a chart for a planned passage.
Wet winching	Retrieval of people from water.

Appendix 1 Wave formation and characteristics

The survivors described the *Enchanter* being knocked down by a large steep wave. The following information provides context to Section 3 of this report.

Wave formation

The size and behaviour of waves are determined by a range of factors, from the direction of the swell to the speed of the tide, prevailing ocean currents, the depth of the water, the shape of the seafloor, the presence of reefs and sandbanks, and even the temperature of the ocean.⁶⁴

However, wind is the primary factor that governs the size of the waves. Waves are caused by wind blowing over the surface of the ocean and transferring energy from the atmosphere to the water. The height of waves is determined by the speed of the wind, how long it blows, and crucially the 'fetch' (the distance that the wind blows in a single direction over the water).

Bigger waves result from conditions that cause strong winds to blow for a sustained period over a large expanse of ocean. The resulting waves can travel for hundreds or even thousands of kilometres, smaller waves being absorbed by larger ones, faster waves overtaking slower ones, all gradually growing and arranging themselves into the regular 'sets' or wave trains⁶⁵.

The result of these interactions is that it is normal to experience a wide range of wave heights when on the water.

'Significant wave height' is the international convention⁶⁶ used to describe the size of swell and wind waves (or 'sea waves') in coastal forecasts. Significant wave height is defined as the average wave height, from trough to crest, of the highest one-third of the measured or observed waves.

Figure 25 shows that a mariner will experience a typical 'wave spectrum' containing a low number of small waves (at the bottom) and a low number of very large waves (at the top). The greatest number of waves is indicated by the widest area of the spectrum curve. The highest one-third of waves is highlighted in dark blue, and the average height of waves in this group is the significant wave height.

⁶⁴ Australian Bureau of Meteorology.

⁶⁵ A group of progressing waves of about the same wavelength moving in the same direction at about the same speed.

⁶⁶ Devised by oceanographer Walter Munk during World War II.




Figure 25: Significant wave height
 (Source: Australian Bureau of Meteorology)

While the most common waves are lower than the significant wave height, it is statistically possible to encounter a wave that is much higher – especially if you are out in the water for a long time. It is estimated that approximately one in every 3,000 waves will reach twice the height of the significant wave height – roughly equivalent to three times every 24 hours.

Wave energy and wave changes with depth

As the energy of a wave passes through water, the energy sets water particles into orbital motion, as shown in Figure 26. Water particles near the surface move in circular orbits with diameters approximately equal to the wave height. The orbital diameter, and the wave energy, decreases deeper in the water. Below a depth of half the wavelength, water is unaffected by the wave energy.

Swells are deep-water waves, meaning that the depth of the water is greater than half the wave’s wavelength. The energy of a deep-water wave does not touch the bottom in the open water (see Figure 27).

When deep-water waves move into shallow water, they change into breaking waves. When the energy of the waves touches the ocean floor, the water particles drag along the bottom and flatten their orbit.




Figure 26: Changes in orbital characteristics of water when waves transition to shallow water.

(Source :University of Hawaii, image by Byron Inouye)

Because of the friction of the deeper part of the wave with particles on the bottom, the top of the wave begins to move faster than the deeper parts of the wave. When this happens, the front surface of the wave gradually becomes steeper than the back surface.

Waves travelling in water where depth is less than half the wavelength but greater than one-twentieth the wavelength are referred to as transitional waves, which are often wind-generated waves that have moved into shallower water.




Figure 27: Wave changes as waves approach the shore

(Source: University of Hawaii, image by Byron Inouye)

Rogue Waves – comment from the United States National Oceanic and Atmospheric Administration

Rogue, freak or killer waves have been part of maritime folklore for centuries but have only been accepted as real by scientists over the past few decades.

Rogues, called 'extreme storm waves' by scientists, are those waves that are greater than twice the size of surrounding waves, are very unpredictable, and often come unexpectedly from directions other than prevailing wind and waves.

Most reports of extreme storm waves say they look like "walls of water." They are often steep-sided with unusually deep troughs.

Since these waves are uncommon, measurements and analysis of this phenomenon is extremely rare. Exactly how and when rogue waves form is still under investigation, but there are several known causes:

Constructive interference – extreme waves often form because swells, while travelling across the ocean, do so at different speeds and directions. As these swells pass through one another, their crests, troughs and lengths sometimes coincide and reinforce each other. This process can form unusually large, towering waves that quickly disappear. If the swells are travelling in the same direction, these mountainous waves may last for several minutes before subsiding.

Focusing of wave energy – when waves formed by a storm develop in a water current against the normal wave direction, an interaction can take place that results in a shortening of the wave frequency. This can cause the waves to dynamically join together, forming very big 'rogue' waves. The currents where these are sometimes seen are the Gulf Stream and Agulhas Current. Extreme waves developed in this fashion tend to be longer lived.

Appendix 2 The *Enchanter's* stability information

- 2.1 Part of a stability analysis is to calculate what is called a GZ Curve. GZ is the theoretical righting lever that forces a vessel back upright when it is heeled by any forces such as wind and waves. The longer the GZ lever, the more force is imparted to return the vessel upright. If a vessel has a negative GZ righting lever, then the force is acting to capsize the vessel rather than returning it upright. In Figure 28, when the vessel is upright (left) the upward thrust of buoyancy (**B**) is equal to and vertically aligned with the downward weight acting through the vessel's centre of gravity (**G**). The vessel is floating in equilibrium when force of **G** equals **B**.
- 2.2 When the vessel heels due to wind and/or waves (right), the position of the vessel's centre of gravity (**G**) remains the same but the position of the centre of buoyancy moves across to the new centroid of the underwater volume (**B1**). The upward thrust through **B1** is no longer aligned with **G**. A righting lever (GZ) is thus created, which in this case tries to return the ship upright until **G** and **B** align again. The length of the righting lever GZ changes as the vessel heels through a range of angles.




Figure 28: Relationship between buoyancy, weight and centre of gravity

- 2.3 For any given stability condition, a range of values for GZ can be calculated and plotted on a graph showing the length of GZ on the X axis against the angle of heel on the Y axis. This graph is the GZ curve mentioned above. Figure 29 shows the calculated GZ curve for a typical stability condition that the *Enchanter* had when nearing the end of a voyage. The value of GZ starts off at zero when there is zero angle of heel and then steadily increases as the angle of heel increases. The length of the righting lever GZ peaks at a heel angle of 33.8 degrees and then begins to decrease as the angle of heel increases beyond 33.8 degrees.
- 2.4 The value for GZ reaches zero at a heel angle of 77 degrees. This is known as the angle of vanishing stability. If the *Enchanter* heeled past 77 degrees, the value of GZ becomes negative. At that point GZ becomes a capsizing lever and the vessel will capsize.




Figure 29: GZ curve for the Enchanter, representative of its stability condition at the time of the capsizing
 (Source: The *Enchanter's* Stability Manual)

		Criteria	Units	Required	Actual	Status
1	MSA 40C	Area 0. to 30.	m.Radians	0.055	0.1300	Pass
2	MSA 40C	Area 0. to 40. or Downflooding Point	m.Radians	0.09	0.1983	Pass
3	MSA 40C	Area 30. to 40. or Downflooding Point	m.Radians	0.03	0.0684	Pass
4	MSA 40C	GZ at 30. or greater	m	0.2	0.391	Pass
5	MSA 40C	Angle of GZ max	Degrees	25	33.8	Pass
6	MSA 40C	GM	m	0.35	1.229	Pass

		0° Heel	10° Starb. Heel	20° Starb. Heel	30° Starb. Heel	40° Starb. Heel	50° Starb. Heel	60° Starb. Heel	70° Starb. Heel
1	GZ m	0.000	0.205	0.330	0.391	0.381	0.324	0.228	0.104
2	Displacement t	26.93	26.93	26.93	26.93	26.93	26.93	26.93	26.93
3	Draft at AP m	1.209	1.195	1.113	0.961	0.772	0.539	0.190	-0.440
4	Draft at FP m	1.462	1.446	1.404	1.336	1.221	1.022	0.724	0.151
5	WL Length m	15.129	15.117	15.077	15.011	14.914	15.083	14.854	15.257
6	Beam max on WL m	4.226	4.096	3.840	3.646	3.564	3.398	3.309	3.248
7	Wetted Area m^2	59.891	58.293	56.060	56.758	58.388	59.826	60.502	59.256
8	Waterpl. Area m^2	49.889	47.871	44.985	41.158	37.543	34.398	31.974	28.947
9	Prismatic coeff. (Cp)	0.632	0.634	0.634	0.642	0.648	0.623	0.625	0.607
10	Block coeff. (Cb)	0.347	0.368	0.433	0.454	0.404	0.406	0.413	0.418
11	LCB from zero pt. (+ve fwd) m	5.640	5.641	5.643	5.649	5.652	5.650	5.647	5.642
12	LCF from zero pt. (+ve fwd) m	4.976	5.053	5.240	5.406	5.809	6.114	6.311	6.349

Loadcase 3 – Arrival Minimum Fuel

	Item Name	Qty.	Weight Tonne	Long.Arm m	Vert. Arm m	FS Mom. Tonne.m
1	Lightship	1	24.309	5.690	1.790	0.000
2	Growth Allowance	1	1.215	5.690	2.170	0.000
3	Fuel Aft P	30%	0.149	-0.557	1.135	0.042
4	Fuel Aft S	30%	0.149	-0.557	1.135	0.042
5	Fuel Mid P	0%	0.000	-7.300	0.000	0.000
6	Fuel Mid S	0%	0.000	-7.300	0.000	0.000
7	Fuel Fwd P	0%	0.000	-7.300	0.000	0.000
8	Fuel Fwd S	0%	0.000	-7.300	0.000	0.000
9	FW P	10%	0.030	1.750	1.230	0.042
10	FW S	10%	0.030	1.750	1.230	0.042
11	Personnel Top Deck	1	0.750	6.000	5.500	0.000
12	Personnel Main Deck	1	0.300	6.000	3.400	0.000
13	Total		26.933	5.624	1.920	0.167
14				FS correction	0.006	
15				VCG fluid	1.926	

1	Displacement Tonne	26.93
2	Heel degrees	0.0
3	Draft at FP m	1.461
4	Draft at AP m	1.209
5	Draft at LCF m	1.295
6	Trim m (+ve by stern)	-0.252
7	LCB to AE. m	5.640
8	LCF to AE. m	4.976
9	KB m	0.977
10	KG m	1.926
11	BMt m	2.178
12	BML m	26.624
13	GMt m	1.229
14	GML m	25.675
15	KMt m	3.155
16	KML m	27.601
17	TPc Tonne/cm	0.511
18	MTc Tonne.m	0.474

Figure 30: Sample calculation representing a typical load case for the Enchanter
(Source: The *Enchanter's* Stability Manual)

Appendix 3 Maritime Rules Part 40C

Maritime Rules

3.2 Offshore limit ships and coastal limit ships

The requirements in Appendix 3.2 apply to ships that proceed in the coastal or the offshore limit.

Item	Requirements						
Survival craft (comprising lifeboats, rescue boats and liferafts)	<p>(1) A ship of 30 metres or more in length overall must be provided with either,—</p> <ul style="list-style-type: none"> (a) on each side of the ship, one or more lifeboats of sufficient aggregate capacity to accommodate all persons on board, and liferafts of sufficient aggregate capacity to accommodate all persons on board; or (b) a rescue boat that is capable of being launched on one side of the ship and liferafts, of sufficient aggregate capacity to accommodate twice the number of persons on board. <p>(2) A ship of less than 30 metres but 15 metres or more in length overall must be provided with—</p> <ul style="list-style-type: none"> (a) at least one lifeboat or rescue boat that is capable of being launched on one side of the ship; and (b) liferafts of sufficient aggregate capacity to accommodate all persons on board. <p>(3) A ship of less than 15 metres in length overall must carry at least one liferaft of sufficient aggregate capacity to accommodate all persons on board.</p> <p>(4) If 16 or more persons are carried in a ship, the number of liferafts provided must be at least 2.</p> <p>(5) Liferafts carried must be stowed so that they can be readily placed in the water on either side of the ship.</p> <p>(6) Each lifeboat or rescue boat must be attached to a separate set of davits that complies with rule 42A.28(2). Liferafts must be provided with a hydrostatic or similar automatic release to enable the liferafts to float free if the ship sinks.</p> <p>(7) Lifeboats must comply with rule 42A.6 and 42A.7 where applicable. A liferaft must comply with rules 42A.8 and 42A.9. A rescue boat must comply with rule 42A.15.</p>						
Lifebuoys	<p>(1) A ship of 60 metres or more in length overall must be provided with at least 8 lifebuoys and a ship of less than 60 metres in length overall must be provided with at least 4 lifebuoys but, where the total number of persons carried on the ship is less than 8, at least the following number of lifebuoys must be carried:</p> <table border="0" data-bbox="638 1500 1021 1590"> <tr> <td>7 or 8 persons</td> <td>4 lifebuoys</td> </tr> <tr> <td>5 or 6 persons</td> <td>3 lifebuoys</td> </tr> <tr> <td>4 or less persons</td> <td>2 lifebuoys</td> </tr> </table> <p>(2) One lifebuoy on each side of the ship must be fitted with a buoyant lifeline. At least 50 percent of the total number of lifebuoys must be provided with self-igniting lights and (on ships greater than 30 metres in length) at least two of the lifebuoys provided with self-igniting lights must also be provided with self-activated smoke signals and be capable of quick release from the navigating bridge.</p> <p>(3) Lifebuoys must comply with rule 42A.16.</p>	7 or 8 persons	4 lifebuoys	5 or 6 persons	3 lifebuoys	4 or less persons	2 lifebuoys
7 or 8 persons	4 lifebuoys						
5 or 6 persons	3 lifebuoys						
4 or less persons	2 lifebuoys						

Part 40C: Design, Construction and Equipment – Non-passenger Ships that are not SOLAS Ships

Lifejackets	<p>(1) A ship must be provided with a lifejacket for every person that the ship is permitted to carry. Lifejackets must have a buoyancy of 150 Newtons and must comply with rule 42A.18.</p> <p>(2) A lifejacket must be provided for each child carried that is of an appropriate size and that complies with rule 42A.19.</p>
Line throwing appliance	A ship of 30 metres or more in length must be provided with a line throwing appliance that complies with rule 42A.30.
Distress flares	A ship must be provided with 6 rocket parachute flares that comply with rule 42A.22.

3.3 Restricted coastal and restricted limit ships

The requirements of Appendix 3.3 apply to ships that proceed in a restricted coastal limit or restricted limits.

Item	Requirements				
Survival Craft (comprising lifeboats, rescue boats and liferafts)	<p>(1) A ship of 35 metres or more in length overall that operates in a restricted coastal limit must be provided with—</p> <p>(a) one or more liferafts, that comply with rules 42A.11 and 42A.12, of sufficient aggregate capacity to accommodate all persons on board and stowed so that they can readily be placed in the water on either side of the ship; and</p> <p>(b) a rescue boat, that complies with rule 42A.15, stowed so that it can readily be placed in the water on one side of the ship.</p> <p>(2) A ship of less than 35 metres in length overall that operates in a restricted coastal limit must be provided with one or more liferafts that comply with rules 42A.11 and 42A.12, of sufficient aggregate capacity to accommodate all persons on board the ship. The liferafts must be stowed so that they can be readily placed in the water on either side of the ship.</p> <p>(3) A ship that does not proceed beyond restricted limits must carry either—</p> <p>(a) lifeboats, that comply with rules 42A.6 and 42A.7; or</p> <p>(b) rescue boats, that comply with rule 42A.15; or</p> <p>(c) liferafts, that comply with rules 42A.11 and 42A.12; or</p> <p>(d) buoyant apparatus, that comply with rule 42A.31; or</p> <p>(e) lifebuoys, that comply with rule 42A.17,</p> <p>that, together with the number of lifebuoys required below, are sufficient to support all persons on board the ship.</p> <p>(4) Each lifeboat or rescue boat provided must be attached to davits that complies with rule 42A.28(2).</p>				
Lifebuoys	<p>(1) A ship must be provided with lifebuoys as follows:</p> <p>(a) for ships of 24 metres or more in length overall, at least 4 lifebuoys, provided that where the total number of persons carried on the ship is less than 8, at least the following number of lifebuoys must be carried—</p> <table style="margin-left: 40px;"> <tr> <td>7 or 8 persons</td> <td>4 lifebuoys</td> </tr> <tr> <td>5 or 6 persons</td> <td>3 lifebuoys</td> </tr> </table>	7 or 8 persons	4 lifebuoys	5 or 6 persons	3 lifebuoys
7 or 8 persons	4 lifebuoys				
5 or 6 persons	3 lifebuoys				

Maritime Rules

	<p>4 or less persons 2 lifebuoys; and</p> <p>(b) for ships of 15 metres or more but less than 24 metres in length overall, at least 2 lifebuoys; and</p> <p>(c) for ships of 9 metres or more but less than 15 metres in length overall, one lifebuoy; and</p> <p>(d) for ships of less than 9 metres in length overall—</p> <p>(i) one lifebuoy; or</p> <p>(ii) one rescue buoy that is satisfactory to a surveyor; or</p> <p>(iii) one throw bag that is satisfactory to a surveyor.</p> <p>(2) At least one lifebuoy must be provided with a buoyant lifeline and at least one lifebuoy must be provided with a self-igniting light, but if a restricted limit ship is permitted to operate in daylight only, self-igniting lights are not required.</p> <p>(3) All lifebuoys must comply with rule 42A.17.</p>
Lifejackets	<p>(1) A ship must carry a lifejacket for every person on board. A children's lifejacket of an appropriate size must be provided for every child carried.</p> <p>(2) Lifejackets must comply with rule 42A.19.</p> <p>(3) For ships operating in a restricted coastal limit, the lifejackets required for adults must have a buoyancy of at least 100 Newtons.</p> <p>(4) For ships operating in a restricted limit, the lifejackets required for adults must have a buoyancy of at least 71 Newtons.</p>
Distress flares	<p>(1) A ship that operates in a restricted coastal limit must be provided with 6 rocket parachute flares that comply with rule 42A.22, and 2 buoyant smoke signals that comply with rule 42A.24.</p> <p>(2) A ship that operates in inshore limits must be provided with 2 rocket parachute flares that comply with rule 42A.22, and 2 buoyant smoke floats that comply with rule 42A.24.</p> <p>(3) Subject to the exceptions in (4), a ship that operates only in enclosed water limits must be provided with at least 2 buoyant smoke floats that comply with rule 42A.24, and 2 hand flares that comply with rule 42A.23.</p> <p>(4) For a ship of 6 metres or less in length overall that operates only in the enclosed water limit,—</p> <p>(a) 2 hand flares are not required if the ship operates in daylight only; and</p> <p>(b) no distress flares need be provided if a surveyor is satisfied that—</p> <p>(i) 2 other independent means of communicating with the shore are always available on the ship;⁴⁰ or</p> <p>(ii) the ship operates only in a river or in a restricted waterway where the use of distress flares is unnecessary.</p>

⁴⁰ For example, the means of communication in rule 40C.53(2).

Appendix 4 Post-salvage inspection



Figure 31: The Enchanter being prepared for towing after raising (top left); being winched up the beach (top right); on the beach after salvage (bottom)




Figure 32: The Enchanter showing damage to bow sustained during salvage (top); overview of what had been the main saloon (middle); and detail of failed connection between the hull and superstructure (bottom).

Appendix 5 Expert analysis of EPIRB data

The *Enchanter* Capsize, description of EPIRB transmissions – 20 March 2022 (all times in UTC)

Enchanter EPIRB Data Analysis for Transport Accident Investigation Commission – New Zealand

By Daniel Bailey (United Kingdom) – 26th January 2023

This analysis has been written from my personal knowledge and experience, and is largely made up of my time spent working on the UK Mission Control Centre and within the Coastguard.

Experience & Background

Current role (Aug 2021 to Present) – Sales Manager – Seas of Solutions (McMurdo, Kannad marine, & Netwave)

Previous roles:

Maritime Technical Trainer (COSPAS-SARSAT and UKMCC) – HM Coastguard – Dec 2019 to July 2021

Senior Maritime Operations Officer – HM Coastguard – June 2017 to July 2021

Maritime Operations Officer – HM Coastguard – Nov 2015 to June 2017

Coastguard Rescue Officer – HM Coastguard – July 2012 to October 2018

Qualifications:

SMC (Search and Rescue Mission Co-ordinator) based on the IMO SMC Model Course - Feb 2020

MCC Operator (COSPAS-SARSAT Mission Control Centre Operator) based upon C/S G.010 – Jun 2017

VHF Short Range Certificate – April 2010

Coastguard Communications Certificate (GMDSS Comms) based upon the GMDSS GOC– May 2016

RYA Level 2 Powerboat – April 2010

RYA Advanced Powerboat – April 2010

RYA Yachtmaster Offshore (Shore based) – May 2016

RYA Day Skipper – May 2016

Incident Analysis – Enchanter Capsize – 20th March 2022 (all times in UTC)

EPIRB Data & Information

HEX ID: 400C9093AEFFBFF

Country Code: 512 – New Zealand

Protocol: Standard Location – Serial

Type Approval Certificate No. 289

Serial No. 2519

Manufacturer - McMurdo Ltd. (previously Orolia Maritime)

Model – McMurdo SmartFind G8 AIS Auto

EPIRB Technical Data – See Annex 1 (Product Data Sheet)

406 MHZ TRANSMITTER		DIMENSIONS (EPIRB)	
Frequency	406.040 MHz + 1kHz	Weight	710 g
Power output	5 W nominal	Height/Width/Depth	423x104x103 mm (incl. antenna)
Modulation	Phase (16K0G1D)	Length of antenna	206 mm
121.5 MHZ TRANSMITTER		DIMENSIONS (MANUAL BRACKET)	
Frequency	121.5 MHz + 3 kHz	Weight	110 g
Power output	100 mW nominal	Height/Width/Depth	270x125x121 mm
Modulation	Swept tone AM (3K20A3X)	DIMENSIONS (FLOAT FREE ENCLOSURE)	
AIS TRANSMITTER (SEE NOTE 1)		Weight	1075 g
Frequencies	161.975 MHz (AIS1); 162.025 MHz (AIS2)	Height/Width/Depth	416x126x132 mm
Power output	1 W nominal	STANDARDS APPLIED	
Modulation	Phase (16K0GXW)	COSPAS-SARSAT	C/S 1.001 C/S T.007
GNSS RECEIVER (SEE NOTE 2)		Europe	MED (wheelmark)
Constellations	GPS, Galileo	USA	USCG & FCC; FCC ID; KLS-Z701;
Frequencies	1575.42 MHz (GPS, Galileo);		4 7 CFR Parts 80, 2;
Sensitivity	-167 dBm minimum	International standards	Dependant on variant
Satellites tracked	72 channel		IEC 61097-2; IEC 60945 incl.
STROBE LIGHT			Corrigendum1; Industry Canada
Type	3 high intensity LEDs		RSS-287; AS/NZS 4280.1;
Light output	0.2 cd minimum		IMO MSC/Circ. 862
Flash rate	23 flashes per minute	IMO regulations	A.662(16); A.694(17); A.810(19);
BATTERY			A.814(19)
Type	Lithium iron disulphide	PART NUMBERS	
Operating life	48 hours minimum	SmartFind G8 Manual EPIRB	23-001-002A
Shelf life (in-service life)	10 years from date of manufacture typical in service (see Note 3)	SmartFind G8 Auto EPIRB	23-001-502A
		SmartFind G8 AIS Manual EPIRB	23-001-001A
		SmartFind G8 AIS Auto EPIRB	23-001-501A
ENVIRONMENT			
Operating temperature	20 °C to +55 °C (-4° F to +131° F)		
Storage temperature	-30 °C to +70 °C (-22° F to +158° F)		
Automatic release depth	4 m maximum		

Type Approval Certificate – See Annex 2 (Type Approval Certificate)



TAC Report Nr. 289-1

TAC Number	289	TAC Date	20-JUL-2017	TAC Rev. date	22-OCT-2021
Beacon Model Name	McMurdo Smartfind AIS G8 (Z701)				
Additional Names	Kannad Safe Pro (Z701), Crewsaver Crewfind G8 AIS (Z701)				
Manufacturer	McMurdo Ltd				
Tx Frequencies	406.040 MHz				
In Production	not in production	Class	2		
Type	FF / Non FF EPIRB	Tested Life (hours)	48		
Battery	Battery pack P/N 23-105B, 3 x 2 AA-size serially connected Energizer L91 Lithium Iron Disulfide cells				
	Battery Legend: Battery cell manufacturer, Cell chemistry, Cell model, No. of cells, Cell size.				
Protocols tested	UL - User-Location, SL - Standard Location, NL - National Location				
Self Test	yes	Self Test RF	yes	Self Test RF (Short/Long)	long
Self Test Format Flag	long	Self Test Consistent with 15 Hex ID	yes		
Homer Freq	121.5 MHz			Homer Duty Cycle	96%
Homer Power	70 mW				
Strobe Light	yes	Strobe Brightness	0.75 cd	Strobe Duty Cycle	23 flashes per minute
Nav Device	internal (GPS, GLONASS, Galileo)	Nav Device Model	U-blox NEO-M8N		
Encoded Position Data Update Interval	Range (minutes) 5-31				
Separable Antenna	no	Antenna Model	Integral antenna		
Additional functions	AIS location transmitter; GNSS self-test mode; Automatic beacon activation via sea water contacts.				
General comments	Designed and tested for operation while floating in water, or on deck, or in a safety raft. Type approved with Standard Location Protocol variants: EPIRB with MMSI, EPIRB with Serial Number; National Location protocol: EPIRB; User-Location protocol variants: Maritime with MMSI, Maritime with Radio Call Sign, EPIRB Float Free with Serial Number, EPIRB Non-Float Free with Serial Number, Radio Call Sign. Beacon is available in orange and yellow colour.				
TAC rev history	1) 20-Jul-17: Originally approved with TAC 289 issued to Orolia Ltd. UK; 2) 6-Oct-17: yellow colour variant added; 3) 13-Jan-2021: Approval of related RLS variant under TAC 1001; 4) 22-Oct-2021: Anticipated termination of production due to S/N limit. Production continued on TAC 347.				

COSPAS-SARSAT Data Plotted

The below has been extracted from the MEOLUT and GEOLUT data provided. There may be additional data available from other MCCs and LUTs, however this analysis provides sufficient information to explain how events unfolded with the EPIRB.

Key:



EPIRB AIS Transmission (accurate to 11 Metres)



EPIRB Encoded Position (60 metre error radius – see note 1*)



MEOSAR DOA Position (with an EHE of less than 6 kilometres – see note 2*)



MEOSAR DOA Position (positions with any EHE – see note 2*)



Image 1

- The above image shows a plot of encoded positions and AIS transmission from the EPIRB for the first 3.5 hours. The first plot at 0721 UTC provides a position approx. 560 metres off shore (with a 60 metre error radius to be applied around the position).
- Noting a very straight line drift of the encoded position, this is due to the limitations of COSPAS-SARSAT data processing, and limiting the encoded position to 2 decimal places on the SIT 185 sent to RCCNZ, which rounds the positions up or down.




Image 2

- To provide context, the yellow markers indicate MEOSAR DOA positions (independent of the EPIRBs GNSS position) which have an EHE of less than 6 kilometres. These position were all received within the first 3.5 hours of the beacon activation, and when you apply their relevant EHE, the GNSS position with the same timestamp is encompassed with the radius of the EHE.
- The pink location markers on this image indicate positions which provided an EHE of more than 6km, which still encompasses their corresponding encoded positions provided by the beacon.



Image 3

- Image 3 provides further MEOSAR independent hits including positions with an EHE greater than 6 kilometres.
- The pink line at the top of the image measures approx. 9.3km, to give context to the EHE provided, which shows that the EPIRBs GNSS position is inside the radius of all MEO DOA positions.

2.7 GNSS Positions

A distress beacon with GNSS capability is able to transmit a GNSS position as part of its beacon message. There are two mechanisms used to derive the GNSS position: either the distress beacon has an internal GNSS receiver, or the distress beacon receives the GNSS data from an external device that connects to the beacon.

If the distress beacon with GNSS capability does not provide a GNSS position (for example, as the internal receiver cannot derive a GNSS position as it cannot track sufficient GNSS satellites), default values are transmitted in the beacon message that indicate that there is no encoded GNSS position available.

Distress beacons that transmit GNSS position data are coded with a Location protocol; however, for FGBs, the particular Location protocol used affects the precision of the GNSS position data that can be sent in a beacon message. Table 2.1 lists the precision for the FGB Location protocols.

Table 2.1: Maximum Precision of the FGB Location Protocols

Protocol	Maximum Difference	Equivalent Distance at Equator
User Location	2 minutes	3.7 kilometres
Standard Location	2 seconds	60 metres
National Location	2 seconds	60 metres
RLS	2 seconds	60 metres
ELT(DT)	2 seconds	60 metres

In some situations, a beacon message may have errors that result in the LUT not being able to produce a fine GNSS position. Instead, a coarse GNSS position is produced. Table 2.2 shows the coarse precision for the Location protocols that may have a coarse precision GNSS position.

Table 2.2: Precision of the FGB Location Protocols with only Coarse Position

Protocol	Maximum Difference*	Equivalent Distance at Equator
Standard Location	7 minutes 30 seconds	13.9 kilometres
National Location	1 minute	1.9 kilometres
RLS	15 minutes	27.8 kilometres
ELT(DT)	15 minutes	27.8 kilometres

* Assumes all available bits are used to provide the coarse position; see section 5.8.1.

Note 1

- As per C/S G.007 (see annex 3), for First Generation Beacons when a refined position is provided in a SIT 185, and the beacon protocol is Standard, the precision of the encoded position provided shall be treated as 2 seconds of latitude/longitude or 60 metres at the equator.
- The position is provided to only 2 decimal places which does not provide any greater accuracy, despite the beacons onboard GNSS chip able to provide a more refined position.
- The McMurdo SmartFind G8 AIS is both an FGB and was coded as Standard Protocol. The encoded positions provided were refined from the first encoded burst from the beacon. No coarse positions were provided in the data supplied.

Note 2 Expected Accuracy for DOA Location

For each DOA location, an Expected Accuracy (i.e., estimated error) value is computed. Information on the Expected Accuracy, also known as the Expected Horizontal Error (EHE), is provided in the SIT 185 message as described in Paragraph 4.

This value is the radius of the circle centered on the DOA location that should contain the true beacon location with a 95% probability. In other words, there is a 95% probability that the location error, which is defined as the distance between the DOA location and the actual beacon location, is lower than the Expected-Accuracy value.

The figure below illustrates the configuration for which the DOA location error is lower than the associated Expected-Accuracy value, with the corresponding confidence percentage.





Figure 3.5: Additional Expected-Accuracy-Related Boundary



Data Distribution

LUT ID	Name
5125	New Zealand MEOLUT
5035	Australia MEOLUT
4163	Chinese Taipei MEOLUT
5124	New Zealand GEOLUT
5635	Singapore MEOLUT
7255	Chile MEOLUT
3669	United States MEOLUT
5123	New Zealand GEOLUT
2711	Turkey LEOLUT

MCC Involved	Data Distribution Region
Australian MCC	South West Pacific DDR
Chilean MCC	Western DDR
Chinese MCC	North West Pacific DDR
Singapore MCC	South West Pacific DDR
United States MCC	Western DDR
Turkey MCC	Central DDR
Japanese MCC	North West Pacific DDR
French MCC	Central DDR

Table 1

- The above table provides the sources of data processed by the MEOSAR satellites which processed the beacon data in this incident.
- In this incident, data was processed via multiple satellites and processed through the ground stations and to their corresponding MCCs. Through the data distribution plan, the data passed through various MCCs and arrived at the AUMCC (Australian MCC) which generated the relevant SIT 185s for RCCNZ.
- Note – There may have been additional data which was transmitted through other existing LUTs and MCCs, but this data has not been provided. Any additional data would be redundant for the purpose of this analysis.

4-6

C/S A.001 – Issue 8 – Rev.7
November 2022

4.1.4.4 South West Pacific DDR

Data flow in South West Pacific DDR (ASMCC, AUMCC, IDMCC, SIMCC and THMCC) is described in Figure 4-5.




Figure 4-5: South West Pacific DDR Network Diagram

Image 4

- Image 4 is a diagram of the South West Pacific DDR which shows how it is connected to other MCCs and how the data is transmitted to RCCs and SPOCs.

- AUMCC is the nodal MCC and is responsible for connection to the other DDRs in the world.

Summary and Analysis

Having looked the data provided and referencing the above plotted positions I can provide the following summary and analysis.

It is unknown of the exact time and method of activation of the Enchanter's EPIRB, however the first beacon burst was received at 0717UTC on the 20th March 2022. An EPIRB will send it's first 406Mhz transmission approx. 50 seconds after it has been activated, so it would be an educated guess that the EPIRB was activated around 0716 to 0717UTC.

Within the first few minutes of the beacon being active, multiple MEOSAR satellites detected the beacon's transmission and relayed the 30 digit hexadecimal code (transmitted by the beacon) to various LUTs within range, this generate the first alert sent to RCCNZ with no position (to alert them to a beacon activation), at the same time an independent calculation of the beacon's position was produced which in turn generated a following SIT 185 with a MEO DOA position.

As the EPIRB had been on for a couple of minutes, the internal GNSS receiver had ascertained a fix with Galileo and GPS satellites, and produced it's own position, which was then transmitted to the MEOSAR satellites. This position was provided alongside the independent MEOSAR position but provided greater accuracy of the beacons position, equating to an approx. error radius of 60 metres (due to limitations of data coding within it's distress message).

As the EPIRB began to drift in a north/north easterly direction, both the MEOSAR DOA positions, and the encoded positions changed, and updated SIT 185s were transmitted to RCCNZ.

4.2.4 Position Update Alert

An MCC will send an update alert if it receives beacon detection data that is not redundant. Cospas-Sarsat has a very detailed definition of when an update is sent, but from the Responsible Agency perspective, an update will be sent when the MCC has additional data or better-quality data, or to indicate that the beacon is still active and transmitting.

An update can be sent before and after confirmation of the location.

Prior to position confirmation, a new alert with DOA position that is otherwise redundant will be sent every five (5) minutes for all beacon types except ELT(DT)s.

To prevent too many MEOSAR alerts from being sent to a Responsible Agency after position confirmation, a MEOSAR alert with DOA position matching the MCC reference position that is not better quality will only be sent every 15 minutes. A MEOSAR alert with DOA position that does not match the MCC reference position and is not better quality will only be sent every ten (10) minutes. An alert with a better-

Note 3

- From C/S G.007. To avoid too many SIT 185 messages being generated, the system will only send updates if position data improves or moves, otherwise they will be sent approx. every 15 minutes.

4-8

C/S G.007 - Issue 3 – Rev.1
November 2022

quality DOA position (based on the expected horizontal error) is always sent, as specified in document C/S A.001. Position is not confirmed for ELT(DT)s, which are assumed to be fast-moving.

For all beacon types except ELT(DT)s, an updated alert with GNSS position is sent if the new GNSS position differs from previously sent GNSS position by three (3) to twenty (20) kilometres or, for an FGB, if the new GNSS position is refined (i.e., more precise) and no previous GNSS position was refined.

Whilst the beacon was transmitting its 406Mhz distress message to the satellites, it was also transmitting its AIS priority message locally which acts in a similar fashion to an AIS SART. The Enchanter's EPIRB was transmitting an AIS message with MMSI 974122519, with 974 as the prefix indicating that the AIS transmission was an EPIRB. On an AIS receiver if you were to interrogate the target and look at message field 14, you would have seen "**EPIRB ACTIVE - 400C9093AEFFBFF**" this then allows you to see that this AIS transmission is from the same EPIRB.

Due to the increased data able to be transmitted over AIS, the position given will be accurate to approx. 11 metres, and you will see on the plotted maps above that the AIS positions are within the 60 metres of the encoded positions transmitted via the COSPAS-SARSAT system.

The beacon continued to drift over the next few hours until rescue assets arrived, and was not recovered, so continued to drift until the beacons battery died several days later.

Throughout the initial 3.5 hours since the beacon first activated, the approx. drift rate was 0.15knots to 0.18knots, which given that it is estimated the capsizing occurred approx. 20 to 25 minutes earlier, it would suggest that the incident occurred no more than approx. 200m to the southwest of the beacon's first position provided at 0717 UTC. Noting that I do not have access to tidal or wind information, this is only an estimate. However previous experience of targets in the water and/or debris, there is limited influence by the wind, and would be tidal driven. Tidal information in the area may assist in estimating the incident location.

Throughout the incident the EPIRB continued to transmit, and data was received almost every minute, which I would label as a 'textbook' incident.

Over my career working on the Mission Control Centre, and as a Search and Rescue Mission Co-ordinator, I dealt with thousands of beacon activations (Real and False Alerts), and in comparison, the data provided I would class as very reliable and clear. Whilst there is some concern that the MEO positions provided had larger than desired EHEs (note – There may be additional data with smaller EHEs, but I do not have access to the information), this incident highlights the importance of owning an EPIRB with a GNSS receiver. But even if the beacon did not have a GNSS receiver, the MEO positions would have led the SAR assets to the rough area, and utilising DF (Direction Finder) equipment, they would have been able to track the 121.5Mhz homing signal which is mandatory on all beacons in the COSPAS-SARSAT system, and would have led them to the beacon's location.

There is nothing within the data that presents any errors, and in my professional opinion, would suggest that the EPIRBs encoded positions were a true reflection of their location (+/- 60 metres) from 0717UTC onwards, and the MEOSAR positions although scattered around, were also correct with their applied EHEs.

I have attached the following documents to support my analysis and findings:

- Annex 1 – McMurdo SmartFind G8 AIS Product Data Sheet
- Annex 2 – Type Approval Certificate 289 – From COSPAS-SARSAT
- Annex 3 – EPIRB Map Data – Data used to plot on the maps.

Annex 4 – C/S A.001 – Data Distribution Plan

Annex 5 – C/S G.007 – Handbook on Distress Alerts for RCCs and SPOCs

I have also attached two reports provided by the UK's Marine Accident Investigation Branch for incidents which I was actively involved with during my time within Her Majesty's Coastguard.

The first report is for a fishing vessel 'Joanna C' which capsized and sank. In this incident the EPIRB automatically activated and search and rescue assets deployed to the MEOSAR positions provided. The EPIRB itself did not have a GNSS receiver, which meant that the search area would have been greater than it need to be, but survivors were still rescued as a result of the EPIRB activation.

The second report is for a fishing vessel 'Diamond D' which capsized and sank. In this incident, the crew were able to abandon to a liferaft and activate the EPIRB manually. This EPIRB had an internal GNSS receiver, and we were able to direct lifeboats and helicopters to their GNSS encoded position, to which all crew members were recovered safely without the need to search.

The reason for sharing these reports is to highlight the importance of a GNSS enabled EPIRB, and that when they are activated, there is little to no ambiguity over their positions, resulting in taking the 'search' out of 'Search and Rescue'.

Glossary:

MCC – Mission Control Centre

Ground station where data from associated LUTs is processed and either passed on to other MCCs or used to generate an alert for an RCC/SPOC.

LUT – Local User Terminal

Receiving ground station terminal which processes beacon data from the relevant satellites.

EHE – Expected Horizontal Error

An expected accuracy applied to a MEO DOA position.

GNSS – Global Navigation Satellite System

Term applied to various systems such as GPS, Galileo, and Glonass, which make up the GNSS network.

EPIRB – Emergency Position Indicating Radio Beacon

A distress beacon which utilises the Cospas-Sarsat network, and is used primarily in the maritime domain.

MEOSAR - Medium-altitude earth orbit search and Rescue

A satellite constellation which makes up part of the space segment in the Cospas-Sarsat network which process distress beacon signals and estimates a beacon's location.

AIS – Automatic Identification System

An automatic tracking system used by vessels and their associated devices to present their position to other vessels/systems tracking AIS transmitters.

MEO DOA – Medium Earth Orbit Difference of Arrival

The MEOSAR satellites process a beacons signal and compute a beacon position based upon their time of arrival and frequency of arrival. These combined are able to generate a MEO DOA position.

FGB – First Generation Beacon

A term used to define beacons on the market today. All PLBs and EPIRBs currently are First Generation Beacons.

RCC – Rescue Co-ordination Centre

A responsible authority who will execute the search and rescue for a beacon incident. They will be actively involved in search planning, asset tasking, and communications.

SPOC – Search & Rescue Point of Contact

A dedicated point of contact who will receive the messages from an MCC. They may or may not also be the RCC. In some cases they may pass the alert data on to another RCC.

Appendix 6 Rescue helicopter flight data (TracPlus data)

Flight data from the rescue helicopter confirms that the first rescue helicopter on scene retrieved the three survivors from the flybridge within 61 metres of the EPIRB's encoded position (see Figures 33 and 34).




Figure 33: Flight data showing helicopter hovering over EPIRB encoded position (green dots)



Figure 34: Close up of helicopter flight path hovering over EPIRB encoded position (green dot). Red circle indicates the 61-metre accuracy around the EPIRB encoded position at 0013

Kōwhaiwhai - Māori scroll designs

TAIC commissioned its four kōwhaiwhai, Māori scroll designs, from artist Sandy Rodgers (Ngāti Raukawa, Tūwharetoa, MacDougal). Sandy began from thinking of the Commission as a vehicle or vessel for seeking knowledge to understand transport accident tragedies and how to avoid them. A 'waka whai mārama' (i te ara haumarū) is 'a vessel/vehicle in pursuit of understanding'. Waka is a metaphor for the Commission. Mārama (from 'te ao mārama' – the world of light) is for the separation of Rangitāne (Sky Father) and Papatūānuku (Earth Mother) by their son Tāne Māhuta (god of man, forests and everything dwelling within), which brought light and thus awareness to the world. 'Te ara' is 'the path' and 'haumarū' is 'safe' or 'risk free'.

Corporate: Te Ara Haumarū - the safe and risk free path



The eye motif looks to the future, watching the path for obstructions. The encased double koru is the mother and child, symbolising protection, safety and guidance. The triple koru represents the three kete of knowledge that Tāne Māhuta collected from the highest of the heavens to pass their wisdom to humanity. The continual wave is the perpetual line of influence. The succession of humps represents the individual inquiries.

Sandy acknowledges Tāne Māhuta in the creation of this Kōwhaiwhai.

Aviation: Ngā hau e whā - the four winds



To Sandy, 'Ngā hau e whā' (the four winds), commonly used in Te Reo Māori to refer to people coming together from across Aotearoa, was also redolent of the aviation environment. The design represents the sky, cloud, and wind. There is a manu (bird) form representing the aircraft that move through Aotearoa's 'long white cloud'. The letter 'A' is present, standing for a 'Aviation'.

Sandy acknowledges Ranginui (Sky father) and Tāwhirimātea (God of wind) in the creation of this Kōwhaiwhai.

Maritime: Ara wai - waterways



The sections of waves flowing across the design represent the many different 'ara wai' (waterways) that ships sail across. The 'V' shape is a ship's prow and its wake. The letter 'M' is present, standing for 'Maritime'.

Sandy acknowledges Tangaroa (God of the sea) in the creation of this Kōwhaiwhai.

Rail: rewhenua - flowing across the land



The design represents the fluid movement of trains across Aotearoa. 'Rere' is to flow or fly. 'Whenua' is the land. The koru forms represent the earth, land and flora that trains pass over and through. The letter 'R' is present, standing for 'Rail'.

Sandy acknowledges Papatūānuku (Earth Mother) and Tāne Mahuta (God of man and forests and everything that dwells within) in the creation of this Kōwhaiwhai.



Transport Accident Investigation Commission

***Recent Maritime Occurrence reports published by
the Transport Accident Investigation Commission
(most recent at top of list)***

MO-2022-206	Charter fishing vessel i-Catcher, Capsize, Goose Bay, Kaikōura, New Zealand, 10 September 2022
MO-2023-201	Passenger vessel Kaitaki, Loss of power, Cook Strait, New Zealand, 28 January 2023
MO-2021-204	Recreational vessel, capsized and sinking with three fatalities, Manukau Harbour entrance, 16 October 2021
MO-2021-205	Container vessel Moana Chief, serious injury to crew member, Port of Auckland, New Zealand, 10 December 2021
MO-2020-205	General cargo vessel, Kota Bahagia, cargo hold fire, Napier Port, 18 December 2020
MO-2021-202	Factory fishing trawler Amaltal Enterprise Engine room fire, 55 nautical miles west of Hokitika, 2 July 2021
MO-2021-203	Collision between fishing vessel 'Commission' and container ship 'Kota Lembah', 84 nautical miles northeast of Tauranga, Bay of Plenty, New Zealand, 28 July 2021
MO-2021-201	Jet boat KJet 8, loss of control, Shotover River, Queenstown, 21 March 2021
MO-2021-203	Collision between fishing vessel 'Commission; and container ship 'Kota Lembah', 84 nautical miles northeast of Tauranga, Bay of Plenty, New Zealand, 28 July 2021
MO-2020-202	Bulk log carrier Funing, Loss of manoeuvrability while leaving port, Port of Tauranga, 6 July 2020
MO-2018-206	Bulk carrier Alam Seri, loss of control and contact with seabed, Port of Bluff, 28 November 2018
MO-2020-201	Collision between bulk carrier Rose Harmony and fishing vessel Leila Jo, Off Lyttelton, 12 January 2020
MO-2019-204	Capsized water taxi Henerata, Paterson Inlet, Stewart Island/Rakiura, 12 September 2019

Price \$31.00

ISSN 2815-8806 (Print)
ISSN 2815-8814 (Online)